



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 1368

Date Received

Repository ☐

2003 AUG -7 PM 10:20
22-JUL-2003

Reference No.
10029831

OWNER INFORMATION (Type or Print)

Name

Address

City NEW YORK

State NY

Zip Code

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Do you authorize NHTSA
In the absence of an
Signature of Owner

Signature of your vehicle?
or address to the vehicle manufacturer.
Date 7/10/03

VEHICLE INFORMATION

17 digit Vehicle Identification Number located at bottom of windshield on driver's side

WB10439B1ZEF46427

Make

BMW

Model

3445000

R1150R

Model Year

2002

Date Purchased

6/02

Dealer's Name and Telephone Number

BMW MANHATTAN

Engine

No. Cylinders

Fuel Type:

2 GAS

Original Owner

☒

Dealer's City

NEW YORK

State

NY

Zip Code

Transmission Type

☐ Antilock Brakes

Powertrain

☐ Cruise Control

Vehicle Component Code

071100 FUEL SYSTEM, GASOLINE-STORAGE:TANK ASSEMBLY

Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)

7/03

Failure Mileage

5500

Failure Speed

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM19ABC036)

☐ Original Equipment

☐ Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash?

☐ Yes ☒ No

Fire

☐ Yes ☒ No

Number of Persons Injured

Number of Deaths

Reported to Police

N

Narrative Description of Incident(s), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

CONSUMER STATED THAT WHILE DRIVING AND WITHOUT WARNING FUEL WAS LEAKING FROM THE VEHICLE. DEALER NOTIFIED.

UPON COLD START, motorcycle leaked 1-2 oz of Fuel
ONTO EXHAUST/CAT CONVERTER. LEAK CEASED AFTER
RE-STARTING. REPAIRING DEALER SAID PROBLEM WAS
O-RINGS ON QUICK-DISCONNECT FUEL LINES.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974 (Public Law 93-579) This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your responses may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.