



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire

To Report Vehicle Safety Defects 2003 NOV 12 PM 6:57

1-888-DASH-2-DOT
(1-888-327-4236)

INTERNET www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 252

Date Received

Repository ☐

Reference No.
10040545

Daytime Telephone Number

E-mail Address

Evening Telephone Number

OWNER INFORMATION (Type or Print)

Name

Address

City

OAKLEY

State CA

Zip Code

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☐ YES ☒ NO
In the absence of an authorized signature, please print your name and address to the vehicle manufacturer.
Signature of Owner Date 11/13/03

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side

Make

BEAVER

Model

PATRIOT

Model Year

2000

Date Purchased

5-5-02

Dealer's Name and Telephone Number

Lamasa RV 530-750-5070

Engine: 330 Gt

No. Cylinders

6

Fuel Type:

DIESEL

Original Owner

Dealer's City

Davis

State

CA

Zip Code

95616-9837

Transmission Type

6 SPD

☒ Antilock Brakes

☐ Cruise Control

Powertrain

330 Gt

Vehicle Component Code

036000 SERVICE BRAKES, HYDRAULIC:ANTILOCK

Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)

24-SEP-2003

Failure Mileage

24,000

Failure Speed

45-50

In a construction area out of TANK

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

The Make

The Model (Name or Number)

The Size (Example P215/65R15)

DOT No. (Example: DOTM15ABC036)

☐ Original Equipment

☐ Prior Repair

Failure Location:

Tire Component Code

The Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash

☐ Yes ☒ No

Fire

☐ Yes ☒ No

Number of Persons Injured

Number of Deaths

Reported to Police

N

Narrative Description of Incident(s), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

WHILE APPLYING THE BRAKES ON A MOTOR HOME AND WITHOUT WARNING BRAKE LIGHT APPEARED ON THE DASHBOARD. ALSO, THERE SMOKE WAS COMING FROM THE LEFT FRONT WHEEL, AND OIL LEAKED FROM IN SIDE OF WHEEL BEARING. HEAT KNOCKED OUT THE ABS BRAKING SYSTEM, CAUSING THE MOTOR HOME TO SKID AND HIT A CURB. *AX

The wheel Bearings are in an oil Bath. Both sides had The oil Boiling out The center hole. Left Front motor has been so hot it has change the color of The steel

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974 (Pub. Law 93-579) This information is requested pursuant to authority vested in the National Highway Traffic Safety Administration and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.