



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100078

Date Received

Repository ☐

2004 APR - 1 PM 12:08
26-FEB-2004

Reference No.
10059851

OWNER INFORMATION (Type or Print)

Name

Address

City SPRINGFIELD

State VA

Zip Code

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☐ YES ☒ NO
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner _____ Date 1/1

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side
4T1B612K7TU816331

Make
TOYOTA

Model
CAMRY

Model Year
1998

Date Purchased
7/02

Dealer's Name and Telephone Number

Engine:
No. Cylinders

Fuel Type:
Gas

Original Owner
☐

Dealer's City

State

Zip Code

Transmission Type
AUTOMATIC

☐ Antilock Brakes
☒ Cruise Control

Powertrain
FRONT WHEEL DRIVE

Vehicle Component Code
123000 EXTERIOR LIGHTING:TAIL LIGHTS

Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)
26-FEB-2004

Failure Mileage
60,000

Failure Speed

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM4SABC098)

☐ Original Equipment
☐ Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), condition, and injury(ies).)

Crash

Fire

Number of Persons Injured

Number of Deaths

Reported to Police

☐ Yes ☒ No

☐ Yes ☒ No

N

Narrative Description of Incident(s), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure:
i.e. parts repaired or replaced (and if old part is available).

NHTSA 96V087000. THE PLASTIC MATERIAL OF THE BULB HOLDERS OF THE REAR TAIL LIGHT ASSEMBLY DOES NOT HAVE SUFFICIENT HEAT RESISTANCE. WHEN THE BULB IS ILLUMINATED, THE RESULTING HIGH TEMPERATURE CAN CAUSE THE BULB HOLDER TO DEFORM. CONSUMER STATED HAS THE SAME PROBLEM. *AK

Include, if available, Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974 (Public Law 93-579) This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.