

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire

TO REPORT VEHICLE SAFETY DEFECTS

1-888-DASH-2-DOT
(1-888-327-4236)

INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

Date Received

 Od_or _____
 rt_dt _____
 od_rt _____
 up_lr _____

2004 APR 20 AM 10:13

Reference No.

10000567

OWNER INFORMATION (Type or Print)

Name

Street No.

Apt. No.

City

 Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☒ YES ☐ NO
 In the absence of a signature, please print your name or address to the vehicle manufacturer.

Signature of Owner

Date 3/17/04

PRODUCT INFORMATION

Vehicle Identification No. (VIN)
(17 Digits)(Located at bottom of
windshield on driver's side)

Make

Model

Year

2 G C E K 1 9 T 4 X

CHEV

c/k Pickup

1999

Purchased Date

5-28-99

Dealer's Name

WALLY MCCARTHY

Engine Size
(CID/CCL)

5.7

No. Cylinders

8

☐ Turbo
☐ Diesel
☐ Gas
☐ Fuel Injection

☐ New ☐ Used

Dealer's City

FOREST LAKE

State

MN

Zip Code

55025

Manufacture Date
(on driver's door or pillar)

2/99

Transmission Type

☐ Manual
☒ Automatic

Restraint System

☒ Driver's Air Bag ☐ Motorbell
☒ Passenger's Air Bag ☐ 2-Point Belt
☐ 3-Point Belt

Cruise Control

☒ Yes
☐ No

Drivetrain

☐ Front
☐ Rear
☒ 4-Wheel

Vehicle Type

☐ Car ☐ Sport Utility
☐ Van ☐ Truck
☐ Minivan ☐ Motorcycle
☐ Other

Body Style

☐ 2-Door ☐ 4-Door
☐ Stationwagon
☒ Pick Up Truck
☐ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

 Part Name(s) **ELECTRONIC BRAKE
TRACTION CONTROL MODULE
PN 88935872**

Location

☐ Left ☐ Right
☐ Front ☐ Rear

Failed Part(s)

☐ Original
☐ Replacement

Handicap Adaptive Equip

☐ Yes
☐ No

TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Brand

Tire Name

Complete Tire Size

DOT No.

No. of Failures

Date(s) of Failure(s)

Mileage at Failure(s)

Vehicle Speed at Failure(s)

Failed Part(s)
Available?
☐ Yes ☐ No
NHTSA Previously
Contacted?
☐ Yes ☐ No

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies). Attach photos if available.)

Crash

☐ Yes ☒ No

Fire

☐ Yes ☒ No

Number of Persons Injured

Number of Fatalities

Reported to Manufacturer

☒ Yes ☐ No

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies). **THE ELECTRONIC BRAKE TRACTION CONTROL MODULE FIRED AND RANG ALL THE TIME. THE FUSE HAS TO BE PULLED TO KEEP MODULE FROM RUNNING, EVEN WHEN KEY IS TURNED OFF. I HAD A DEALER CHECK THE PROBLEM AND THEY SAID THE MODULE WAS FAULTY AND NEEDED TO BE REPLACED, IF I WANTED THE ABS SYSTEM TO WORK. I WAS TOLD THE COST TO REPLACE THE MODULE WOULD BE ABOUT \$75.00 FOR THE PART AND 1.5-2 HRS LABOR - ABOUT \$1,000.00. DUE TO THE HIGH COST OF REPLACING THIS PART, I'M SURE MANY PEOPLE, LIKE MYSELF, ARE DRIVING WITHOUT THE ABS SYSTEM WORKING. I UNDERSTAND THIS IS A PROBLEM MOSTLY WITH THE 1999 MODEL AND THAT OTHER YEAR MODELS WILL NOT WORK ON A 1999. I FEEL THIS ITEM IS SOMETHING A LOT OF PEOPLE ARE HAVING TROUBLE WITH, AND THAT GM SHOULD REPLACE WITH AN IMPROVED PART.**

The Privacy Act of 1974 - Public Law 93-579 This information is requested pursuant to 49 U.S.C. Chapter 301. You are under no obligation to respond to this questionnaire. Your responses may be used to assist NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Mail postage free or fax to 202-368-7882