



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4736)
INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100222

Date Received

01-OCT-2004

Repository

Reference No.
10094863

1: 27

OWNER INFORMATION (Type or Print)

Name [REDACTED]
Address [REDACTED]
City **6UDA** State **TX** Zip Code [REDACTED]

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES NO
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.
Signature of Owner _____ Date 1/1

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom or windshield on driver's side
KLATA22611B [REDACTED] Make **DAEWOO** Model **LANOS** Model Year **2001**
Date Purchased **10-28-02** Dealer's Name and Telephone Number **From Private Person** Engine: No. Cylinders **4** Fuel Type: **Gas**
Original Owner No Dealer's City _____ State _____ Zip Code _____
Transmission Type **AUTOMATIC** Antilock Brakes Cruise Control Powertrain **FRONT WHEEL DRIVE** Vehicle Component Code **141000 AIR BAGS:FRONTAL**
Multiple Failures: **1**

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s) **01-OCT-2004** Failure Mileage **15000** Failure Speed _____

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make _____ Tire Model (Name or Number) _____ Tire Size (Example P215/65R15) _____
DOT No. (Example: DOTM19ABC036) Original Equipment Prior Repair Failure Location: _____
Tire Component Code _____ Tire Failure Type _____

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: _____ Date Manufactured: _____ Model No./Name: _____
Seat Type: _____ Installation System: _____
Child Seat Component Code: _____ Failed Part: _____

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash Yes No Fire Yes No Number of Persons Injured _____ Number of Deaths _____ Reported to Police **N**

Narrative Description of Incident(s), Crash(es), and Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure, i.e. parts repaired or replaced (and if old part is available).

CONSUMER RECEIVED RECALL 02V131000 FOR AIR BAGS. THERE WERE NO DEALERS TO MAKE THE REPAIRS AT NO COST TO CONSUMER.
*AK

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974 (Public Law 93-579) This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

September, 2004

(II)

Safety Recall Notice
Lanos, Nubira, Leganza

Dear Lanos, Nubira, and Leganza Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daewoo has decided that a defect which relates to motor vehicle safety exists in certain Lanos, Nubira and Leganza model vehicles.

The problem is with the Camshaft Position (CMP) Sensor that may be installed in your Daewoo vehicle. The CMP sensor sends a CMP sensor signal to the engine control module (ECM). The ECM uses this signal as "sync pulse" to trigger the fuel injectors in the proper sequence. In rare instances, due to a possible crack in the C2 capacitor attached to the CMP Sensor PC board, CMP Sensor may malfunction, which will cause the check engine warning light in your instrument panel to illuminate. Additionally, the Camshaft Position Sensor and wiring may melt resulting in a burning smell and/or visible smoke and possibly an underhood fire.

If you have taken your Daewoo in for service since October 2001 because the Check Engine Warning Light was illuminated on your instrument panel, contact your Daewoo Dealer or Authorized Service Center (ASC) immediately to arrange for your vehicle to be inspected, because your CMP Sensor may have been replaced with one that is subject to this recall. Your dealer or ASC will inspect your vehicle and, if your CMP Sensor needs to be replaced, will replace the sensor and add an in-line fuse to the CMP Sensor wiring. If you are not the first owner of your Daewoo vehicle and/or are not sure if your vehicle has been serviced because of an illuminated Check Engine Warning Light, you should also immediately contact your Daewoo Dealer or Authorized Service Center (ASC) to arrange for your vehicle to be inspected.

If your vehicle has not been serviced since October of 2001 to address an illuminated Check Engine Light, or your vehicle's VIN is not within the following VIN range, your vehicle is not subject to this recall campaign, and you need take no further action at this time.

- Lanos (VIN* numbers: 158465 to 715080)
- Nubira (VIN* numbers: 157058 to 778128, 898142 to 988146)
- Leganza (VIN* numbers: 105594 to 331911)

*VIN=Vehicle Identification Number



412 BY 2000
3315 2094 2098

Daewoo Motor America, Inc.
1055 W. Victoria St.
Compton, CA 90220-9709

September 27, 2004

Recall Campaign No. 02V-131
Safety Recall: Lanos Passenger Air Bag Assembly Modification

SECOND NOTICE

Dear Lanos Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. We are writing as a follow-up to an earlier communication regarding this important subject. Our records indicate that you have not yet made your Daewoo Lanos available to your Daewoo Dealer or Authorized Service Center (ASC) allowing them to perform this important safety-related repair to the passenger air bag assembly.

Reason for This Recall: Daewoo Motor Company, Ltd. in Korea has decided that all 1998-2001 and specific 2002 Lanos models (VINs KLATC2261WB158465 - KLATA22612B708814) fail to conform to FMVSS 201 (Occupant Protection in Interior Impact). In the event of an accident in which the air bags do not deploy, there is a possibility of increased head injury to the front seat passenger should contact with the passenger side air bag cover occur.

What Will Be Done: To meet the FMVSS 201 requirement, Daewoo will install new energy absorbing air bag mounting brackets. This service will be performed for you at no charge.

How Long Will The Repair Take?: The actual length of time required to perform this air bag assembly modification is approximately one (1) hour. If your dealer has a large number of vehicles awaiting service, however, additional time will be required to process your vehicle. Please ask your Dealer how much time they will need to complete this procedure.

Contacting Your Dealer: Please contact your Daewoo Dealer as soon as possible to schedule a service date. Parts are available, and instructions for making this correction have been sent to your Dealer. Please ask your Dealer if you wish to know how much time will be needed to schedule, process and repair your vehicle. Your Daewoo Dealer is fully prepared and will provide this service as soon as possible. If, however, you take your vehicle to your Dealer on the scheduled service date and you have a problem obtaining the corrective service on that date, please contact the Daewoo Customer Assistance Center toll-free at (877) 352-1234, option 6. A Daewoo representative will assist you with arranging prompt service for your vehicle.

If you are the owner of the subject vehicle, but have leased it to another person, you are required by law to forward a copy of this notice to your lessee by first class mail within ten days of your receipt of this letter. See 49 C.F.R. 577.7(a)(2)(iv).

If after contacting the Dealer and the Daewoo Customer Assistance Center you are still not satisfied that we have done our best to remedy the condition without charge to you and within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street SW, Washington D.C. 20590 or call (888) 327-4236.

Customer Reply Card: The enclosed Owner Reply Card identifies your vehicle. Presenting the card at the time of your service will assist your Daewoo Dealer in completing this procedure in the shortest time possible. If you have sold or traded your vehicle, please let us know by completing the enclosed postage-paid reply card and returning it to us.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

DAEWOO CUSTOMER RELATIONS DEPARTMENT

www.daewooup.com

PLEASE RETAIN FOR YOUR RECORDS



NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES