

From:
Sent: Wednesday, December 29, 2004 6:47 PM
To: Chan, Steve
Subject: Defective Ford Truck F250 Wheel Rims Hub Cap

*Add to
~~10104425~~
10104425*

I file a complaint with Ford Motor Company Area Representative of Southern Los Angeles County. The reply was not very responsive. The Fire Department Personal said the hubs are coming off at highway speed with no warning. The drivers notice hub caps flying off in any direction. One drive notice a hub cap hitting a driver side door Mirror.

I file a seven E-mail complaint through www.nhtsa.dot.gov Office of Defects Investigation. The following seven have assigned (ODI Numbers).

Vehicle #	ODI # List
1. F0926	10104245
2. F0927	10104246
3. F0928	10104269
4. F1037	10104401
5. F1038	10104418
6. F1039 VID# 1ffax20tx1ed79885	1010xxx-Wrong # 754440?? 10104425
7. F1040	10104430

The pictures will show the base plastic hub cap locks are cracking off or missing all together. The part number is Ford Component # Style F81 A-1130-AA 4X2. The whole sale cost each is \$52.14 plus state sales tax 8.5%. We order seventeenth hub caps for seven units. My office telephone is
Job Title: Vehicle Coordinator

1/11/2005


F0926	FORD	F 250 SD	97404	2001	1FTNX20FX1E	PICKUP EXT CAB W/SHELL	INVESTIGATOR	007	
F0927	FORD	F 250 SD	88000	2001	1FTNX20F81E	PICKUP EXT CAB W/SHELL	INVESTIGATOR	005	
F0928	FORD	F 250 SD	82194	2001	1FTNX20F81E	PICKUP EXT CAB W/SHELL	INVESTIGATOR	008	
F1037	FORD	F 250 SD	57440	2001	1FTNX20F81E	PICKUP EXT CAB W/SHELL	INVESTIGATOR	008	
F1038	FORD	F 250 SD	46788	2001	1FTNX20F41E	PICKUP EXT CAB W/SHELL	INVESTIGATOR	003	
F1039	FORD	F 250 SD	81975	2001	1FTNX20F81E	PICKUP EXT CAB W/SHELL	INVESTIGATOR	002	



MVC-001F.JPG
(35KB)



MVC-002F.JPG
(32KB)



MVC-003F.JPG
(36KB)



MVC-004F.JPG
(40KB)



MVC-005F.JPG
(46KB)