

10109344

2004 DEC 29 PM 4:17

December 28, 2004

TO:

U.S. Department of Transportation  
National Highway Traffic Safety Administration  
Office of Defects Investigation (NVS-211)  
400 7th Street, SW  
Washington, DC 20590

FROM:

Sweet Home OR

Dear Sirs:

We purchased a 2001 Olds Aurora, VIN 1G3GS64C51 in summer of 2002 from  
Wentworth Buick in Eugene, OR.

In the past year this car has suddenly died and restarted when on normal travelling speeds. It has  
also died at low RPM when negotiating a corner at a traffic light intersection, causing much angst  
for myself and the others in that intersection.

Dealers do not seem to have knowledge of how to repair this, or even what is causing it. There is  
some thought it is caused by the "anti-theft" device and/or the computerized key.

We consider this to be a dangerous situation. There have been near collisions due to having to  
restart the engine in an intersection.

Mami  
1/14/05