



U.S. Department of Transportation
National Highway Traffic Safety Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100216

Date Received: 10-FEB-2006
Repository: []
Reference No.: 10111332

OWNER INFORMATION (Type or Print)
Name: [REDACTED]
Address: [REDACTED]
City: RYE State: NY Zip Code: [REDACTED]

Daytime Telephone Number: [REDACTED] E-mail Address: [REDACTED]
Evening Telephone Number: [REDACTED]

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES NO
In the absence of an authorization, NHTSA will not provide your name or address to the vehicle manufacturer.
Signature of Owner: [REDACTED] Date: 2-12-06

VEHICLE INFORMATION
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side: IFMYU93135D
Make: FORD Model: ESCAPE Model Year: 2005
Date Purchased: June 04 Dealer's Name and Telephone Number: RYE FORD 914 967 6300
Original Owner: [X] Dealer's City: RYE State: NY Zip Code: 10580
Engine: No. Cylinders: 6 Fuel Type: Gas
Transmission Type: AUTOMATIC Antilock Brakes Powertrain: [REDACTED]
 Cruise Control Vehicle Component Code: 181000 VEHICLE SPEED CONTROL/ACCELERATOR PEDAL
Multiple Failure: 2

FAILED COMPONENT(S)/PART(S) INFORMATION
Incident Date(s): 09-DEC-2004 Failure Mileage: 19903 Failure Speed: 20
0.104 2005
See copies in addition new transmission and seat belt were added after SV through of they had finished.

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE
Tire Make: [REDACTED] Tire Model (Name or Number): [REDACTED] Tire Size (Example P215/65R15): [REDACTED]
DOT No. (Example: DOTMALBABC036): [REDACTED] Original Equipment Prior Repair Failure Location: [REDACTED]
Tire Component Code: [REDACTED] Tire Failure Type: [REDACTED]

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE
Make: [REDACTED] Date Manufactured: [REDACTED] Model No./Name: [REDACTED]
Seat Type: [REDACTED] Installation System: [REDACTED]
Child Seat Component Code: [REDACTED] Failed Part: [REDACTED]

APPLICABLE INCIDENT INFORMATION
(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)
Crash: Yes No Fire: Yes No
Number of Persons Injured: 0 Number of Deaths: 0 Reported to Police: Y

Narrative Description of Incident(S), Crash(es), and Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).
WHILE DRIVING 20 MPH VEHICLE ACCELERATED UNCONTROLLABLY. DRIVER WAS NOT ABLE TO MAINTAIN CONTROL OF THE VEHICLE, AND IT COLLIDED WITH A UTILITY POLE. VEHICLE WAS TOWED TO THE DEALER FOR INSPECTION, BUT MECHANIC COULD NOT DUPLICATE THE PROBLEM. HOWEVER, THE PROBLEM RECURRED. *AK Whoever I spoke with mixed up the two incidents. The first occurred Dec 9, 2004. I was trying to slow to make a left turn from Mamaroneck Ave to Maple Ave in White Plains NY. Instead of ending up on Maple I was going to go into a store front on the corner and pulled hard on the steering wheel to avoid that and collided with the telephone pole on the right side of the car. I then pulled hard in

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY
The Privacy Act of 1974-Public Law 93-502 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

evening, Feb 1, 2005, I received a call from a friend that Consumers Union had reported all Ford Escapes 2002-2004 had been recalled for an accelerator problem. While my car is a 2005, it was manufactured April 2004. When I called the Ford Recall number they said my VIN was not included in the recall. I think it should have been.

Sincerely

[REDACTED]

[REDACTED]
Kye NY
[REDACTED]

Estimate ID: 49309
 Estimate Version: 9
 Supplement: 1 (F) 1/11/08 08:00:12 AM
 Print ID: ATLANTIC

Hudson Valley Auto Appraisers, Inc.

40 Park Road, Newburgh, NY 12550
 (845) 561-3394
 Fax: (845) 567-3279

1ST SUPPLEMENT

Cash Paid By: [REDACTED]
 Supplement By: [REDACTED]

Condition Code: Good
 Date of Loss: 12/8/04
 Deductible: 1,000.00
 File Number: 49309
 Policy No: [REDACTED]

Type of Loss: Collision

Insured Address: [REDACTED] NY, NY
 Telephone: Home Phone: [REDACTED]

Claim Number: [REDACTED]

Michel Service: 017828

Description: 2006 Ford Escape XLT
 Body Style: 4D LB
 VIN: 1F8P9U8913304 [REDACTED]
 Weight: 1,883
 Chassis: C
 Color: 4899a
 Colors: A, ALUMINUM WHEELS, AIR CONDITIONING, POWER STEERING, POWER BRAKES, POWER WINDOWS, POWER DOOR LOCKS, ELECTRIC DEFOGGER, LEATHER SEATS, AUTOMATIC TRANSMISSION, AM-FM 6-SPEAKER(SINGLE), PASSENGER-FRONT AIR BAG, POWER REVOLVE MIRROR, 4-DOOR, DRIVER-FRONT AIR BAG, POWER SEATS

Drive Train: 3.0L I-4 CVT 4WD
 License: [REDACTED]

Search Code: 8883207

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/Part Number	Dollar Amount	Labor Units
				FRONT BUMPER			
1		BDY	OVERHAUL	FRT BUMPER ASBY			1.4
2	700082	BDY	REMOVE/REPLACE	FRT BUMPER COVER	SLBZ 170857 CAA	482.02	INC
3	703084	BDY	REMOVE/REPLACE	FRT BUMPER LICENSE BRACKET	SLBZ 174025 AAB	28.87	INC
4	701482	BDY	REMOVE/REPLACE	FRT BUMPER REINFORCEMENT	SLBZ 17797 AA	72.05	INC
5	701483	BDY	REMOVE/REPLACE	R FRT BUMPER REINFORCEMENT BRKT	YLKZ 178782 AA	57.25	INC
6	701484	BDY	REMOVE/REPLACE	L FRT BUMPER REINFORCEMENT BRKT	YLKZ 178782 BA	57.25	INC
7	703085	BDY	REMOVE/REPLACE	FRT BUMPER SHD PLATE	SLBZ 88018 AAA	57.25	INC
				GRILLE			
8	703086	BDY	REMOVE/REPLACE	GRILLE	SLBZ 8309 AAB	83.32	INC #
9	700029	BDY	REMOVE/REPLACE	GRILLE EMBLEM	YLKZ 794222B B5	13.80	INC #
				FRONT LAMPS			
10	708134	BDY	CHECK/ADJUST	HEADLAMPS			0.4
11	703118	BDY	REMOVE/REPLACE	R FRONT COMBINATION LAMP ASSEMBLY	ORDER FROM DEALER	188.10	0.2 #
12	703117	BDY	REMOVE/REPLACE	L FRONT COMBINATION LAMP ASSEMBLY	ORDER FROM DEALER	188.10	0.2 #
13	703128	BDY	REMOVE/REPLACE	L FOG LAMP ASSEMBLY	ZMS2 18209 AB	75.07	INC #
				HOOD			
14	700045	BDY	REMOVE/REPLACE	HOOD PANEL	SLBZ 15812 AA	361.28	0.9
15		REF	REFINISH	HOOD OUTSIDE			C 2.3
16		REF	REFINISH	HOOD UNDERSIDE			C 1.5
17	700062	BDY	REMOVE/REPLACE	HOOD LATCH	SLBZ 18700 AA	38.48	0.3

ESTIMATE RECALL NUMBER: 1/11/08 08:31:17 49309

Michel Data Version: DBO_04_A
 Ultrafile Version: 6.0.027

Ultrafile is a Trademark of Michel International
 Copyright (C) 1994 - 2005 Michel International
 All Rights Reserved

18	701488	BOY	REMOVE/REPLACE	HOOD CABLE LEVER COOLING	YL&Z 18A770 AA	11.10	
19	700061	BOY	REMOVE/REPLACE	COOLING RADIATOR TRANS OIL COOLER	YL&Z 8005 LB	325.22	1.0
20	705170	MCH	REMOVE/REPLACE	TRANS OIL COOLER -M	SL&Z 7AD85 BA	148.37	0.5 #
21	701233	MCH	REMOVE/REPLACE	TRANS OIL COOLER INLET HOSE -M	YL&Z 70410 BA	24.38	0.4 #
22	708172	MCH	REMOVE/REPLACE	TRANS OIL COOLER OUTLET HOSE -M	SL&Z 78280 AA	28.00	0.8 #
				AC INHAERVENTILATION			
23	700103	MCH	REMOVE/REPLACE	EVACUATE & RECHARGE AC -M			1.4
24	708104	MCH	REMOVE/REPLACE	AC REFRIGERANT RECOVERY -M			0.3
25	703178	MCH	REMOVE/REPLACE	AIR COND CONDENSER -M	N.A.	336.32	0.4 #
26	701580	BOY	REMOVE/REPLACE	N LPR AIR COND CONDENSER BRACKET	YL&Z 18702 DA	3.80	
27	701681	BOY	REMOVE/REPLACE	L LPR AIR COND CONDENSER BRACKET	YL&Z 18733 DA	6.10	
28	700118	MCH	REMOVE/REPLACE	AIR COND ACCUMULATOR -M	YL&Z 18C558 AA	101.02	0.8
				FRONT FENDER			
29	700141	BOY	REMOVE/REPLACE	L FENDER PANEL	YL&Z 18D05 DA	228.85	2.3 #
30		REF	REFINISH	L FENDER OUTSIDE			C 1.6
31		REF	REFINISH	L FENDER EDGE			C 0.5
32	700142	BOY	REMOVE/REPLACE	R FENDER PANEL	YL&Z 18D09 BA	228.89	1.1
33		REF	REFINISH	R FENDER OUTSIDE			C 1.8
34		REF	REFINISH	R FENDER EDGE			C 0.8
35	703203	BOY	REMOVE/REPLACE	L FENDER LINER	SL&Z 18103 AA	48.85	INC #
				FRONT INNER STRUCTURE			
36		REF	REFINISH	RADIATOR SUPPORT COMPLETE			1.6
37	700187	BOY	REMOVE/REPLACE	LPR FRONT BODY RADIATOR SUPPORT -B	SL&Z 18134 BA	182.85	3.0
38	703143	BOY	REMOVE/REPLACE	L FRONT BODY BRACKET	SL&Z 88085 AA	7.39	
39	785218	BOY	REMOVE/REPLACE	FRONT BODY BRACE	SL&Z 18C780 AA	20.18	
40	783219	BOY	REMOVE/REPLACE	R FRONT BODY BRACE	SL&Z 18A080 AA	26.72	
41	785220	BOY	REMOVE/REPLACE	L FRONT BODY BRACE	SL&Z 18P024 AA	28.72	
42	700174	BOY	REMOVE/REPLACE	LWR FRONT BODY RADIATOR SUPPORT -B	SL&Z 18138 AA	89.12	1.5
43	701833	BOY	REMOVE/REPLACE	LWR FRONT BODY SPLASH SHIELD	YL&Z 18109 AA	28.70	0.3
44	703221	BOY	REMOVE/REPLACE	R LPR FRONT BODY SPLASH SHIELD	YL&Z 18103 CA	24.22	
45	700178	REF	REFINISH	L APRON ASSEMBLY COMPLETE			2.0
46	703223	BOY	REPAIR	L FRONT BODY FRONT APRON PANEL -B	Existing		3.0* #
47	701641	BOY	REPAIR	L FRONT BODY SIDE RAIL -B	Existing		2.0*
				FRONT SUSPENSION			
48	700288	MCH	ALIGN	FOUR WHEEL -M			1.8
				ELECTRICAL			
49	703682	BOY	REMOVE/REPLACE	HIGH NOTE HORN ASSY	SL&Z 13801 AA	21.10	C 1.0 #
				WINDSHIELD			
50	700488	GLB	REMOVE/INSTALL	WINDSHIELD			2.8 #
51	700481	BOY	REMOVE/REPLACE	WINDSHIELD MOLDING	YL&Z 7803144 AA	49.82	
52	800500	BOY *	ADD'L LABOR OP	COLOR BAND AND BUFF	Existing		2.0*
53	800580	REF *	REMOVE/REPLACE	ASST HARDWARE NUTS, BOLTS, CUPS	**Qual Repl Part	25.00 *	0.0*
54	800580	REF *	REMOVE/REPLACE	UNDERCOATING	**Qual Repl Part	18.00 *	0.5*
55	800500	PRM *	ADD'L LABOR OP	BENCH SET UP & MEASURE	Existing		2.5*
56	800500	PRM *	ALIGN	UNIBODY PULL AND ALIGN	Existing		4.0*
57	800880	BOY *	ADD'L LABOR OP	COLLISION ADDRESS	Existing		1.0*
58	800500	BOY *	REMOVE/REPLACE	BEAM SEALER AND CAULK	**Qual Repl Part	15.00 *	0.5*
59	800500	BOY *	REMOVE/REPLACE	GLASS URETHANE KIT	**Qual Repl Part	25.00 *	0.0*
60	800500	BOY *	ADD'L LABOR OP	CORROSION PROTECTION	Existing		0.5*
61	800880	MCH *	REMOVE/REPLACE	R-134A	**Qual Repl Part	55.00 *	0.0*
62	838603		ADD'L COST	COOLANT		15.00 *	
				ROCKER/PILLAR/FLOOR			
63	700888	BOY	REPAIR	L COM/DASH HINGE PILLAR -B	Existing		6.8*
64		REF	REFINISH	L HINGE PILLAR			C 1.0
65	701341	BOY	REMOVE/INSTALL	R STEP RAIL ASSY			0.8
66	701382	BOY	REMOVE/INSTALL	L STEP RAIL ASSY			0.5
67	703488	BOY	REPAIR	L STEP RAIL ASSEMBLY	Existing		1.0*

ESTIMATE RECALL NUMBER: 1/1/08 08:31:17 48303

Michell Data Version
 Estimate Version:

DEC_04_A
 0.0.027

Urethane is a Trademark of Michell International
 Copyright (c) 1994 - 2008 Michell International
 All Rights Reserved

Page 2 of 8

FRONT DOOR

88	700774	REF	BLIND	L FRT DOOR OUTSIDE				C 1.0*
89	700783	BOY	REPAIR	R FRT DOOR REPAIR PANEL	Edging			3.0**
90		REF	REFINISH	R FRT DOOR OUTSIDE				C 1.9
91	700784	BOY	REPAIR	L FRT DOOR REPAIR PANEL	Edging			2.0**
92	702481	BOY	REMOVE/INSTALL	R FRT OTR BELT MOULDING				0.2
93	702482	BOY	REMOVE/INSTALL	L FRT OTR BELT MOULDING				0.2
94	700787	BOY	REMOVE/INSTALL	R FRT DOOR MOULDING				0.2
95	700788	BOY	REMOVE/INSTALL	L FRT DOOR MOULDING				0.2
96	702877	BOY	REMOVE/REPLACE	R FRT DOOR POWER MIRROR ASSY	2L&Z 17882 CAB	197.73		0.2 #
97	702878	BOY	REMOVE/REPLACE	L FRT DOOR POWER MIRROR ASSY	3L&Z 17883 MAA	197.73		0.2 #
98	700789	BOY	REMOVE/INSTALL	R FRT DOOR TRIM PANEL				0.3
99	700800	BOY	REMOVE/INSTALL	L FRT DOOR TRIM PANEL				INC
100	700822	BOY	REMOVE/INSTALL	L FRT OTR DOOR HANDLE				0.8 #
101	704838	BOY	REMOVE/REPLACE	R FRT DOOR OUTSIDE HANDLE	2L&Z 7522604 AAA	22.36		0.3 #
				REAR DOOR				
102	700841	BOY	REPAIR	R REAR DOOR REPAIR PANEL	Edging			3.1**
103		REF	REFINISH	R REAR DOOR OUTSIDE				C 1.6
104	700843	BOY	REMOVE/INSTALL	R REAR DOOR MOULDING				0.2
105	702818	BOY	REMOVE/INSTALL	R REAR OTR BELT MOULDING				0.2
106	700881	BOY	REMOVE/INSTALL	R REAR DOOR TRIM PANEL				INC
107	700913	BOY	REMOVE/INSTALL	R REAR OTR DOOR HANDLE				0.5 #
				QUARTER PANEL				
108	701003	REF	REFRESH	R QTR PNR FILLAR				C 0.2
109	701016	BOY	REPAIR	R QUARTER OUTER PANEL	Edging			4.8**
110		REF	REFRESH	R QUARTER PANEL OUTSIDE				C 1.6
				REAR SUSPENSION				
111	702787	MCH	REMOVE/REPLACE	L LWR REAR SLIP CONTROL ARM	-M YLEZ 5300 AB	28.20		0.4 #
112	702788	MCH	REMOVE/REPLACE	L LWR REAR SLIP CONTROL ARM	-M 6L&Z 5300 AD	28.20		0.4 #
				FUEL TANK				
113	700928	BOY	REMOVE/REPLACE	FUEL SYSTEM GH BLD	6L&Z 98087 BA	109.98		
				REAR LAMPS				
114	701174	BOY	REMOVE/INSTALL	R REAR COMBINATION LAMP				0.2
				REAR BUMPER				
115	700185	BOY	REMOVE/INSTALL	REAR BUMPER ASSY				0.6 #
116	900500	MCH*	REMOVE/REPLACE	TRANSMISSION	New	1,910.00*		INC*
117	900500	MCH*	REMOVE/REPLACE	TRANSMISSION LABOR @ 90\$/HR	New	1,040.00*		INC*
				Negotiated at Local Mechanical Rates				
118	900399	BOY*	REMOVE/REPLACE	TRANSMISSION CORE CHARGE	New	600.00*		INC*
119	900399	BOY*	REMOVE/REPLACE	TRANSMISSION FLUID	**Qual Repl Part	15.00*		0.0*
120	900399	BOY*	REMOVE/REPLACE	ENGINE OIL AND FILTER	**Qual Repl Part	21.95*		0.0*
				ADDITIONAL COSTS & MATERIALS				
121	838001		ADD'L COST	TOWING				210.00*
				ADDITIONAL OPERATIONS				
122		REF	ADD'L OPR	CLEAR COAT				3.0
123			ADD'L COST	PAINT/MATERIALS				430.20*
124			ADD'L COST	HAZARDOUS WASTE DISPOSAL				3.00*

* - Judgement Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc

Prior Damage
 None

ESTIMATE RECALL NUMBER: 1/11/05 09:31:17

Michell Data Viewer
 Ultimate Version:

DSO_04_A
 3.0.027

Ultimate is a Trademark of Michell International
 Copyright (C) 1994 - 2005 Michell International
 All Rights Reserved

Labor Subtotal's	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals
Body	48.3	40.00	0.00	0.00	1,932.00 T
Refinish	23.9	40.00	0.00	0.00	956.00 T
Glass	2.8	40.00	0.00	0.00	104.00 T
Frame	8.5	42.00	0.00	0.00	273.00 T
Mechanical	7.0	40.00	0.00	0.00	280.00 T
Tangible Labor					3,485.00
Labor Tax @ 7.500%					262.68
Labor Summary					88.3
					3,724.68

Part Replacement Summary		Amount
Tangible Parts		7,436.08
Sales Tax @ 7.500%		567.70
Total Replacement Parts Amount		8,423.78

Additional Costs		Amount
Tangible Costs		451.20
Sales Tax @ 7.500%		33.84
Non-Tangible Costs		216.00
Total Additional Costs		805.84

Adjustments		Amount
Insurance Deductible		1,000.00
Customer Responsibility		1,000.00

I. Total Labor:	3,724.68
II. Total Replacement Parts:	8,423.78
III. Total Additional Costs:	805.84
Gross Total	13,843.88

IV. Total Adjustments:	1,000.00
Net Total:	11,843.88
Less Original Net Total:	7,867.71
Net Supplement Amount:	3,976.17
①: Job Notation 14-837885	8,000.87

Point(s) of Impact
 12 Front Door (P)

Insurance Co: Atlantic Motor Company
 Address: Claims Department
 PO Box 4628, 1325 Electric Rd.
 Roanoke, VA
 Telephone: (877) 210-2148
 Fax Phone: (800) 678-6847

Report Date: 1/27/04

Body Shop: B&V Auto Body
 Address: 322 Center Ave
 Monticello, NY 10543
 Telephone: (814) 888-7295
 Fax Phone: (814) 888-2108
 State Lic. No: 7058310

THIS IS NOT AN AUTHORIZATION FOR ANY REPAIR TO THIS VEHICLE OR
 COMMITMENT FOR PAYMENT OR LIABILITY. SUPPLEMENTAL DAMAGE
 REQUIRES PRIOR APPROVAL. THIS SPECIFIES AND INTENDS THAT ALL REPAIRS
 BE MADE IN STRICT ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS

ESTIMATE RECALL NUMBER: 1/11/05 06:31:17

Mitchell Data Version: DEC_04_A
 Ultratek Version: 6.0.027

Ultratek is a Trademark of Mitchell International
 Copyright (C) 1994 - 2003 Mitchell International
 All Rights Reserved

AND RECOMMENDATIONS WHEN AUTHORIZED BY THE OWNER. O.E.M. PARTS
LISTED UNLESS OTHERWISE INDICATED.

Any person who knowingly and with intent to defraud any insurance company or other person files an application for commercial insurance or a statement of claim for any commercial or personal insurance benefits containing any materially false information, or conceals for the purpose of misleading, information concerning any fact material thereto, and any person who, in connection with such application or claim, knowingly makes or knowingly assists, abets, solicits or conspires with another to make a false report of the theft, destruction, damage or conversion of any motor vehicle to a law enforcement agency, the department of motor vehicles or an insurance company, commits a fraudulent insurance act, which is a crime, and shall also be subject to a civil penalty not to exceed five thousand dollars and the value of the subject motor vehicle or stated claim for each violation.

ESTIMATE RECALL NUMBER: 1/11/09 06:31:17 48003

Michel Data Version:
Ultrafile Version:

DEC_04_A
5.0.027

Ultrafile is a Trademark of Michel International
Copyright (C) 1994 - 2009 Michel International
All Rights Reserved

Page 8 of 8

**THE ATTACHMENTS TO THIS
DOCUMENT HAVE BEEN REMOVED
TO PROTECT UNWARRANTED
INVASION OF PERSONAL PRIVACY
PURSUANT TO EXEMPTION 6 OF
THE FREEDOM OF INFORMATION
ACT (FOIA), 5 U.S.C. 552(b)(6).**