 <p>U.S. Department of Transportation National Highway Traffic Safety Administration</p>		<p>DOT Auto Safety Hotline</p> <p>Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline</p>		<p>FOR AGENCY USE ONLY 100148</p>	
		<p>Date Received 24-MAY-2005</p>		<p>Repository <input type="checkbox"/></p> <p>Reference No. 10122043</p>	
OWNER INFORMATION (Type or Print)					
Name		Daytime Telephone Number		E-mail Address	
Address		Evening Telephone Number			
City	State	Zip Code	<p>SAME AS ABOVE</p>		
AVON PARK		FL			
<p>Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO</p> <p>In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.</p> <p>Signature of Owner _____ Date 6/16/05</p>					
VEHICLE INFORMATION					
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side		Make	Model	Model Year	
1GBLP37J8T3		FLEETWOOD	BOUNDER	1996	
Date Purchased	Dealer's Name and Telephone Number		Engine:	Fuel Type:	
03-JUL-96	A+S RV Sales		No: Cylinders 8	Gas	
Original Owner	Dealer's City	State	Zip Code		
<input checked="" type="checkbox"/>	Auburn Hills	Mi			
Transmission Type	<input type="checkbox"/> Antilock Brakes	Powertrain	Vehicle Component Code		
AUTOMATIC	<input checked="" type="checkbox"/> Cruise Control	FRONT WHEEL DRIVE	132000 VISIBILITY:GLASS, SIDE/REAR		
			Multiple Failure: 1		
FAILED COMPONENT(S)/PART(S) INFORMATION					
Incident Date(s)	Failure Mileage	Failure Speed			
01-MAY-2005					
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE					
Tire Make	Tire Model (Name or Number)		Tire Size (Example P215/65R15)		
DOT No. (Example: DOTM19ABC036)	<input type="checkbox"/> Original Equipment <input type="checkbox"/> Prior Repair		Failure Location:		
Tire Component Code			Tire Failure Type		
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE					
Make:	Date Manufactured:	Model No./Name:			
Seat Type:	Installation System:				
Child Seat Component Code:	Failed Part:				
APPLICABLE INCIDENT INFORMATION					
(Use one describe in detail the incident(s), failure(s), crash(es), and injury(ies).)					
Crash	Fire	Number of Persons Injured	Number of Deaths	Reported to Police	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			N	
Narrative Description of Incident(S), Crash(es), and Injury(ies).					
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).					
<p>DT: CONSUMER STATES: PASSENGER'S WINDOW WAS REPLACED, WINDOW WAS ALMOST OPENED, HAD TO OPEN THE WINDOW, AND PUT HEAD OUT IN ORDER TO SEE TO BACK UP OR TO CHANGE LANES. *AK</p> <p style="text-align: right;">OPAGUE</p>					
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.			ATTACH ADDITIONAL SHEETS IF NECESSARY		
<p>The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response or a statistical summary thereof, may be used in support of the agency's action</p>					

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

Our 1996 Buander made by Fleetwood - side passenger window became opaque so you couldn't see out of it. Couldn't use side mirror to change lanes so we had to replace it on 5-20-05. Fleetwood had a recall for the 1996-97 Buander driver and passenger window due to a defect in the driver + passenger window. They say our match home is one of the recall, but many other Buander from year + 97 have the same problem. The driver window is starting to go as well so we will have to replace it. It cost \$890.00 for the window + 146.00 to install it and that was for one window. We believe we also got the defected windows ~~for~~ Fleetwood will not agree to it.


ATTACH ADDITIONAL SHEETS IF NECESSARY

U.S. Department of Transportation

National Highway Traffic Safety Administration

400 Seventh St., S.W. Washington, D.C. 20590

Official Business Penalty for Private Use \$300



BUSINESS REPLY MAIL
FIRST CLASS PERMIT NO 73173 WASHINGTON, D.C.

POSTAGE WILL BE PAID BY NATL. HWY. TRAFFIC SAFETY ADMIN.

U.S. Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation, NVS-216
400 7th Street, SW
Washington, DC 20590



VEHICLE OWNER'S QUESTIONNAIRE

DOT AUTO SAFETY HOTLINE

TO REPORT VEHICLE SAFETY DEFECTS COMPLETE THIS FORM OR


DASH2DOT

and dial toll free at

1-888-DASH-2-DOT

1-888-327-4236

DOT Auto Safety Hotline (DASH) 2 DOT



U.S. Department of Transportation
National Highway Traffic Safety Administration
www.nhtsa.dot.gov/hotline