

Type: Customer E-mail
From: [REDACTED]
To: webmaster@nhtsa.dot.gov
Subject: 2004 Malibu Maxx - Power Steering Failure

*Received
1/14/05*

10127993

From: [REDACTED]

Comments:

2004 MalibuMaxx was serviced @ 9:30am on 1/15/2005, at dealership for 15,000 checkup. At 12:30 pm, same day, console reported power steering failure. Called dealership, was instructed to drive vehicle directly there. As of 4:00 pm 1/17/2005, still waiting for dealership to inform cause and actions being taken.

From NHTSA Web Site.

*NAP
2005
7/1/05*