



DOT Auto Safety Hotline Vehicle Owner's Questionnaire

TO REPORT VEHICLE SAFETY DEFECTS
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

Date Received: 2005 JUL 22 AM 5:20

10131268

Od_or _____
rt_dt _____
od_rt _____
up_ltr _____

Reference No. _____

Daytime Telephone Number _____

OWNER INFORMATION (Type or Print)

Name: _____

Street No: _____ Apt. No. _____

City: STAMFORD State: CT Zip Code: _____

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES NO
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner: _____ Date: 7/8/05

PRODUCT INFORMATION

Vehicle Identification No. (VIN): KLAJB82Z6YK [redacted] (Located at bottom of windshield on driver's side)

Make: DAEWOO Model: NUBIRA Year: 2000

Purchased Date: 10/16/2000 Dealer's Name: KEY AUTO GROUP Engine Size (CID/CC): 2.0 Turbo Diesel Gas Fuel Injection

Dealer's City: WHITE PLAINS State: NY Zip Code: 10601-4512 No. Cylinders: 4

New Used

Manufacture Date: _____ Transmission Type: Manual Automatic

Restraint System: Driverside Air Bag Motorbelt Passengerside Air Bag 2-Point Belt 3-Point Belt

Cruise Control: Yes No

Drivetrain: Front Rear 4-Wheel

Vehicle Type: Car Sport Utility Van Truck Minivan Motorcycle Other

Body Style: 2-Door 4-Door Stationwagon Pick Up Truck Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Part Name(s): POWER STEERING RACK

Location: Left Right Front Rear

Failed Part(s): Original Replacement

Handicap Adaptive Equip: Yes No

TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Brand: _____ Tire Name: _____

Complete Tire Size: _____ DOT No.: _____

No. of Failures: _____ Date(s) of Failure(s): _____ Mileage at Failure(s): _____ Vehicle Speed at Failure(s): _____

Failed Part(s) Available? Yes No

NHTSA Previously Contacted? Yes No

APPLICABLE INCIDENT INFORMATION
(Please describe in detail the Incident(s), Failure(s), Crash(es), and Injury(ies). Attach photos if available.)

Crash: Yes No

Fire: Yes No

Number of Persons Injured: 0

Number of Fatalities: 0

Reported to Manufacturer: Yes No

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies):

STEERING HARD TO TURN. TURNING WHEEL BACK IS FORCEFUL.
AFTER SEVERAL INCIDENTS OF CAR ALMOST GOING OFF TARMAC AFTER
TURN I BROUGHT THE CAR TO THE MECHANIC AS IT WAS
UNSAFE TO DRIVE.
REPLACING POWER STEERING RACK COST \$1279.
MILEAGE 42856.

Continue on back.

The Privacy Act of 1974 - Public Law 93-579 This information is requested pursuant to a 49 U.S.C. Chapter 301. You are under no obligation to respond to this questionnaire. Your response may be used to assist NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

908 BRIDGEPORT AVE.
MILFORD, CT.
06460
TEL: 203.878.9989


Name
Address

5

Telephone
Vehicle (VIN)
License
Technician
Mileage
Time Printed

3/18/05 8:33 PM

Daewoo : Nubira : 1998-2002



THE ATTACHMENTS TO THIS DOCUMENT HAVE BEEN REMOVED TO PROTECT UNWARRANTED INVASION OF PERSONAL PRIVACY PURSUANT TO EXEMPTION 6 OF THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(b)(6).