



U.S. Department of Transportation  
National Highway Traffic Safety Administration

DOT Auto Safety Hotline

**Vehicle Owner's Questionnaire**  
To Report Vehicle Safety Defects  
1-888-DASH-2-DOT  
(1-888-327-4236)  
INTERNET:www.nhtsa.dot.gov/hotline

2008 MAR -5 AM 7:23

FOR AGENCY USE ONLY 100148

Date Received

01-DEC-2005

Repository

Reference No.

10144116

**OWNER INFORMATION (Type or Print)**

Name

Address

City

NEW LONDON Quincy

State

IL MO

Zip Code

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle?  YES  NO  
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner

Date / /

**VEHICLE INFORMATION**

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side

Make  
CHEVROLET

Model  
LUMINA

Model Year  
1998

Date Purchased  
01-JUN-99

Dealer's Name and Telephone Number

Engine:

No: Cylinders 6

Fuel Type:  
Gas

Original Owner

Dealer's City

State

Zip Code

Transmission Type  
AUTOMATIC

Antilock Brakes  
 Cruise Control

Powertrain  
FRONT WHEEL DRIVE

Vehicle Component Code  
063200 ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:MANIFOLD

Multiple Failure: 2

**FAILED COMPONENT(S)/PART(S) INFORMATION**

Incident Date(s)  
27-NOV-2005

Failure Mileage  
~~99,000~~

Failure Speed  
-0-

**ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE**

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM9ABC036)

Original Equipment  
 Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type

**ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE**

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

**APPLICABLE INCIDENT INFORMATION**

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash

Yes  No

Fire

Yes  No

Number of Persons Injured

Number of Deaths

Reported to Police

N

Narrative Description of Incident(S), Crash(es), and Injury(ies).  
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

DT: THE CONTACT STATES WHEN TRYING TO START VEHICLE THE ENGINE WOULD NOT START. WHEN TURNING THE IGNITION HEARD AN EXTREMELY LOUD POP. SHE RAISED THE HOOD AND DISCOVERED THE MANIFOLD COMPLETELY SHATTERED. NO REPAIRS HAVE BEEN MADE. THIS SAME PROBLEM OCCURRED PREVIOUSLY, AND THE MANIFOLD WAS REPLACED AT THE CONTACT'S EXPENSE. \*AK

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.



Providing Quality Service Since 1960

www.jcautoparts.com

JOHN HAVERMALE, Mgr. • 1004 Hwy. 24-36 East • Monroe City, MO 63456  
573-735-4099 • 888-735-4099

# Invoice

Date	Invoice #
06/03/2004	7230

Bill To
[REDACTED]
New London Mo [REDACTED]

P.O. No./Mileage	Terms	Mechanic	Year/Make	Model/VIN#
5249/206590	Due at Repair Com...	JF	98 Lumina	2G1WN52K2W [REDACTED]

Item	Description	Qty	Rate	Amount
Engine	Used	1	750.00	750.00T
Micro-V Belt	GAT K060926	1	41.10	41.10T
Spark Plug	AC 41-101	6	9.42	56.52T
Fuel Filter	Wix 33311	1	17.71	17.71T
Oil Filter	Wix 51040	1	7.50	7.50T
Air Filter	Wix 46302	1	11.31	11.31T
Wire Set	OMS 9541	1	37.80	37.80T
Gasket	Valve Cover-FEL VS50080R	1	15.96	15.96T
Anti-Freeze	Per Gal	2	13.86	27.72T
Washer Solvent		1	2.42	2.42T
Labor Rate	Labor to install fuel lines	2.1	42.00	88.20
Labor Rate	Labor to install used motor and wiring harness	14.3	42.00	600.60

<b>Subtotal</b>	\$1,656.84
<b>Sales Tax (6.85%)</b>	\$66.31
<b>Total</b>	\$1,723.15
<b>Payments/Credits</b>	\$0.00
<b>Balance Due</b>	\$1,723.15



Providing Quality Service Since 1960

www.jcautoparts.com

JOHN HAVERMALE, Mgr. • 1004 Hwy. 24-36 East • Monroe City, MO 63456  
573-735-4099 • 888-735-4099

# Invoice

Date	Invoice #
12/07/2005	11146

Bill To
[REDACTED]
New London Mo [REDACTED]

P.O. No./Mileage	Terms	Mechanic	Year/Make	Model/VIN#
9258/228072	Due at Repair Com...	JE	98 Chev Lumin	2G1WN52K2W [REDACTED]

Item	Description	Qty	Rate	Amount
Regulator	89017530	1	67.63	67.63T
Intake	DOR 615-180	1	175.48	175.48T
Labor Rate	Labor to install intake and fuel pressure regulator <i>1 yr warranty</i>		291.27	291.27
Anti-Freeze	Per Gal	2	14.16	28.32T
Manifold Set	FEL MS95809-1	1	52.90	52.90T
Oil Filter	Wix 51040	1	8.86	8.86T
brake clean	Per Can	2	2.99	5.98T
Head Gasket	FEL 9918PT	1	21.96	21.96T
Motor Oil	Per Quart	5	2.19	10.95T
Labor Rate	Labor to remove and replace intake manifold assy, #6 cyl miss, computer test dead cylinder, remove and install head and remove exhaust valve and clean plastic debris from valve seat and chamber, reassemble and change oil, filter, refill and road test		472.06	472.06

*PL*  
*Chk # 1016*  
*12-10-05*

<b>Subtotal</b>	\$1,135.41
<b>Sales Tax (6.85%)</b>	\$25.49
<b>Total</b>	\$1,160.90
<b>Payments/Credits</b>	\$0.00
<b>Balance Due</b>	\$1,160.90