



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

Repository ☐

2006 MAR 28 AM 7:13
27-FEB-2006

Reference No.
10151296

OWNER INFORMATION (Type or Print)

Name [REDACTED]
Address [REDACTED]
City **LOS GATOS** State **CA** Zip Code [REDACTED]

Daytime Telephone Number [REDACTED]

E-mail Address [REDACTED]

Evening Telephone Number [REDACTED]

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle?
In the absence of an authorized signature, provide your name or address to the vehicle manufacturer.
Signature of Owner [REDACTED] Date **3/20/2006** ☒ YES ☐ NO

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side
ZHKRL1B653H [REDACTED] Make **HONDA** Model **ODYSSEY** Model Year **1999**

Date Purchased **01-AUG-99** Dealer's Name and Telephone Number **CAPITOL HONDA** Engine: No: Cylinders **6** Fuel Type: **Gas**
Original Owner ☒ Dealer's City **SAN JOSE** State **CA** Zip Code [REDACTED]

Transmission Type **AUTOMATIC** ☒ Antilock Brakes ☒ Cruise Control **FRONT WHEEL DRIVE** Vehicle Component Code **116100 ELECTRICAL SYSTEM:IGNITION:SWITCH**
Multiple Failure: **MANY**

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s) **27-FEB-2006** Failure Mileage **72000** Failure Speed **85**

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make [REDACTED] Tire Model (Name or Number) [REDACTED] Tire Size (Example P215/65R15) [REDACTED]
DOT No. (Example: DOTM18ABC038) [REDACTED] ☐ Original Equipment ☐ Prior Repair Failure Location: [REDACTED]
Tire Component Code [REDACTED] Tire Failure Type [REDACTED]

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: [REDACTED] Date Manufactured: [REDACTED] Model No./Name: [REDACTED]
Seat Type: [REDACTED] Installation System: [REDACTED]
Child Seat Component Code: [REDACTED] Failed Part: [REDACTED]

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies).)

Crash ☐ Yes ☒ No Fire ☐ Yes ☒ No Number of Persons Injured [REDACTED] Number of Deaths [REDACTED] Reported to Police **N**

Narrative Description of Incident(s), Crash(es), and Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure;
i.e., parts repaired or replaced (and if old part is available).

DT*: THE CONTACT STATED THE ENGINE STALLED WHEN PULLING INTO OR OUT OF A PARKING SPACE. THIS STARTED ONE MONTH AGO AND HAS BEEN OCCURRING AT LEAST ONCE A WEEK SINCE THEN. THIS ALSO OCCURRED ONCE WHILE DRIVING 55 MPH. THE VEHICLE WAS STEERED OFF THE ROAD AND RESTARTED. THE VEHICLE HAS NOT BEEN SEEN BY A MECHANIC. THERE IS A NHTSA RECALL, # 02V120000, REGARDING THE IGNITION SWITCH. THE VEHICLE HAS THE SAME PROBLEMS AS INDICATED IN THE RECALL; HOWEVER, IT IS NOT INCLUDED IN THE RECALL DUE TO THE VIN.

PROBLEM STARTED TO OCCUR EVEN MORE FREQUENTLY - EVERY FEW DAYS. BECAME TOO DANGEROUS TO DRIVE, ESPECIALLY ON FREEWAYS. OUR MECHANIC INSPECTED THE IGNITION SWITCH AND REPLACED IT. THE PROBLEM WENT AWAY AND HAS NOT REOCCURED IN OVER 3 WEEKS.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

"Frequent driver"

Earn rewards for something you do every day—driving.

APP



HOME * RESEARCH * BUY NEW * BUY USED * FINANCE

Photos * Videos * Reviews * Compare * Reliability * Features * Blue Book * Build & Price

CF APP 0.0

Search

RECALLS

1999 Honda Odyssey EX

8 Recall Notices

These recall notices may not apply to all vehicles. Please contact your dealer for more details or contact the National Highway Traffic Safety Administration's Auto Safety hotline at 1-888-DASH-2-DOT (1-888-327-4236).

Select Different Vehicle



Campaign Number: 03V423000 Date: 2003-Oct-27

Component: Electrical System: Ignition: Switch

Defect Summary: ON CERTAIN PASSENGER VEHICLES AND MINI VANS, THE IGNITION SWITCH MAY WEAR EXCESSIVELY AND PREVENT PROPER INTERLOCK OPERATION, MAKING IT POSSIBLE TO TURN THE IGNITION KEY TO THE "OFF" POSITION AND REMOVE THE KEY WITHOUT SHIFTING THE TRANSMISSION TO "PARK."

Consequence Summary: IF THE VEHICLE OPERATOR DOES NOT SHIFT TO "PARK" BEFORE REMOVING THE KEY AND FAILS TO ENGAGE THE PARKING BRAKE, THE VEHICLE COULD ROLL AND A CRASH COULD OCCUR.

Corrective Summary: DEALERS WILL PERFORM AN INSPECTION PROCEDURE THAT DETERMINES THE AMOUNT OF CYLINDER BODY WEAR. IF SIGNIFICANT WEAR IS INDICATED, THE DEALER WILL REPLACE THE CYLINDER BODY, COLLAR, AND LATCH PLATE. IF NO SIGNS OF WEAR ARE INDICATED, DEALERS WILL REPLACE THE LATCH PLATE WITH A REDESIGNED PART. OWNER NOTIFICATION BEGAN DECEMBER 8, 2003. OWNERS SHOULD CONTACT HONDA AT 1-800-999-1009 OR ACURA AT 1-800-382-2238.

To schedule service online click here

Campaign Number: 02V120000 Date: 2002-May-16

Component: Electrical System: Ignition: Switch

Defect Summary: ON CERTAIN SEDANS, COUPES, HATCHBACKS, AND SPORT UTILITY VEHICLES, ELECTRICAL CONTACTS IN THE IGNITION SWITCH CAN DEGRADE DUE TO THE HIGH ELECTRICAL CURRENT PASSING THROUGH THE SWITCH WHEN THE VEHICLE IS STARTED.

Consequence Summary: WORN CONTACTS COULD CAUSE THE ENGINE TO STALL WITHOUT WARNING, INCREASING THE RISK OF A CRASH.

Corrective Summary: DEALERS WILL REPLACE THE IGNITION SWITCH. OWNER NOTIFICATION BEGAN JUNE 14, 2002. OWNERS WHO TAKE THEIR VEHICLES TO AN AUTHORIZED DEALER ON AN AGREED UPON SERVICE DATE AND DO NOT RECEIVE THE FREE REMEDY WITHIN A REASONABLE TIME SHOULD CONTACT HONDA AT 1-800-999-1009 OR ACURA AT 1-800-382-2238.

To schedule service online click here

Campaign Number: 00V183000 Date: 2000-Jul-06

Component: Interior Lighting

Defect Summary: VEHICLE DESCRIPTION: MINI VANS. THE DIMMER CONTROL FOR THE INSTRUMENT PANEL LIGHTS CAN FAIL.

Consequence Summary: AT NIGHT, THE DRIVER WOULD NOT BE ABLE TO SEE INSTRUMENT PANEL GAUGES AND DISPLAYS.

Corrective Summary: DEALERS WILL REPLACE THE MULTIPLEX UNIT.

AD

**THE ATTACHMENTS TO THIS
DOCUMENT HAVE BEEN REMOVED
TO PROTECT UNWARRANTED
INVASION OF PERSONAL PRIVACY
PURSUANT TO EXEMPTION 6 OF
THE FREEDOM OF INFORMATION
ACT (FOIA), 5 U.S.C. 552(b)(6).**