



U.S. Department of Transportation  
National Highway Traffic Safety Administration

**DOT Auto Safety Hotline**  
**Vehicle Owner's Questionnaire**  
To Report Vehicle Safety Defects  
1-888-DASH-2-DOT  
(1-888-327-4236)  
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

28-JUN-2006 54

Repository

Reference No.  
10160972

**OWNER INFORMATION (Type or Print)**

Name: [Redacted]  
Address: [Redacted]  
City: RONKONKONA State: NY Zip Code: [Redacted]

Daytime Telephone Number

Evening Telephone Number

E-mail Address

[Redacted]

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle?  YES  NO  
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner \_\_\_\_\_ Date: / /

**VEHICLE INFORMATION**

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side 2FALP74 [Redacted]	Make FORD	Model CROWN VICTORIA	Model Year 1993
Date Purchased 01-JAN-03	Dealer's Name and Telephone Number BURNS FORD		Engine: No: Cylinders 8
Original Owner <input type="checkbox"/>	Dealer's City MIDDLETOWN	State NY	Zip Code 11743
Transmission Type AUTOMATIC	Powertrain REAR WHEEL DRIVE	Vehicle Component Code 034200 SERVICE BRAKES, HYDRAULIC: FOUNDATION COMPONENTS	
<input checked="" type="checkbox"/> Cruise Control	Multiple Failure: 1		

**FAILED COMPONENT(S)/PART(S) INFORMATION**

Incident Date(s) 28-JUN-2006	Failure Mileage 107113	Failure Speed
---------------------------------	---------------------------	---------------

**ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE**

Tire Make	Tire Model (Name or Number)	Tire Size (Example P215/65R15)
DOT No. (Example: DOTM19A3C036)	<input type="checkbox"/> Original Equipment <input type="checkbox"/> Prior Repair	Failure Location:
Tire Component Code	Tire Failure Type	

**ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE**

Make:	Date Manufactured:	Model No./Name:
Seat Type:	Installation System:	
Child Seat Component Code:	Failed Part:	

**APPLICATION INCIDENT INFORMATION**

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured	Number of Deaths	Reported to Police N
--	---	---------------------------	------------------	-------------------------

Narrative Description of Incident(s), Crash(es), and Injury(ies).  
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

DT\*: THE CONTACT STATED BRAKE FLUID LEAKED OUT OF THE REAR BRAKE LINE CAUSING THE BRAKES TO BECOME INOPERATIVE. WHEN THE BRAKE PEDAL WAS DEPRESSED, THE PEDAL WENT ALL THE WAY TO THE FLOOR. THERE IS AN NHTSA RECALL # 961002000, REGARDING THE SERVICE BRAKES, HYDRAULIC: FOUNDATION COMPONENTS: HOSES, LINES/PIPING, AND AND FITTINGS. THE VIN WAS NOT INCLUDED IN THE RECALL.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY.

The Privacy Act of 1974 (Public Law 93-502) This information is requested pursuant to authority vested in the National Highway Traffic Safety Administration and subsequent Amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

2FALP 74W [REDACTED]

Lowry, Janet

From: [REDACTED]

Sent: Tuesday, June 27, 2006 6:56 AM

To: [REDACTED]

Subject: Check this

**1993 Ford Crown Victoria Recall ID from NHTSA: 961002000**

Auto Recall Date: 19980313

Vehicle Component: SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:HOSES, LINES/PIPING, AND FITTINGS

Estimated Vehicles Affected: 17600

1993 Ford Crown Victoria Defect Summary:

Defect Consequence:

Remedy:

DEALERS WILL INSPECT THE REAR BRAKE LINES, AND IF NECESSARY, REPLACE A SECTION OF THE REAR BRAKE LINES IF IT IS LEAKING. ALSO THE RUBBER SHIELD ON THE LINE WILL BE INSPECTED TO VERIFY THAT IT IS PROPERLY LOCATED AND IT WILL BE SECURED WITH AN ADDITIONAL WORM-DRIVE TYPE CLAMP.

Notes: FORD MOTOR COMPANY,

PETER  
REFERENCE [REDACTED]

95V194000

1888 327

1888-327-4236

NHTSA

**THE ATTACHMENTS TO THIS  
DOCUMENT HAVE BEEN REMOVED  
TO PROTECT UNWARRANTED  
INVASION OF PERSONAL PRIVACY  
PURSUANT TO EXEMPTION 6 OF  
THE FREEDOM OF INFORMATION  
ACT (FOIA), 5 U.S.C. 552(b)(6).**