



U.S. Department of Transportation
National Highway Traffic Safety Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received 2007 JAN 18 AM 9:40
05-JAN-2007

Repository
Reference No.
10177934

OWNER INFORMATION (Type or Print)

Name [REDACTED]
Address [REDACTED]
City FAYETVILLE State NC Zip Code [REDACTED]

Daytime Telephone Number [REDACTED]
Evening Telephone Number [REDACTED]

E-mail Address

Signature of Owner [REDACTED] Date 1/1/07

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side: 2MF1M75W4P [REDACTED]
Make MERCURY Model GRAND MARQUIS Model Year 1993
Date Purchased 10-JAN-02 Dealer's Name and Telephone Number [REDACTED] Engine: No: Cylinders Fuel Type: Gas
Original Owner [REDACTED] Dealer's City [REDACTED] State [REDACTED] Zip Code [REDACTED]
Transmission Type AUTOMATIC Antilock Brakes Cruise Control Powertrain REAR WHEEL DRIVE Vehicle Component Code 185000 VEHICLE SPEED CONTROL:CRUISE CONTROL Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s) 02-SEP-2006 Failure Mileage Failure Speed 0

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make Tire Model (Name or Number) Tire Size (Example P215/65R15)
DOT No. (Example: DOTM19ABC036) Original Equipment Prior Repair Failure Location:
Tire Component Code Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: Date Manufactured: Model No./Name:
Seat Type: Installation System:
Child Seat Component Code: Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please respond in detail the accident(s), failure(s), crash(es), and injury(ies).)

Crash Yes No Fire Yes No Number of Persons Injured 0 Number of Deaths 0 Reported to Police Y

Narrative Description of Incident(S), Crash(es), and Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e, parts repaired or replaced (and if old part is available).

TL* - THE CONTACT STATED THAT FORD ISSUED A RECALL NOTICE 99V124000 ON THE SPEED CONTROL DEACTIVATION SWITCH OF THE 1993 MERCURY GRAND MARQUIS. THE RECALL STATED THAT THE VEHICLE COULD DEVELOP A RESISTIVE SHORT IN THE ELECTRICAL CIRCUIT THAT COULD POTENTIALLY RESULT IN A FIRE UNDER THE HOOD. HE CONTACTED FORD, AND THEY DENIED IT. THE CONTACT TOOK THE VEHICLE TO THE LOCAL DEALERSHIP TO HAVE THE RECALL REPAIRS PERFORMED AND THEY DENIED HIM. THE CONTACT'S VEHICLE CAUGHT ON FIRE AND WAS DESTROYED. *AK

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.