



U.S. Department of Transportation
National Highway Traffic Safety Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

Repository

2007 DEC 12 PM 12:36
15-OCT-2007

Reference No.
10205722

OWNER INFORMATION (Type or Print)

Name [REDACTED]
Address [REDACTED]
City LAKEWOOD State NJ Zip Code [REDACTED]

Daytime Telephone Number 7328860160
Evening Telephone Number [REDACTED]
E-mail Address [REDACTED]

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES NO
In the absence of an authorized name or address to the vehicle manufacturer.
Signature of Owner [REDACTED] Date 10/19/2007

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side 1GCGK29F8 [REDACTED]
Make CHEVROLET Model SILVERADO 2500 Model Year ~~2000~~ 1999
Date Purchased ~~01-APR-06~~ Dealer's Name and Telephone Number FRANCINI CHEVROLET Engine: No: Cylinders 8 Fuel Type: Diesel
Original Owner Dealer's City GARFIELD State NJ Zip Code [REDACTED]
Transmission Type AUTOMATIC Antilock Brakes Cruise Control Powertrain 4-WHEEL DRIVE
Vehicle Component Code 036000 SERVICE BRAKES, HYDRAULIC:ANTILOCK
Multiple Failure: 5

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s) 01-MAY-2007 Failure Mileage 94000 Failure Speed < 15MPH
ANTILOCK BRAKE SYSTEM

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make [REDACTED] Tire Model (Name or Number) [REDACTED] Tire Size (Example P215/65R15) [REDACTED]
DOT No. (Example: DOTMAL9ABC036) Original Equipment Prior Repair Failure Location: [REDACTED]
Tire Component Code [REDACTED] Tire Failure Type [REDACTED]

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: [REDACTED] Date Manufactured: [REDACTED] Model No./Name: [REDACTED]
Seat Type: [REDACTED] Installation System: [REDACTED]
Child Seat Component Code: [REDACTED] Failed Part: [REDACTED]

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash Yes No Fire Yes No
Number of Persons Injured 0 Number of Deaths 0 Reported to Police N

Narrative Description of Incident(s), Crash(es), and Injury(ies):
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

TL*THE CONTACT OWNS A ~~2000~~ 1999 CHEVROLET SILVERADO 2500. WHILE APPROACHING A STOP, THE ABS ACTIVATED AND THE VEHICLE BEGAN TO SWERVE FROM RIGHT TO LEFT. THE VEHICLE FINALLY STOPPED APPROXIMATELY ONE VEHICLE LENGTH AWAY. THE CONTACT REMOVED THE ABS FUSE AND THE VEHICLE STOPPED NORMALLY. THE DEALER WAS NEVER NOTIFIED REGARDING THE FAILURE. THE SPEED WAS UNKNOWN. THE CURRENT MILEAGE WAS 105,000 AND FAILURE MILEAGE WAS 94,000.

ENCLOSED FIND CAMPAIGN # 05U379000 which describes problem.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Campaign Number: 06V066000 Date: 2006-Mar-08
Component: Structure: Body: Tailgate: Hinge And Attachments

Defect Summary: CERTAIN PICKUP TRUCKS HAVE GALVANIZED-BRAIDED-STEEL TAILGATE SUPPORT CABLES USED TO SUPPORT THE TAILGATE IN THE FULL OPEN (HORIZONTAL) POSITION. OVER TIME THESE CABLES CAN CORRODE AND FRACTURE WHEN LOADS ARE APPLIED TO THEM.

Consequence Summary: IF ONE CABLE FRACTURES, THE REMAINING CABLE MAY RETAIN THE TAILGATE IN A HORIZONTAL POSITION. IF BOTH CABLES FRACTURE, THE TAILGATE WOULD DROP AND STRIKE THE TOP SURFACE OF THE REAR BUMPER. IF ANYONE IS SITTING OR STANDING ON THE HORIZONTAL SURFACE OF THE TAILGATE WHEN BOTH CABLES FRACTURED, THEY COULD FALL AND BE INJURED. ON VEHICLES WITHOUT A BUMPER, THE TAILGATE MAY DROP TO A LOWER POSITION.

Corrective Summary: DEALERS WILL REPLACE THE GALVANIZED SUPPORT CABLES WITH STAINLESS STEEL SUPPORT CABLES. IN ADDITION, DEALERS ARE TO INSPECT THE TAILGATE HINGE AND REPLACE IT, IF NECESSARY. THE RECALL IS EXPECTED TO BEGIN DURING APRIL 2006. OWNERS MAY CONTACT CHEVROLET AT 1-800-630-2438 OR GMC AT 1-866-996-9463.

GM # 15 05068

Campaign Number: 05V379000 Date: 2005-Aug-29
Component: Service Brakes, Hydraulic: Antilock

Defect Summary: CERTAIN PICKUP TRUCKS AND SPORT UTILITY VEHICLES MAY EXPERIENCE UNWANTED ANTILOCK BRAKE SYSTEM (ABS) ACTIVATION. THIS CONDITION IS MORE LIKELY TO OCCUR IN ENVIRONMENTALLY CORROSIVE AREAS. THIS RECALL WILL BE LAUNCHED IN THE "SALT BELT" STATES OF CONNECTICUT, DELAWARE, ILLINOIS, INDIANA, IOWA, MARYLAND, MASSACHUSETTS, MAINE, MICHIGAN, MINNESOTA, MISSOURI, NEW HAMPSHIRE, NEW JERSEY, NEW YORK, OHIO, PENNSYLVANIA, RHODE ISLAND, VERMONT, WEST VIRGINIA, WISCONSIN AND THE DISTRICT OF COLUMBIA ONLY.

Consequence Summary: THIS CAN CAUSE INCREASED STOPPING DISTANCES DURING LOW-SPEED BRAKE APPLICATIONS, WHICH COULD RESULT IN A CRASH.

Corrective Summary: DEALERS ARE TO REMOVE THE WHEEL SPEED SENSOR AND THOROUGHLY CLEAN THE WHEEL SPEED SENSOR MOUNTING SURFACE ON THE BEARING, APPLY RUST INHIBITOR TO THE CLEANED SURFACE, GREASE THE MOUNTING SURFACE, REINSTALL THE WHEEL SPEED SENSOR, AND CHECK THE PEAK-TO-PEAK OUTPUT VOLTAGE TO ENSURE THE WHEEL SPEED SIGNAL IS WITHIN SPECIFICATIONS. THE RECALL BEGAN SEPTEMBER 22, 2005. OWNERS MAY CONTACT CHEVROLET AT 1-800-630-2438 OR GMC AT 1-866-996-9463.

GM 1-800-462-8782

NATIONAL Highway & TRAFFIC SAFETY ADMIN
1-888-327-4236

VIN 1GCGK29F [REDACTED]
CASE [REDACTED]



LIMITED LABOR WARRANTY

This Repair Facility guarantees the labor used in performing the repairs listed on the front of the Repair Order for a period of 12 months or 12,000 miles (whichever comes first) from the date such repairs were completed. This Limited Warranty specifically excludes: front end alignments, electrical wiring and shorts, and fuel system - when due to contamination. This Limited Warranty is extended to the vehicle owner/customer and is not transferable to, nor enforceable by, any other person.

During the duration period of this Limited Warranty, the Repair Facility will provide additional labor, at no expense to customer, for any additional repairs that are necessitated as a result of any defect in labor performed while completing the repairs listed on the front of the Repair Order.

To obtain repairs under this Limited Warranty, customer must: (a) notify the Repair Facility at the address shown on the front of the Repair Order of any defect in labor within a reasonable time after customer discovers or should have discovered any such defect. Such notice, however, must be given to the Repair Facility before the end of the duration period of this Limited Warranty, as specified above; (b) deliver the vehicle to the Repair Facility at the address shown on the front of the Repair Order within (5) days of notice of such defect in labor; (c) authorize the Repair Facility to make the repairs required; and (d) pay the charges for any additional parts required together with applicable sales tax upon completion of such repair.

All implied warranties, including the implied warranties of merchantability and fitness for a particular purpose, are limited to the duration period of this limited warranty. Under no circumstances will the Repair Facility be liable to customer for any incidental or consequential damages including, but not limited to, damages for loss of property, loss of vehicle use, loss of time, loss of income and profits, inconvenience or commercial loss.

This part(s) is sold "as is". The only warranties applying to this part(s) are those which may be offered by the manufacturer(s). The selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss or profits or income, or any other incidental damages. In addition, expressly excluded is any dealer liability for defects pertaining to safety or performance, by way of "strict liability", negligence or otherwise.

THE ATTACHMENTS TO THIS
DOCUMENT HAVE BEEN REMOVED
TO PROTECT UNWARRANTED
INVASION OF PERSONAL PRIVACY
PURSUANT TO EXAMPTION 6 OF
THE FREEDOM OF INFORMATION
ACT (FOIA), 5 U.S.C. 552(b)(6).