



U.S. Department of Transportation  
National Highway Traffic Safety Administration

**DOT Auto Safety Hotline**  
**Vehicle Owner's Questionnaire**  
To Report Vehicle Safety Defects  
1-888-DASH-2-DOT  
(1-888-327-4236)  
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received  
24-OCT-2007  
-6 AM 8:37

Repository   
Reference No.  
10206741

2007 NOV

**OWNER INFORMATION (Type or Print)**

Name: [REDACTED]  
Address: [REDACTED]  
City: NEW BRACKTON BRACKTON State AL Zip Code [REDACTED]  
Daytime Telephone Number: [REDACTED] E-mail Address: [REDACTED]  
Evening Telephone Number: [REDACTED]  
Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle?  YES  NO  
In the absence of a signature, please provide your name or address to the vehicle manufacturer.  
Signature of Owner: [REDACTED] Date: 10/29/07

**VEHICLE INFORMATION**

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side: 3GKEC16Z8 [REDACTED]  
Make: GMC Model: YUKON XL Model Year: 2002  
Date Purchased: 01-AUG-02 Dealer's Name and Telephone Number: NICHOLS GMC  
Engine: No: Cylinders 8 Fuel Type: Gas  
Original Owner:  Dealer's City: ENTERPRISE State AL Zip Code 36330  
Transmission Type: AUTOMATIC  Antilock Brakes  Cruise Control  
Powertrain: REAR WHEEL DRIVE  
Vehicle Component Code: 036000 SERVICE BRAKES, HYDRAULIC:ANTILOCK  
Multiple Failure: 10

**FAILED COMPONENT(S)/PART(S) INFORMATION**

Incident Date(s): 01-OCT-2006 Failure Mileage: 79000 Failure Speed: 55 MPH  
ABS MODULE. ABS PUMP RUNS CONTINUOUSLY. MUST PUSH FUSE.

**ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE**

Tire Make: [REDACTED] Tire Model (Name or Number): [REDACTED] Tire Size (Example P215/65R15): [REDACTED]  
DOT No. (Example: DOTM9ABC036): [REDACTED]  Original Equipment  Prior Repair Failure Location: [REDACTED]  
Tire Component Code: [REDACTED] Tire Failure Type: [REDACTED]

**ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE**

Make: [REDACTED] Date Manufactured: [REDACTED] Model No./Name: [REDACTED]  
Seat Type: [REDACTED] Installation System: [REDACTED]  
Child Seat Component Code: [REDACTED] Failed Part: [REDACTED]

**APPLICABLE INCIDENT INFORMATION**  
(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash:  Yes  No Fire:  Yes  No  
Number of Persons Injured: 0 Number of Deaths: 0 Reported to Police: N

**Narrative Description of Incident(S), Crash(es), and Injury(ies).**  
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

TL\*THE CONTACT OWNS A 2002 GMC YUKON XL. THE CONTACT STATED THAT THE ABS WAS FAILING AND THE ANTILOCK BRAKING PUMP CONTINUOUSLY RUNS. HE TOOK THE VEHICLE TO THE DEALER AND THEY INFORMED HIM THAT THE PAD-CIRCUIT BOARD WAS FAILING AND CAUSED THE PUMP TO RUN AT HIGH SPEEDS. THIS COULD LEAD TO OVERHEAT AND A POSSIBLE FIRE. THE FAILURE OCCURS AFTER DRIVING THE VEHICLE AT SPEEDS GREATER THAN 55 MPH. WHEN THE ENGINE WAS SHUT OFF, IT MADE A DRENCHING NOISE. HE SEARCHED AND DISCOVERED NHTSA CAMPAIGN ID NUMBER 05V379000 (SERVICE BRAKES, HYDRAULIC:ANTILOCK). THE RECALL ONLY APPLIES TO CERTAIN STATES AND HIS VIN WAS NOT INCLUDED. THE VEHICLE HAS NOT BEEN REPAIRED. THE FAILURE MILEAGE WAS 79,000 AND CURRENT MILEAGE WAS 93,000.  
OVERHEAT High pitched noise  
SEE SEPARATE DOCUMENT FROM COMPANY THAT REPAIR THESE PROBLEMS.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY  
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.



Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

There is a known failure systemic to the  
Vauxhall HANES ABS Module. Several web sites  
describe the problem & cost to repair.

I think GMC should recall the module &  
provide repair to upgraded non OEM  
module.

ATTACH ADDITIONAL SHEETS IF NECESSARY

U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

400 Seventh St., S.W.  
Washington, D.C. 20590

Official Business  
Penalty for Private Use \$300

MONTGOMERY AL 361

31 OCT 2007 PM 4 T

NO POSTAGE  
NECESSARY  
IF MAILED  
IN THE  
UNITED STATES

**BUSINESS REPLY MAIL**

FIRST CLASS PERMIT NO 73173 WASHINGTON, D.C.

POSTAGE WILL BE PAID BY NATL. HWY. TRAFFIC SAFETY ADMIN.


U.S. Department of Transportation  
National Highway Traffic Safety Administration  
Office of Defects Investigation, NVS-210  
400 7th Street, SW  
Washington, DC 20590



400 SEVENTH ST SW WASHINGTON DC 20590



Think your vehicle  
has a safety defect?



If so:  
Use the enclosed  
form to file a report.

or visit:


[www.safercar.gov](http://www.safercar.gov)

or call:

Vehicle Safety Hotline  
888-327-4236



Vehicle Owner's Questionnaire (VOQ)  
U.S. Department of Transportation  
National Highway Traffic Safety Administration




# WWW - ModuleMaster.com

The ABS Module Experts

- FAQ
- About Us
- Contact Us
- Home
- ABS Repair
- ABS Codes
- Repair Info
- Diagrams

## General Motors ABS Module Repair - \$150 Flat Rate

### Kelsey Hayes EBCM ABS Module



Click ABS Module Lg. Picture

Applies to the following AC Delco ABS Module part numbers:

- 88982285, 88982288
- 88982302, 88935872
- 88935286, 88982299
- 88982323, 88982287
- 88982286, 15100884
- 88982938, 10356388

### 1999-2003 Kelsey Hayes (TM) ABS Module

#### Common problems with this ABS module:

- Constantly running pump
- Internal EBCM logic failure
- Water penetration

We provide a complete ABS repair and upgrade service **with a 5-year warranty** for your following ABS modules: **GMC or Chevy Silverado, Yukon, Trailblazer, Suburban, Bravada, Sonoma, K2500, Envoy, Sierra, Z71, Tahoe, Blazer, Jimmy, S-10, S-15, Isuzu Rodeo and Amigo, Honda Passport or Opel Frontera** equipped with a 1999+ Kelsey Hayes(TM) ABS module control.

### Click HERE for ABS Module Removal Instructions

This repair is permanent - definitely exceeding original design expectations. It is not a quick-fix "patch" or other temporary type of repair. The replacement parts selected are significantly better and more costly than the OEM originals to avoid any future recurring problems.

If you experienced a constantly running pump motor and had to pull the fuse, and face orange and red dashboard lights, this repair will solve your problem permanently and save you major money. Your trade in value will immediately increase by \$1000.00 after the repair as this is what dealers look for. The pump and manifold are okay, the electronic control module is at fault and can be properly serviced without costly replacement. The module must be upgraded by ModuleMaster for the permanent solution.