



U.S. Department of Transportation
National Highway Traffic Safety Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT 2007 DEC 12 AM 11:03
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received	Repository <input type="checkbox"/>
03 NOV-2007	Reference No. 10208425

OWNER INFORMATION (Type or Print)

Name	Daytime Telephone Number	E-mail Address
[REDACTED]	9738350631	[REDACTED]
Address	Evening Telephone Number	
[REDACTED]	9739341603	
City WAYNE	State NJ	Zip Code [REDACTED]

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES NO
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.
Signature of Owner [REDACTED] Date 12/13/2007

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side 1GTGC29R1V [REDACTED]	Make GMC	Model SIERRA	Model Year 1997
Date Purchased 01-OCT-99	Dealer's Name and Telephone Number		Engine: No: Cylinders 8
Original Owner <input type="checkbox"/>	Dealer's City	State	Zip Code
Transmission Type AUTOMATIC	<input checked="" type="checkbox"/> Antilock Brakes <input checked="" type="checkbox"/> Cruise Control	Powertrain REAR WHEEL DRIVE	Fuel Type: Gas
Vehicle Component Code 136000 VISIBILITY:WINDSHIELD WIPER/WASHER		Multiple Failure: 1	

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s) 01-NOV-2007	Failure Mileage 90433 ?	Failure Speed 0
---------------------------------	----------------------------	--------------------

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make	Tire Model (Name or Number)	Tire Size (Example P215/65R15)
DOT No. (Example: DOTM19ABC036)	<input type="checkbox"/> Original Equipment <input type="checkbox"/> Prior Repair	Failure Location:
Tire Component Code	Tire Failure Type	

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:	Date Manufactured:	Model No./Name:
Seat Type:	Installation System:	
Child Seat Component Code:	Failed Part:	

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured 0	Number of Deaths 0	Reported to Police N
--	---	--------------------------------	-----------------------	-------------------------

Narrative Description of Incident(S), Crash(es), and Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

TL*THE CONTACT OWNS A 1997 GMC SIERRA. THE WINDSHIELD WIPERS WOULD NOT OPERATE. THE VEHICLE WAS NOT INSPECTED BY A DEALER. THE MANUFACTURER STATED THAT THE VIN WAS NOT INCLUDED IN NHTSA CAMPAIGN ID NUMBER 03V159000 (VISIBILITY:WINDSHIELD WIPER/WASHER). THE CURRENT AND FAILURE MILEAGES WERE 90,433.

INITIAL FAILURE OCCURED SOME TWO YEARS AGO. I PERSONALLY "FIXED" THE PROBLEM! OBSERVING A WARPED COVER ON THE WIPER MOTOR ASSY ALLOWING DIRT & MOISTURE TO ACCUMULATE ON THE TC BOARD, - CLEANED UNIT & SEALED WARPED COVER WITH SILICON - AGAIN FAILED OCT 2007.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

FALL 07 WAS ADVISED BY FRIENDS ABOUT GM RECALL - WENT ON INTERNET AND READ INFO. SOURCE IN RECALL IS EXACTLY WHAT MY PROBLEM IS. ALTHOUGH I CANNOT SEE ANY COLD SOLDER JOINTS, TRUCK TO BE REPAIRED WEEK OF 11-13-07 BY LOCAL CHEV(GM) DEALER