



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

Repository

16 MAR 2008

Reference No.
10221402

OWNER INFORMATION (Type or Print)

Name [REDACTED]
Address [REDACTED]
City POLAND State OH Zip Code [REDACTED]

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle?
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.
Signature of Owner [REDACTED] Date 03/29/08 YES NO

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side: 1G1ZG57BX84 [REDACTED]
Make CHEVROLET Model MALIBU Model Year 2008
Date Purchased 28-FEB-08 Dealer's Name and Telephone Number SWEENEY CHEVROLET 800-686-6141 Engine: No: Cylinders 4 Fuel Type: Gas
Original Owner Dealer's City ~~BOARDMAN~~ BOARDMAN State OH Zip Code 44513
Transmission Type AUTOMATIC Antilock Brakes Cruise Control Powertrain FRONT WHEEL DRIVE Vehicle Component Code 194000 TIRES:VALVE Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s) 16-MAR-2008 Failure Mileage 156 Failure Speed 45

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make UNIROYAL Tire Model (Name or Number) TIGERPAW Tire Size (Example P215/65R15) P215/60R16
DOT No. (Example: DOTM19ABC036) APX8BE5U2007 Original Equipment Prior Repair Failure Location:
Tire Component Code 194000 TIRES:VALVE Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: Date Manufactured: Model No./Name:
Seat Type: Installation System:
Child Seat Component Code: Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash Yes No Fire Yes No Number of Persons Injured 0 Number of Deaths 0 Reported to Police N

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

TL*THE CONTACT OWNS A 2008 CHEVROLET MALIBU. THE VEHICLE HAS UNIROYAL TIGERPAW TIRES. WHILE DRIVING 45 MPH, THE FRONT DRIVER'S SIDE TIRE VALVE FELL INSIDE OF THE TIRE AND CAUSED IT TO FAIL. THE TIRE VALVE WAS REPLACED. THE MONITORING SYSTEM ACTIVATES AFTER THE FAILURE OCCURS. THE TIRE SIZE WAS UNKNOWN. THE CURRENT MILEAGE WAS 196 AND FAILURE MILEAGE WAS 156.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

7577404

154528



INVOICE

8010 MARKET STREET
P.O. BOX 3540
YOUNGSTOWN, OH 44513
PHONE: (330) 758-7521

PAGE 1

POLAND, OH
HOME: [REDACTED] BUS:

SERVICE ADVISOR: 7515 MARK MORAN

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG	
PEWTER	08	CHEVROLET MALIBU	1G1ZG57BX84		196/196		
DEL DATE	PROD DATE	WARR EXP	PROMISED	PO NO.	RATE	PAYMENT	INV DATE
27FEB08 DD			WAIT 17MAR08			CASH	17MAR08

R.O. OPENED	READY	OPTIONS: STK:5377
08:06:17MAR08	08:33:17MAR08	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A DISMOUNT/REMOUNT TIRE (RE-INSTALL TEMS VALVE STEM) CHECK FOR LEAK & REBALANCE							

CAUSE: CS21-1 TIRE MOUNT AND BALANCE (N/C)
 196 DISMOUNTED TIRE FOUND VALVE STEM NOT SEALED CORRECTLY.
 RE-INSTALLED VALVE STEM AND CHECKED ALL OTHERS.



WARRANTY STATEMENT AND DISCLAIMER
 The only warranty on parts and products sold in conjunction with repairs performed by Dealer are those of the manufacturer or supplier of said parts or products. Dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for any liability in connection with the sale of parts or products. Dealer warrants its workmanship in conjunction with repairs performed by Dealer for 90 days or 4,000 miles, whichever comes first. If there is a failure within the stated period due to our workmanship we will perform the necessary labor to remedy the failure. You are responsible for the cost of any necessary parts and products.

SHOP SUPPLY COSTS: We have added a charge equal to 8% of the cost of labor, not to exceed \$15.00, to the Repair Order for shop supplies used in connection with the repair.
 ALL PARTS INSTALLED ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS/OIL/LUBE	0.00
SUBLET AMOUNT	0.00
MISC CHARGES	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00

TO ORDER: www.repsource.com, 1-800-344-0966, fax 1-800-331-9035
GSP-99-94 (4/07)

CUSTOMER COPY

