



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
2008 NOV -6 PM 1:58
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

07-OCT-2008

Repository ☐

Reference No.
10244625

OWNER INFORMATION (Type or Print)

Name

Address

City

BROOKEN ARROW

State OK

Zip Code

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☒ YES ☒ NO
In the absence of an authorized signature, ~~you must~~ NOT provide your name or address to the vehicle manufacturer.
Signature of Owner _____ Date 10/25/2008

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side

1FTEF15N3L

Make

FORD

Model

F150

Model Year

1990

Date Purchased

Dealer's Name and Telephone Number

Engine:

No: Cylinders

Fuel Type:

Gasoline

Original Owner

Dealer's City

State

Zip Code

Transmission Type

☐ Antilock Brakes

Powertrain

☒ Cruise Control

Vehicle Component Code

070000 FUEL SYSTEM, GASOLINE

Multiple Failure:

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)

03-OCT-2008

Failure Mileage

160000

Failure Speed

0

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM19ABC036)

☐ Original Equipment

☐ Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash

☐ Yes ☒ No

Fire

☐ Yes ☒ No

Number of Persons Injured

0

Number of Deaths

0

Reported to Police

N

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

TL*THE CONTACT OWNS A 1990 FORD F150. WHILE THE ENGINE WAS OPERATING, FUEL WAS LEAKING OUT OF THE FILLER NECK OF THE FRONT FUEL TANK IN LARGE AMOUNTS. THE VEHICLE WAS TAKEN TO AN INDEPENDENT MECHANIC AND THEY REFERENCED NHTSA CAMPAIGN ID NUMBER 93V125000 (FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY). THE RECALL STATES THAT A MALFUNCTIONING CHECK VALVE WITHIN THE FUEL PUMP ASSEMBLY CAUSES A PORTION OF THE UNUSED FUEL FROM ONE TANK TO BE RETURNED TO THE SECOND TANK. WHEN THIS OCCURS, THE CAPACITY OF THE SECOND TANK CAN BE EXCEEDED, CAUSING FUEL SPILLAGE. THE CURRENT AND FAILURE MILEAGES WERE LESS THAN 160,000.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

PRO-TOUCH IMPORT AUTO & REPAIR

900 SOUTH 9TH. * BROKEN ARROW * OK 74012

PO #

Date: 10/10/2008

Invoice #

25499

Phone1

Phone2

Ext.

Vin # : 1FTEF15N3LP

Yr/Make : 1990 FORD

Model : F150

Plate :

Miles : 169301

Motor Hours :

Writer : ROGER

Date : 10/03/2008

Motor :

Unit # : 1266

Work To Be Performed

fuel runing out of front tank

Quantity	Part Number / Tech	Description	Parts	Labor
1.00	005840	FUEL PUMP	\$193.63	
1.00	FF679	FUEL FILTER	\$10.43	
	GASTINEAU	C:FUEL RUNING OUT OF FRONT TANK		\$234.60
		C:CHECK RETURN HOSE FOR BLOCKAGE [OK], FUEL		
		RETUN NOT OPENING UP IN REAR PUMP , PUMP BAD		
		R: R&R FUEL TANK & REPLACE FUEL PUMP		
	GASTINEAU	R: REPLACE FUEL FILTER		\$27.60
	Sublet	GAS		\$10.00

THANKS FOR BRINGING YOUR VEHICLE TO US FOR REPAIRS OUR COMMITMENT TO YOU IS QUALITY AND EXCELLENCE, IF YOU THINK YOUR VEHICLE NOT WRIGHT CALL STEVE OR ROGER THE OWENERS OF PRO TOUCH, WE WILL MAKE IT WRIGHT, WE STAND IN FRONT OF OUR WORK !

Service Recommendations

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of testing, inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.

X

Received By

Labor	\$262.20
Parts	\$204.06
	\$0.00
	\$0.00
Towing	\$0.00
Sublet	\$10.00
Sales Tax	\$18.40
Shop Charge	\$8.00
F.E.T.	\$0.00
Inspection	\$0.00
Amount Paid	\$0.00
Total Due	\$502.66