 <p>U.S. Department of Transportation National Highway Traffic Safety Administration</p>	<p>DOT Auto Safety Hotline</p> <p>Vehicle Owner's Questionnaire To Report Vehicle Safety Defects</p> <p>2009 FEB 17 PM 4:58 PH-888-488-4888 (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline</p>		FOR AGENCY USE ONLY 100148	
	Date Received 06-JAN-2009		Repository <input type="checkbox"/> Reference No. 10254044	
OWNER INFORMATION (Type or Print)				
Name		Daytime Telephone Number		E-mail Address
Address		Evening Telephone Number		
City	State	Zip Code		
NORTH ROYALTON	OH			
Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? <input checked="" type="checkbox"/> YES <input checked="" type="checkbox"/> NO In the absence of an address to the vehicle manufacturer. Signature of Owner _____ Date <u>1-20-09</u>				
VEHICLE INFORMATION				
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side JN1CA21A5W		Make NISSAN	Model MAXIMA	Model Year 1998
Date Purchased 7/30/98	Dealer's Name and Telephone Number NORTH COAST NISSAN 440 884-7800		Engine: No: Cylinders 6	Fuel Type: GASOLINE
Original Owner <input type="checkbox"/>	Dealer's City	State	Zip Code	
Transmission Type AUTOMATIC	<input checked="" type="checkbox"/> Antilock Brakes	Powertrain	Multiple Failure:	Incident Date(s) 22-NOV-2002
	<input checked="" type="checkbox"/> Cruise Control			
FAILED COMPONENT(S)/PART(S) INFORMATION				
Vehicle Component Code: 140000 AIR BAGS			Failure Mileage 40278	Failure Speed 0
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE				
Tire Make	Tire Model (Name or Number)		Tire Size (Example P215/65R15)	
DOT No. (Example: DOTM19ABC036)	<input type="checkbox"/> Original Equipment <input type="checkbox"/> Prior Repair		Failure Location:	
Tire Component Code				Tire Failure Type:
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE				
Make:	Date Manufactured:	Model No./Name:		
Seat Type:	Installation System:			
Child Seat Component Code:	Failed Part:			
APPLICABLE INCIDENT INFORMATION <i>(Please describe in detail the incident(s), Failure(s), Crash(es), and injury (ies).)</i>				
Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured 0	Number of Deaths 0	Reported to Police N
<p>Narrative Description of Incident(S), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).</p> <p>TL*THE CONTACT OWNS A 1998 NISSAN MAXIMA. THE CONTACT STATED THAT THE AIR BAG SENSOR WARNING INDICATOR CONTINUED TO ILLUMINATE ON THE INSTRUMENT PANEL. THE AIR BAG MODULE ASSEMBLY WAS REPLACED UNDER WARRANTY. ON A SEPARATE OCCASION, THE AIR BAG WARNING INDICATOR FLASHED ON THE INSTRUMENT PANEL. THE DEALER PERFORMED A DIAGNOSTIC AND RECOMMENDED REPLACING THE PASSENGER SIDE AIR BAG MODULE AGAIN AT AN ESTIMATED COST OF \$709. IN THE EVENT OF A CRASH, THE AIR BAGS WOULD NOT DEPLOY. THE FAILURE MILEAGE WAS 40,278 AND CURRENT MILEAGE WAS 82,000.</p>				
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY				
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.				

1/28/2009

US Department of Transportation
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE.
Washington, D.C. 20590

I am reporting the failure of an airbag sensor. This is a safety issue for me due to the fact that the air bags will not deploy in my vehicle in the event of a collision. Air bags are standard equipment on all vehicles because of the overwhelming evidence that they save lives in the event of a collision. My position is that air bags and their components should be covered for the lifetime of the vehicle by the manufacturer (especially if the manufacturer knows that the part is faulty). Previously, I have had an airbag sensor replaced. This was done under warranty. Nissan customer service was contacted concerning this recent failure and will not assist with the repair. Their position is that the vehicle is out of warranty and Nissan is not obligated to repair the air bag assembly. The cost of the repair is estimated at \$709.00.

Enclosed are copies of the repair invoice for the replaced air bag assembly in 2003 and the diagnostic in 2009 indicating the failure of the air bag module.

My contact person for Nissan Consumer repairs was Mandy Murray: 1-866-799-1690x1626.
My case number with Nissan is _____

Further investigation on the internet reveals several other similar complaints on the web site: The Center for Auto Safety. Three complaints were documented with their vehicle VIN #. In each case, Nissan was contacted for assistance to pay for the repair and apparently they refused.

Finally, there are several technical service bulletins printed concerning the air bag system in the 1998 Nissan Maxima. I have not ordered any of them, but have included the reports from your web site.

Because Nissan is unwilling to assist with the repairs, it appears that the only way to get the repairs performed on the vehicles that are still on the road is to issue a mandatory recall. In the interest of public safety and corporate responsibility, I am requesting that all 1998 Nissan Maximas (and other model year vehicles that appear to have faulty air bag sensors) be recalled by Nissan to inspect and replace the known air bag defect in their vehicles.

Sincerely,



987206

91514

INVOICE



7168 Pearl Road
MIDDLEBURG HTS., OHIO 44130
Phone 884-7800

N ROYALTON, OH
HOME: _____ BUS: _____

PAGE 1

SERVICE ADVISOR: 30 MIKE MCNEELEY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
PEBBLE BEI	98	NISSAN MAXIMA	JN1CA21A5W		40278/40278		
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30JUL1998			17:00 06FEB03		70.00	CASH	06FEB2003
R.O. OPENED	READY	OPTIONS: STK:7206 DLR:22016					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CUSTOMER STATES AIR BAG LIGHT FLASHING INSTALL ORDERED PART.
CAUSE: INTERNAL FAILURE.

RQ32AA RPL ONE SIDE AIR BAG MODULE ASSY
88 W93 0.40 (N/C)

1 K8EHA-7L002 MODULE ASM (N/C)

RQ666A COMBINATION: AIR BAG CONSULT TROUBLE
DIAGNOSIS
88 W93 0.20 (N/C)

FC: HD32
PART#: K8EHA-7L002
COUNT:
CLAIM TYPE: PP
AUTH CODE:

B OIL AND FILTER CHANGE, TOP OFF FLUIDS, 14 PT. INSPECTION
XL30 OIL AND FILTER CHANGE, TOP OFF FLUIDS, 14 PT.
INSPECTION
88 CP 0.30
1 15208-9E000 FILTER OIL 6.75 10.08 10.08
1 OIL 8.62 5.25 5.25
1 11026-01M02 WASHER-DRA 1.44 8.62 8.62
1.44 1.44 1.44

C CUSTOMER STATES CHECK BRAKES
1100 INCLUDED IN LINE H
88 CP 0.00 0.00 0.00

D CUSTOMER STATES CHECK ENGINE LIGHT ON
1100 REPLACE VENT CONTROL VALVE.
88 CP 1.50
1 14935-54U04 VALVE ASSY 59.98 105.00 105.00
59.98 59.98 59.98

E** REPLACE BATTERY
1100 REPLACE BATTERY

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	DESCRIPTION	TOTALS
		LABOR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		LESS INSURANCE	
		SALES TAX	
(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

987206

91514

INVOICE



7168 Pearl Road
MIDDLEBURG HTS., OHIO 44130
Phone 884-7800

N ROYALTON, OH
HOME:

BUS:

PAGE 2

SERVICE ADVISOR: 30 MIKE MCNEELEY

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/OUT, TAG. Includes details for PEBBLE BEI 98 NISSAN MAXIMA and service dates.

Main service list table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Lists items like F** REPLACE DRIVE BELTS, G** FLUSH COOLANT, H** REPLACE TRANSMISSION FLUID, I** REPLACE FRONT BRAKE PADS, J** MACHINE FRONT BRAKE ROTORS, K** REPLACE REAR BRAKE PADS.

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER.

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item/items.

Summary table with columns: DESCRIPTION, TOTALS. Rows include LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES, TOTAL CHARGES, LESS INSURANCE, SALES TAX, PLEASE PAY THIS AMOUNT.

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

CUSTOMER COPY

987206

91514

INVOICE



7168 Pearl Road
MIDDLEBURG HTS., OHIO 44130
Phone 884-7800

N ROYALTON, OH
HOME:

3US:

PAGE 3


SERVICE ADVISOR: 30 MIKE MCNEELEY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
PEBBLE BEI	98	NISSAN MAXIMA	JN1CA21A5W		40278/40278		
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30JUL1998			17:00 06FEB03		70.00	CASH	06FEB2003
R.O. OPENED	READY	OPTIONS: STK:7206 DLR:22016					
07:44 06FEB03	11:43 06FEB03						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	44060-7E690	PAD KIT-DI			49.99	49.99	49.99
1	44080-54C29	HARDWARE K			26.40	26.40	26.40

L** REPLACE REAR BRAKE ROTORS - CLEAN AND LUBE CALIPER SLIDES							
RRR REPLACE REAR BRAKE ROTORS - CLEAN AND LUBE CALIPER SLIDES							
		88	CP	1.00		70.00	70.00
2	31134	R ROTORS			49.98	49.98	99.96

CHEMICALS & MATERIALS USED FOR REPAIRS							10.00



ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	DESCRIPTION	TOTALS
		LABOR AMOUNT	585.03
		PARTS AMOUNT	434.96
		GAS, OIL, LUBE	0.00
		SUBLET AMOUNT	0.00
		MISC. CHARGES	10.00
		TOTAL CHARGES	1029.99
		LESS INSURANCE	0.00
		SALES TAX	72.10
(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT	1102.09

CUSTOMER COPY




7168 Pearl Road · MIDDLEBURG HTS., OHIO 44130
 Phone (440) 884-7800
 www.northcoastnissan.com

N ROYALTON, OH

SERVICE ADVISOR **JAMES ORLOSKY**

REPAIR ORDER WRITTEN:	DATE READY	STOCK NO.	VEHICLE IDENTIFICATION	CUST. NO.	TAG NO.	P.O. NO.	INVOICE PRINTED	INVOICE NO.
02JAN09	02JAN09	7206	JN1CA21A5W				02JAN09	
TIME IN	TIME READY	YEAR	MAKE & MODEL	TELEPHONE NO.	CUST. PAY LABOR RATE	DELIVERY DATE	PREPARED BY	S/A
07:33	09:26	98	NISSAN MAXIMA		85.00	30JUL98	83	83
MILEAGE IN	MILEAGE OUT	LICENSE NO.						
82246	82246							

TECH	TYPE	HOURS	LIST/UNIT	NET/UNIT	TOTAL
A C/S AIR BAG LIGHT ON					
1100 RECOMMEND RIGHT SIDE AIR BAG MODULE					
CUSTOMER DECLINED AT THIS TIME					
79	CP	1.00		90.00	90.00
CHEMICALS & MATERIALS USED FOR REPAIRS					4.50



lock-move
 keys under vison

**** PRE-INVOICE ****

Please check our web site for product information and to schedule a service appointment.

You may receive a **Customer Satisfaction Survey** From Nissan. If, for any reason, you cannot Grade us "**Excellent**", please contact Mike McNeeley.

Thank You!

DESCRIPTION	TOTALS
LABOR AMOUNT	90.00
PARTS AMOUNT	0.00
GAS,OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	4.50
TOTAL CHARGES	94.50
LESS INSURANCE	0.00
SALES TAX	7.33
PLEASE PAY THIS AMOUNT	101.83

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.


I HEREBY ACKNOWLEDGE RECEIPT OF A COPY HEREOF.

X

RECOMMEND RIGHT SIDE AIR BAG MODULE \$709.00+TAX

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

(SIGNED) _____ DEALER GENERAL MANAGER OR AUTHORIZED PERSON DATE _____



Complaint Thomas Lambert Nissan Maxima 1998

Contact Information

- Name: Thomas Lambert
- Address:
14702 Kamputa Drive
Centreville, VA
USA

Problem Description


- Problem Description:
SECOND AIR BAG needs to be replaced. First airbag replaced in August. Car has not been in an accident - No reason for airbag failures. Nissan says that Driver Side Airbag assembly failed this time. Called corporate office again to see if they would cover any of the cost. Said they'd return call next day but we're still waiting. It has been 3 days.
- Interested in Class Action? no

Vehicle Information

- Make: Nissan
- Model: Maxima
- Year: 1998
- VIN: JN1CA21A9WT404325
- Transmission: automatic
- Vehicle involved in:

Failures and Repairs

Item Failed	Date of Failure	Mileage at Failure	Total Repair Cost	Amount Manufacturer Paid	Number of Repair Attempts
airbag	August 2004	78777	595	0	1



Complaint Jan Abeita Nissan Maxima 1998

Contact Information

- Name: Jan Abeita
- Address:
P.O. Box 961 135 Stakeout Dr.
Ranchos de Taos, NM
USA

Problem Description

- Problem Description:
SRS Light flashing on dash; dealer mechanic indicates failure of driver-side air bag module.

Driver-side mirror no longer defrosts and is loose in housing.


- Interested in Class Action? no

Vehicle Information

- Make: Nissan
- Model: Maxima
- Year: 1998
- VIN: JN1CA21A8WT404557
- Transmission: manual
- Vehicle involved in:

Failures and Repairs

Item Failed	Date of Failure	Mileage at Failure	Total Repair Cost	Amount Manufacturer Paid	Number of Repair Attempts
airbag	February 2004	52500	372	0	1
mirrors	September 2003	49500	0	0	1



Complaint E Friesen Nissan Maxima 1998

Contact Information

- Name: E Friesen
- Address:
15 Radley Bay
WPG, BC
CAN

Problem Description

- Problem Description:
This is the third time the airbag module has been replaced. The first two times were under warranty and were defects, now that I am at 110000 km I am told it is not a defect and I have to pay for it. This car has never been in an accident therefore how is it that the airbag modules keep having a problem?
- Interested in Class Action? no


Vehicle Information

- Make: Nissan
- Model: Maxima
- Year: 1998
- VIN: jn1ca21a2wt403100
- Transmission: automatic
- Vehicle involved in:

Failures and Repairs

Item Failed	Date of Failure	Mileage at Failure	Total Repair Cost	Amount Manufacturer Paid	Number of Repair Attempts
airbag	August 2003	110000	426	0	1

TSB# : NTB 00042 Side air bag system 140000
 NTB 00043 Frontal 141100
 NTB 08-055A Frontal
 NTB 08070 Air bag light flashing 8/15/98



Safety Ratings	Defects & Recalls	Safe Driving Information
----------------	-------------------	--------------------------

Office of Defects Investigation

DEFECTS & RECALLS

File a Complaint

SERVICE BULLETINS - SEARCH RESULTS

Navigate: ODI Home » Service Bulletins » Results List

Search Complaints

Defect Investigations

Search Results

Safety Recalls

Report Date : December 29, 2008 at 01:02 PM

Service Bulletins

Search Type : VEHICLE

Year : 1998

Downloads

Make : NISSAN

Model : MAXIMA

Foreign Campaigns

Results : 52 | All records displayed

Make : NISSAN

Model : MAXIMA

Year : 1998

EWR Information

Manufacturer : NISSAN NORTH AMERICA, INC.

Service Bulletin Number : NTB08-055A

Date of Bulletin : JL

Sitemap

NHTSA Item Number : 10025522

7/21/08

Component : AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE

Contact ODI

Summary :

(888) 327-4236

SRS PRECAUTIONS DURING SERVICE;IMPROPER MAINTENANCE, INCLUDING IN AND INSTALLATION OF THE SRS, CAN LEAD TO A SERIOUS INJURY OR DEATH CAUS UNINTENTIONAL ACTIVATION OF THE SRS ON ALL NISSAN MODELS WITH THE SRS :

TTY: (800) 424-9153

Check to Request Research. Submit below.

Make : NISSAN

Model : MAXIMA

Year : 1998

Manufacturer : NISSAN NORTH AMERICA, INC.

Service Bulletin Number : 99022

Date of Bulletin : OC

NHTSA Item Number : 10017473

Component : SEAT BELTS:FRONT

Summary :

FRONT SEAT BELT LATCH PLATE RETAINING BUTTON MISSING. *TT

Check to Request Research. Submit below.

NTB 08-040
 ABS sensor
 can't be checked
 using ON car
 BRAKE
 LIGHT

Make : NISSAN **Model :** MAXIMA **Year :** 1998
Manufacturer : NISSAN NORTH AMERICA, INC.
Service Bulletin Number : NTB99014A **Date of Bulletin :** JU
NHTSA Item Number : 613950
Component : POWER TRAIN:AUTOMATIC TRANSMISSION

Summary :
 SOME VEHICLES WITH AUTOMATIC TRANSMISSION MAY EXHIBIT A SITUATION V
 HANDLE IS HARD TO MOVE OR OPERATÉ. THIS PROBLEM MAY BE WORSE DURING I
 Check to Request Research. Submit below.

Make : NISSAN **Model :** MAXIMA **Year :** 1998
Manufacturer : NISSAN NORTH AMERICA, INC.
Service Bulletin Number : NTB99031B **Date of Bulletin :** MA
NHTSA Item Number : 613476
Component : SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS

Summary :
 SOME VEHICLE MAY EXHIBIT A GROAN OR HUMMING NOISE FROM THE REAR O
 AFTER RELEASING THE BRAKE PEDAL AND MOVING FORWARD SLOWLY AT APPROX
 MPH). *TT
 Check to Request Research. Submit below.

Make : NISSAN **Model :** MAXIMA **Year :** 1998
Manufacturer : NISSAN NORTH AMERICA, INC.
Service Bulletin Number : NTB99-036A **Date of Bulletin :** MA
NHTSA Item Number : 613480
Component : STRUCTURE:BODY:DOOR

Summary :
 INFORMATION REGARDING KEYLESS REMOTE ENTRY PROGRAMMING. *TT
 Check to Request Research. Submit below.

Make : NISSAN **Model :** MAXIMA **Year :** 1998
Manufacturer : NISSAN NORTH AMERICA, INC.
Service Bulletin Number : NTB00043 **Date of Bulletin :** MA
NHTSA Item Number : 613478
Component : AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE

Summary :
 SOME VEHICLES MAY EXHIBIT THE SRS LIGHT FLASHING, WITH SELF DIAGNOSI
 EITHER SIDE MODULE LH [OPEN] (CODE DA) OR SIDE MODULE RH [OPEN] (CODE 7A
 Check to Request Research. Submit below.

Make : NISSAN **Model :** MAXIMA **Year :** 1998

Manufacturer : NISSAN NORTH AMERICA, INC.

Service Bulletin Number : NTB98070A **Date of Bulletin :** SEI

NHTSA Item Number : 615219

Component : AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE

Summary :

SOME VEHICLES MAY EXHIBIT A SRS LIGHT FLASHING, AND SIDE MODULE LH / I
DA / 7A. *TT

Check to Request Research. Submit below.

Make : NISSAN **Model :** MAXIMA **Year :** 1998

Manufacturer : NISSAN NORTH AMERICA, INC.

Service Bulletin Number : NTB99067 **Date of Bulletin :** SE

NHTSA Item Number : 609965

Component : UNKNOWN OR OTHER

Summary :

NISSAN INTEGRATED HOMELINK TRANSMITTER SYSTEM USED TO ACTIVATE M
GARAGE DOORS AND SECURITY GATES. *TT

Check to Request Research. Submit below.

Make : NISSAN **Model :** MAXIMA **Year :** 1998

Manufacturer : NISSAN NORTH AMERICA, INC.

Service Bulletin Number : NTB98008B **Date of Bulletin :** SEI

NHTSA Item Number : 610036

Component : ELECTRICAL SYSTEM:WIRING:FRONT UNDERHOOD

Summary :

SUBJECT REGARDING EGI HARNESS WIRE BREAKAGE DIAGNOSIS AND REPAIR

Check to Request Research. Submit below.

Make : NISSAN **Model :** MAXIMA **Year :** 1998

Manufacturer : NISSAN NORTH AMERICA, INC.

Service Bulletin Number : NTB99022A **Date of Bulletin :** AU

NHTSA Item Number : 607626

Component : SEAT BELTS

Summary :

CONCERNS WITH THE FRONT SEAT BELT LATCH PLATE STOPPER BUTTON MIS

Check to Request Research. Submit below.

Make : NISSAN **Model :** MAXIMA **Year :** 1998

Manufacturer : NISSAN NORTH AMERICA, INC.

Service Bulletin Number : NTB99030A **Date of Bulletin :** JU

Component : STRUCTURE:BODY

Summary :

SERVICE PROCEDURES FOR CONSOLE LID REPAIR. *YC

Check to Request Research. Submit below.

Make : NISSAN

Model : MAXIMA

Year : 1998

Manufacturer : NISSAN NORTH AMERICA, INC.

Service Bulletin Number : NTB98070

Date of Bulletin : AUG

NHTSA Item Number : 609568

Component : AIR BAGS

Summary :

AIR BAG LIGHT FLASHING. YD

Check to Request Research. Submit below.

Make : NISSAN

Model : MAXIMA

Year : 1998

Manufacturer : NISSAN NORTH AMERICA, INC.

Service Bulletin Number : NTB98053

Date of Bulletin : JUL

NHTSA Item Number : 602097

Component : ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:EMISSION CONTROL

Summary :

CONDITION WITH (MIL) MALFUNCTION INDICATOR LAMP ON WITH REAR OXYGEN P0137 (MINIMUM VOLTAGE MONITORING) (REAR H02S) STORED IN THE ECM. *YC

Check to Request Research. Submit below.

Make : NISSAN

Model : MAXIMA

Year : 1998

Manufacturer : NISSAN NORTH AMERICA, INC.

Service Bulletin Number : NTB98050

Date of Bulletin : JUL

NHTSA Item Number : 601730

Component : ENGINE AND ENGINE COOLING:ENGINE:GASOLINE

Summary :

EXPERIENCING SPARK KNOCK DURING ENGINE START. *YC

Check to Request Research. Submit below.

Make : NISSAN

Model : MAXIMA

Year : 1998

Manufacturer : NISSAN NORTH AMERICA, INC.

Service Bulletin Number : NTB98054

Date of Bulletin : JUL

NHTSA Item Number : 601727

Component : STEERING:COLUMN LOCKING:ANTI-THEFT DEVICE

Summary :

INFORMATION REGARDING SECURITY SYSTEM FALSE ALARMS. *YC