

 DOT Auto Safety Hotline Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline		FOR AGENCY USE ONLY 100148 Date Received: 27-JAN-2009 Repository: ☐ Reference No.: 10256526	
OWNER INFORMATION (Type or Print) Name: [REDACTED] Address: [REDACTED] City: CAMARILLO State: CA Zip Code: [REDACTED] Daytime Telephone Number: [REDACTED] E-mail Address: [REDACTED] Signature of Owner: [REDACTED] Date: 2/3/2009			
Do you authorize NHTSA to contact the manufacturer of your vehicle? ☒ YES ☐ NO In the absence of a signature, please print the name and address of the vehicle manufacturer.			
VEHICLE INFORMATION 17 digit Vehicle Identification Number Located at bottom of windshield on driver's side: JTKDE167 [REDACTED] Make: TOYOTA Model: SCION TC Model Year: 2005/6220A Date Purchased: 12/29/2004 Dealer's Name and Telephone Number: Ventura Toyota 805/650-0510 Original Owner: ☒ Dealer's City: Ventura State: CA Zip Code: 93003 Engine: 2.4L No: Cylinders: 4 Fuel Type: unleaded DOHC, 16 valve VVT-i SFI gasoline Transmission Type: automatic Antilock Brakes: ☒ Powertrain: Multiple Failure: Incident Date(s): 3-27-07, 5-27-08, 9-16-08, 11-19-08 Cruise Control: ☒			
FAILED COMPONENT(S)/PART(S) INFORMATION Vehicle Component Codes: 140000 AIR BAGS, 150000 SEAT BELTS, 110000 ELECTRICAL SYSTEM Tire Pressure indicator monitor system Failure Mileage: 14,987 Failure Speed: 0			
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE Tire Make: Bridgestone Tire Model (Name or Number): Potenza RE-92 Tire Size (Example P215/65R15): P215/45ZR17 DOT No. (Example: DOTM19ABC036): ☒ Original Equipment ☐ Prior Repair Failure Location: front passenger sidewall Tire Component Code: Tire Failure type: Sidewall Blowout			
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE Make: Date Manufactured: Model No./Name: Seat Type: Installation System: Child Seat Component Code: Failed Part:			
APPLICABLE INCIDENT INFORMATION (Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).) Crash: ☐ Yes ☒ No Fire: ☐ Yes ☒ No Number of Persons Injured: 0 Number of Deaths: 0 Reported to Police: N			
Narrative Description of Incident(S), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available). TL*THE CONTACT OWNS A 2005 TOYOTA SCION TC. THE CONTACT STATED THAT THE SPEEDOMETER, SEAT BELTS, AND AIR BAG COVER HAVE FAILURES. THE SPEEDOMETER DOES NOT WORK WHEN THE VEHICLE IS IN MOTION. THE DRIVER'S SIDE SEAT BELT LATCH WAS NOT WORKING PROPERLY AND WAS REPAIRED. CURRENTLY, THE PASSENGER SIDE SEAT BELT IS EXPERIENCING DIFFICULTY DISCONNECTING FROM THE LATCH. THE DEALER STATED THAT THE E CLIP FAILED IN THE AIR BAG COVER. THE COVER WAS REPAIRED, WHICH ONLY LASTED A FEW MONTHS BEFORE FAILING AGAIN. THE VEHICLE HAS BEEN AT THE DEALER APPROXIMATELY FOUR TIMES FOR THESE FAILURES. THE FAILURE MILEAGE WAS 15 AND CURRENT MILEAGE WAS 38,000.			
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY			
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.			