



DOT Auto Safety Hotline

U.S. Department of Transportation National Highway Traffic Safety Administration

Vehicle Owner's Questionnaire To Report Vehicle Safety Defects

FOR AGENCY USE ONLY 100148

Date Received 19-MAR-2009

Repository Reference No. 10262459

2009 APR -1 PM 2:53

1-888-DASH-2-DOT (1-888-327-4236) INTERNET:www.nhtsa.dot.gov/hotline

OWNER INFORMATION (Type or Print)

Name Address City TUCSON State AZ Zip Code

Daytime Telephone Number Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES NO Signature of Owner Date

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side Make HYUNDAI Model TIBURON Model Year 2003 Date Purchased 3/1/08 Dealer's Name and Telephone Number Pvt - Owner / Jim Clark Hyundai Engine: No: Cylinders 6 Fuel Type: Gas Original Owner Dealer's City Tucson State AZ Zip Code Transmission Type Antilock Brakes Powertrain Multiple Failure: Incident Date(s) 14-MAR-2009

FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Codes: 150000 SEAT BELTS; 140000 AIR BAGS Failure Mileage 65000 Failure Speed 0

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make Tire Model (Name or Number) Tire Size (Example P215/65R15) DOT No. (Example: DOTM19ABC036) Original Equipment Prior Repair Failure Location: Tire Component Code Tire Failure Type:

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: Date Manufactured: Model No./Name: Seat Type: Installation System: Child Seat Component Code: Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury (ies).)

Crash Fire Number of Persons Injured Number of Deaths Reported to Police Yes No Yes No 0 0 N

Narrative Description of Incident(S), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e, parts repaired or replaced (and if old part is available).

TL\*THE CONTACT OWNS A 2003 HYUNDAI TIBURON. THE CONTACT STATED THAT THE AIR BAG WARNING INDICATOR REMAINS ILLUMINATED IN THE VEHICLE. HE TOOK HIS VEHICLE TO THE DEALER AND WAS INFORMED THAT THE DRIVER'S SEAT BELT BUCKLE WIRING CAUSED THE AIR BAG WIRING LAMP TO ILLUMINATE, THE FAILURE COULD ALSO CAUSE THE AIR BAG FUSE TO OPEN AND PREVENT AIR BAG DEPLOYMENT. THE VEHICLE WAS NOT INCLUDED IN NHTSA CAMPAIGN ID NUMBER 02V29000 (COMPONENT: SEAT BELTS:FRONT:BUCKLE ASSEMBLY). THE CONTACT WOULD HAVE TO PAY \$300 FOR THE REPAIR. THE MANUFACTURER AGREED WITH THE DEALER. THE CONTACT STATED THAT HE JUST PURCHASED THE VEHICLE FIVE DAYS PRIOR TO THE FAILURE. THE FAILURE MILEAGE WAS 65,000.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.