



DOT Auto Safety Hotline

FOR AGENCY USE ONLY 100148

U.S. Department of Transportation National Highway Traffic Safety Administration

Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline

Date Received 30-MAR-2009 Repository Reference No. 10263601

OWNER INFORMATION (Type or Print)

Name Address City PLEASANT LAKE State IN Zip Code

Daytime Telephone Number Evening Telephone Number E-mail Address

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES NO Signature of Owner Date 4/7/09

VEHICLE INFORMATION

17 digit Vehicle Identification Number 1GN0M19W2WB Make CHEVROLET Model ASTRO Model year 1998 Date Purchased 6-2-99 Dealer's Name PRIVATE Engine: No: Cylinders 6 Fuel Type: Gas State IN Zip Code 46703 Incident Date(s) 20-OCT-1998

FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Codes: 180000 VEHICLE SPEED CONTROL, 031000 SERVICE BRAKES, HYDRAULIC: PEDALS AND LINKAGES Failure Mileage 114000 Failure Speed 0

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make Tire Model (Name or Number) Tire Size (Example P215/65R15) DOT No. (Example: DOTM9ABC036) Original Equipment Prior Repair Failure Location: Tire Component Code Tire Failure Type:

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: Date Manufactured: Model No./Name: Seat Type: Installation System: Child Seat Component Code: Failed Part:

APPLICABLE INCIDENT INFORMATION

Crash Yes No Fire Yes No Number of Persons Injured 0 Number of Deaths 0 Reported to Police N

Narrative Description of Incident(S), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e, parts repaired or replaced (and if old part is available).

TL\*THE CONTACT OWNS A 1998 CHEVROLET ASTRO. THE CONTACT STATED THAT THERE WAS NOT ENOUGH SPACE BETWEEN THE BRAKE PEDAL AND THE MOTOR COVER FOR HIM TO MANEUVER HIS FEET. HE WAS CONCERNED THAT HE COULD POSSIBLY GET HIS FOOT CAUGHT BETWEEN THE BRAKE PEDAL AND MOTOR COVER IN THE EVENT THAT HE NEEDED TO APPLY THE BRAKES QUICKLY. THE VIN WAS UNKNOWN. THE FAILURE AND CURRENT MILEAGES WERE LESS THAN 114,000.

There is 5" between Brake pedal and motor cover My shoe is 4 3/4" wide, this is the way it came to me that is where Gas Pedal is located

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.