



U.S. Department  
of Transportation  
National Highway  
Traffic Safety  
Administration

DOT Auto Safety Hotline  
**Vehicle Owner's Questionnaire**  
To Report Vehicle Safety Defects  
1-888-DASH-2-DOT  
(1-888-327-4236)  
INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

19-MAY-2009

Repository Reference No.  
10269403

## OWNER INFORMATION (Type or Print)

Name [REDACTED]

Address [REDACTED]

City DENVILLE

State NJ

Zip Code [REDACTED]

Daytime Telephone Number  
[REDACTED]E-mail Address  
[REDACTED]Evening Telephone Number  
[REDACTED]

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle?  YES  NO  
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner \_\_\_\_\_ Date \_\_\_\_/\_\_\_\_/\_\_\_\_

## VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side

WB10509079Z [REDACTED]

Make

BMW

Model

K 1300 S

Model Year

2009

Date Purchased

Dealer's Name and Telephone Number

Engine:

No: Cylinders

Fuel Type:

Original Owner

Dealer's City

State

Zip Code

Transmission Type

 Antilock Brakes

Powertrain

Multiple Failure:

Incident Date(s)

11-MAY-2009

 Cruise Control

## FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Code: 061000 ENGINE AND ENGINE COOLING: ENGINE

Failure Mileage  
580Failure Speed  
0

## ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM9ABC036)

 Original Equipment  
 Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type:

## ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

## APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash

 Yes  No

Fire

 Yes  No

Number of Persons Injured

0

Number of Deaths

0

Reported to Police

N

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

TL\*THE CONTACT OWNS A 2009 BMW K1300S MOTORCYCLE. THE CONTACT STATED THAT THE ENGINE SHUTS OFF WHEN COASTING OR DOWNSHIFTING TO A STOP. THE FAILURE OCCURS WHENEVER HE ATTEMPTS TO STOP HIS VEHICLE AT A STOP LIGHT. IN ADDITION, THE PASSENGER SIDE SIGNAL SWITCH WAS NOT WORKING. THE DEALER DID NOT HAVE THE NECESSARY PARTS BECAUSE THE VEHICLE WAS NEW AND THEY COULD NOT DETERMINE WHY THE ENGINE WAS STALLING. THE FAILURE MILEAGE WAS 580. UPDATED 05/21/09 \*BF

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.



U.S. Department  
of Transportation

**National Highway  
Traffic Safety  
Administration**

**DOT Auto Safety Hotline**  
**Vehicle Owner's Questionnaire**  
**To Report Vehicle Safety Defects**  
**1-888-DASH-2-DOT**  
**(1-888-327-4236)**  
**INTERNET:www.nhtsa.dot.gov/hotline**

FOR AGENCY USE ONLY 100148

Date Received

19-MAY-2009

Repository

Reference No.  
10269403

**OWNER INFORMATION (Type or Print)**

Name

Address

City

DENVILLE

State

NJ

Zip Code

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle?  YES  NO  
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner \_\_\_\_\_ Date \_\_\_\_/\_\_\_\_/\_\_\_\_

**VEHICLE INFORMATION**

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side

WB10509079Z

Make

BMW

Model

K 1300S

Model Year

2009

Date Purchased

Dealer's Name and Telephone Number

Engine:

No: Cylinders

Fuel Type:

Original Owner

Dealer's City

State

Zip Code

Transmission Type

Antilock Brakes

Powertrain

Multiple Failure:

Incident Date(s)

11-MAY-2009

Cruise Control

**FAILED COMPONENT(S)/PART(S) INFORMATION**

Vehicle Component Code: 061000 ENGINE AND ENGINE COOLING: ENGINE

Failure Mileage

580

Failure Speed

0

**ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE**

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM9ABC036)

Original Equipment  
 Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type:

**ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE**

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

**APPLICABLE INCIDENT INFORMATION**

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash

Yes  No

Fire

Yes  No

Number of Persons Injured

0

Number of Deaths

0

Reported to Police

N

**Narrative Description of Incident(S), Crash(es), and Injury(ies).**

**Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).**

TL\*THE CONTACT OWNS A 2009 BMW K1300S MOTORCYCLE (NA). THE CONTACT STATED THAT THE ENGINE SHUTS OFF WHEN COASTING OR DOWNSHIFTING TO A STOP. THE FAILURE OCCURS WHENEVER HE ATTEMPTS TO STOP HIS VEHICLE AT A STOP LIGHT. IN ADDITION, THE PASSENGER SIDE SIGNAL SWITCH WAS NOT WORKING. THE DEALER DID NOT HAVE THE NECESSARY PARTS BECAUSE THE VEHICLE WAS NEW AND THEY COULD NOT DETERMINE WHY THE ENGINE WAS STALLING. THE FAILURE MILEAGE WAS 580.

Correction from above: Vehicle occasionally stalls when coming to a stop.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.