



U.S. Department of Transportation

National Highway Traffic Safety Administration

2009 Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received 27-MAY-2009

Repository Reference No. 10270054

OWNER INFORMATION (Type or Print)

Name, Address, City (BERLIN), State (NJ), Zip Code

Daytime Telephone Number, Evening Telephone Number, E-mail Address

Do you authorize... Signature of Owner, Date 6/2/09

VEHICLE INFORMATION

17 digit Vehicle Identification Number 1HGCD5636TA, Make HONDA, Model ACCORD LX, Model Year 1996

Date Purchased, Dealer's Name and Telephone Number, Engine: No: Cylinders, Fuel Type, Original Owner, Dealer's City, State, Zip Code

Transmission Type, Antilock Brakes, Cruise Control, Powertrain, Multiple Failure, Incident Date(s) 20-MAY-2009

FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Code: 110000 ELECTRICAL SYSTEM, Failure Mileage 205759, Failure Speed 0

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make, Tire Model, Tire Size, DOT No., Original Equipment, Prior Repair, Failure Location, Tire Component Code, Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make, Date Manufactured, Model No./Name, Seat Type, Installation System, Child Seat Component Code, Failed Part

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury (ies).)

Crash Yes No, Fire Yes No, Number of Persons Injured 0, Number of Deaths 0, Reported to Police N

Narrative Description of Incident(s), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure;

TL\*THE CONTACT OWNS A 1996 HONDA ACCORD. THE VEHICLE HAS AN IGNITION SWITCH ISSUE. ONCE THE KEY IS RELEASED FROM THE IGNITION, THE VEHICLE STALLS. THE FAILURE OCCURRED AT A STORE ONCE AND THE VEHICLE COULD NOT BE STARTED. THE MECHANIC INITIALLY THOUGHT THERE WAS A LOOSE CONNECTION ON THE BATTERY, BUT HE LATER DISCOVERED THAT IT WAS A SWITCH ISSUE. THE SWITCH WAS REPLACED. THE CONTACT STATED THAT THE 1997 ACCORDS ARE UNDER RECALL FOR THIS SAME FAILURE, BUT NOT THE 1996 ACCORDS. THE CURRENT AND FAILURE MILEAGES WERE 185000, 205759.

NOTE: IGNITION SWITCH # SV4-2 SENT WITH THIS FORM FOR EVALUATION, TAGGED: REF# 10270054

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY.

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.



# Read's Auto & Truck Repair, LLC

329 Williamstown Road • Berlin, NJ 08009  
 ☎ 753-6900 • ☎ 753-6901 fax

6103

QTY.	PART NO. AND DESCRIPTION	PRICE
1	Ign Switch	41.00
2	Brookhead Bolts	4.00

NAME	CUSTOMER'S ORDER NO.	DATE
[REDACTED]		5-22-09
A	ORDER WRITTEN BY	PROMISED
[REDACTED]		A.M. P.M.
CITY, STATE		ODOMETER IN
Berlin NJ		90514
HOME PHONE	BUS. PHONE	LICENSE NUMBER
YEAR, MAKE AND MODEL	SERIAL NUMBER	MOTOR NUMBER
96 Honda Accord.		
		TERMS

DESCRIPTION OF WORK	AMOUNT
<input type="checkbox"/> LUBE <input type="checkbox"/> CHANGE OIL <input type="checkbox"/> OIL FILTER <input type="checkbox"/> TUNE-UP <input type="checkbox"/> TRANS. <input type="checkbox"/> DIFF.	
Checked no start. Removed and replaced Bad ign. Switch	105.00

MAY BE CONTINUED ON OTHER SIDE)

TOTAL PARTS	45.00
ACCESSORIES	
TOTAL ACCESSORIES	

*Paid Cash.*

_____ LITERS/GALS. OF GAS @	TOTAL LABOR	105.00
_____ LITERS/QTS. OF OIL @	TOTAL PARTS	45.00
_____ kg/LBS. OF GREASE @	ACCESSORIES	
	GAS, OIL AND GREASE	
	SUBLET REPAIRS	
	EPA / WASTE DISPOSAL	150.00
	TAX	10.50
	TOTAL	160.50
	THANK YOU	

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

SAVE OLD PARTS?  YES  NO



NHTSA Campaign ID # 03V 423000



- Safety Ratings
- Defects & Recalls
- Safe Driving Information
- Resources

Office of Defects Investigation (ODI)

# DEFECTS & RECALLS

Safety Complaints ?

## RECALLS - SEARCH RESULTS

856 983 0600

File a Complaint  
online or by phone

Navigate: ODI Home » Recalls » Search » Results List

Search Complaints

Help

Defect Investigations

**Search Results**

Report Date: May 25, 2009 at 10:57 AM New Search

Search Type: VEHICLE

Make: HONDA

Model: ACCORD Print Version

Model Year: 1997

Results : 1 | All records displayed

Make: HONDA	Model: ACCORD
Model Year: 1997	Mfr's Report Date: MAY 13, 2002
Manufacturer: AMERICAN HONDA MOTOR CO.	NHTSA Action Number: N/A
NHTSA CAMPAIGN ID Number: 02V120000	
Component: ELECTRICAL SYSTEM:IGNITION:SWITCH	
Potential Number of Units Affected: 1000000	

Document Search

Check to Request Research. Submit below. Get Summary

Request Research

Safety Recalls

Service Bulletins

Downloads

Foreign Campaigns

EWR Information

Sitemap

Contact ODI

(888) 327-4236

TTY: (800) 424-9153



111

RSS | Web Policies & Notices | Terms of Use | FOIA | Privacy Policy | Cookie Policy | Accessibility | E-mail NHTSA

Des/200  
10/95  
make

VIN  
1HGCD5636TA [REDACTED]

NHTSA #  
Case #  
10270054

10/95  
OR 1996

Honda Accord Lx

# RECALLS SUMMARY

Vehicle Make / Model:	Model Year(s):
ACURA / CL	1997-1999
ACURA / TL	1999
HONDA / ACCORD	1997-1999
HONDA / CIVIC	1998-2000
HONDA / CR-V	1997-1999
HONDA / ODYSSEY	1997-1999
HONDA / PRELUDE	1997-1999
ISUZU / OASIS	1998-1999

**NHTSA CAMPAIGN ID Number:** 02V120000

**Summary:**

ON CERTAIN SEDANS, COUPES, HATCHBACKS, AND SPORT UTILITY VEHICLES, ELECTRICAL CONTACTS IN THE IGNITION SWITCH CAN DEGRADE DUE TO THE HIGH ELECTRICAL CURRENT PASSING THROUGH THE SWITCH WHEN THE VEHICLE IS STARTED.

**Consequence:**

WORN CONTACTS COULD CAUSE THE ENGINE TO STALL WITHOUT WARNING, INCREASING THE RISK OF A CRASH.

**Remedy:**

DEALERS WILL REPLACE THE IGNITION SWITCH. OWNER NOTIFICATION BEGAN JUNE 14, 2002. OWNERS WHO TAKE THEIR VEHICLES TO AN AUTHORIZED DEALER ON AN AGREED UPON SERVICE DATE AND DO NOT RECEIVE THE FREE REMEDY WITHIN A REASONABLE TIME SHOULD CONTACT HONDA AT 1-800-999-1009 OR ACURA AT 1-800-382-2238.

**Notes:**

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S AUTO SAFETY HOTLINE AT 1-888-DASH-2-DOT (1-888-327-4236).

Close Window

*Callow Honda  
may 26 @ 2:45*

*By Honda -  
CASE # -  
NA32019-15-264  
1255*

*Also Callow  
NHTSA  
NHTSA #  
10270054*