



OCT 20 2009

DOT Auto Safety Hotline

U.S. Department of Transportation

Vehicle Owner's Questionnaire

To Report Vehicle Safety Defects

1-888-DASH-2-DOT

(1-888-327-4236)

INTERNET: www.nhtsa.dot.gov/hotline

National Highway Traffic Safety Administration

FOR AGENCY USE ONLY 100148

Date Received

14-AUG-2009

Repository

Reference No.
10280450

OWNER INFORMATION (Type or Print)

Name

Address

City

PARKER

State

CO

Zip Code

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Same

The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side

1HGCG5643WA

Make

HONDA

Model

ACCORD

Model Year

1998

Date Purchased

08-10-98

Dealer's Name and Telephone Number

Empire Honda

Engine:

No: Cylinders

4

Fuel Type:

gas

Original Owner

Dealer's City

Denver

State

CO

Zip Code

Transmission Type

Auto

Antilock Brakes

Cruise Control

Powertrain

Multiple Failure:

yes

Incident Date(s)

18-MAY-2009

FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Code: 061000 ENGINE AND ENGINE COOLING; ENGINE

Failure Mileage
124000

Failure Speed
100 to 55 mph

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM19ABC036)

Original Equipment
 Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type:

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash

Yes No

Fire

Yes No

Number of Persons Injured

0

Number of Deaths

0

Reported to Police

N

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

TL*THE CONTACT OWNS A 1998 HONDA ACCORD. WHILE DRIVING AT ANY SPEED, THE VEHICLE SUDDENLY SHUTS OFF. THE VEHICLE IS ABLE TO IMMEDIATELY RESTART AFTER THE FAILURE OCCURS. THE DEALER COULD NOT DUPLICATE THE FAILURE. THE CURRENT AND FAILURE MILEAGES WERE 124,000.

Failure has occurred a repeated number of times between 124,000 + 133,000 miles at any speed. One time the engine shut off and restarted itself. The main relay has been replaced but that did not fix the problem.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Parker Imports
 6250 E. Pinelane #B
 Parker, CO. 80138
 Phone - 303-840-9355

INVOICE

13882

Org. Est. # 028562

YOU WORK HARD FOR YOUR MONEY AND SO DO WE!

INVOICE

Work Completed Date : 07/14/2009

Print Date : 07/14/2009



PARKER, CO
 Home
 Cust ID : 1470

Ref # :

1998 Honda - Accord LX
 2.3L, In-Line4, VIN (CG5), AUTO
 Lic # :
 Unit # :
 Vin # : 1HGCG5643WA
 Hat # :

Odometer In : 124253
 Odometer Out :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
Fuel Injection Relay OEM 39400-S84-003	1.00	58.67	58.67	PULL CODES FOR CK ENGINE LIGHT, CHECK OUT TIME, CODE 67-1 CAT DETERIATION	92.75
Shop Supplies		5.48	5.48		
				WILL BE GOING ABOUT 45 MPH CAR DIES BUT WILL RESTART REPL MAIN RELAY	N/C 46.38
				Discount \$15.00 off parts	

[Technicians : COLLINS, JARROD; Please Select, Technician; KRAMER,
 RICHARD]

Org. Estimate \$207.03	Revisions \$0.00	Current Estimate \$ 207.03	Additional Cost	Revised Estimate	Labor: 139.13
					Parts: 64.15
					Sublet: 0.00
					Discount: -15.00
					Sub: 188.28
					Tax: 2.51
					Total: 190.79
					Bal Due: \$190.79

[Payments -]

I the undersigned acknowledge receipt of the vehicle, services, and parts/repairs here on. All parts and labor are guaranteed for 6 months or 6,000 miles, whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Should collection be required to fulfill this obligation I agree to pay all reasonable collection and/or attorney fees, with or without suit. In addition I agree to pay 1 3/4% per month interest/service charge (an annual rate of 21%) beginning with the date of this invoice

SIGNATURE..... Date..... Time.....