

 DOT Auto Safety Hotline Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline				FOR AGENCY USE ONLY 100148	
				Date Received 30-AUG-2010	Repository ☐ Reference No. 10352839
OWNER INFORMATION (Type or Print)					
Name [REDACTED]		Daytime Telephone Number [REDACTED]		E-mail Address [REDACTED]	
Address [REDACTED]		Evening Telephone Number			
City COLUMBIA	State MO	Zip Code [REDACTED]			
<i>The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).</i>					
VEHICLE INFORMATION					
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side 1N4AL11D23 [REDACTED]			Make NISSAN	Model ALTIMA	Model Year 2003
Date Purchased	Dealer's Name and Telephone Number			Engine: No: Cylinders	Fuel Type:
Original Owner ☐	Dealer's City	State	Zip Code		
Transmission Type	☐ Antilock Brakes ☐ Cruise Control	Powertrain	Multiple Failure:	Incident Date(s) 03-JUL-2010	
FAILED COMPONENT(S)/PART(S) INFORMATION					
Vehicle Component Code: 060000 ENGINE AND ENGINE COOLING				Failure Mileage 123000	Failure Speed 30
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE					
Tire Make	Tire Model (Name or Number)		Tire Size (Example P215/65R15)		
DOT No. (Example: DOTM9ABC036)	☐ Original Equipment ☐ Prior Repair	Failure Location:			
Tire Component Code			Tire Failure Type:		
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE					
Make:	Date Manufactured:	Model No./Name:			
Seat Type:	Installation System:				
Child Seat Component Code:	Failed Part:				
APPLICABLE INCIDENT INFORMATION					
<i>(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)</i>					
Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Deaths	Reported to Police N	
Narrative Description of Incident(S), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).					
TL*THE CONTACT OWNS A 2003 NISSAN ALTIMA. THE CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 30 MPH, SHE NOTICED THAT THE VEHICLE STARTED LOSING POWER. SHE DROVE THE VEHICLE TO A REPAIR SHOP WHERE SHE WAS INFORMED THAT THE CATALYTIC CONVERTER WAS REPLACED. A FEW DAYS LATER, THE MECHANIC NOTICED THAT THE VEHICLE WAS BECOMING LOW ON OIL. THE CONTACT FILLED THE FUEL TANK AND NOTICED THAT THERE WAS VERY LITTLE OIL LEFT. THE VEHICLE WAS TAKEN TO AN AUTHORIZED DEALERSHIP WHERE THE CONTACT WAS TOLD THAT SHE NEEDED A NEW ENGINE AND THE PROBLEM WAS WIDESPREAD WITH THE CATALYTIC CONVERTER. THE CONTACT CALLED THE MANUFACTURER WHO ADVISED HER TO TAKE THE VEHICLE IN FOR A DIAGNOSTIC FEE BEFORE THEY COULD ESCALATE HER CASE TO A REGIONAL SPECIALIST. THE CONTACT TOOK THE VEHICLE INTO THE DEALERSHIP WHERE IT WAS CONFIRMED THAT SHE NEEDED A NEW ENGINE; THE MANUFACTURER STATED THAT THERE WAS NOTHING THEY COULD DO TO ASSIST. THE VEHICLE HAD NOT BEEN REPAIRED AT THE TIME OF THE COMPLAINT. THE CONTACT BELIEVED THE FAILURE TO BE RELATED TO RECALL 03V084000 (ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:MANIFOLD/HEADER/MUFFLER/TAIL PIPE) BUT THE MANUFACTURER REFUSED TO REPAIR IT SINCE THE MILEAGE WAS TOO HIGH. THE CURRENT MILEAGE WAS APPROXIMATELY 124,000. THE FAILURE MILEAGE WAS APPROXIMATELY 123,000.					
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.			ATTACH ADDITIONAL SHEETS IF NECESSARY		
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.					

S E R V I C E - C O M M

09/03/10 11:34:35

CICSWB08

FIVE YEARS CLAIM HISTORY

WARRANTY CLAIM DATA

VIN: 1N4AL11D23C [REDACTED]

RO DATE: 10/15/03 RO NBR: *010802 SERVICING DEALER: PERRY NISSAN, INC.

MILEAGE: 24,422

COLUMBIA

MO 65203

PNC: R3007 '02-'03 L31 QR25 ENGINE CAMP

SUBLET: 0.00

OPERATIONS: R30071 LABOR OP #1

PARTS REPLACED:

152089E000	FILTER OIL
206958J010	BEARING-SEAL, EXHAUST JOINT
A65908J026	COVER - EXHAUST MANIFOLD KIT
LOCALENOIL	ENOIL DESCRIPTION

ENTER = CONTINUE N = NEXT VEHICLE M = RETURN TO SERVICE-COMM MENU>



Joe Machens Nissan

201 Nebraska Ave. • Columbia, MO 65203
Phone 573-443-1660 Toll Free 877-305-1660

CUSTOMER NO. 12746	ADVISOR CASEY	329	TAG NO. 2162	INVOICE DATE 08/23/10	INVOICE NO. NICS107972
	LABOR RATE	LICENSE NO.	MILEAGE 124,288	COLOR /	STOCK NO.
	YEAR / MAKE / MODEL 03/NISSAN/ALTIMA/			DELIVERY DATE	DELIVERY MILES
COLUMBIA, MO	VEHICLE I.D. NO. 1 N 4 A L 1 1 D 2 3 C			SELLING DEALER NO.	PRODUCTION DATE
	F.T.E. NO.		P.O. NO.	R.O. DATE 08/23/10	REPRINT# 1
RESIDENCE PHONE	BUSINESS PHONE		COMMENTS		

MO: 124288

JOB# 1 CHARGES-----

LABOR-----

J# 1 10NIZ DRIVEABILITY HOURS: 0.50 TECH(S):325 48.50

CUST STS HAD EXHAUST WORK DONE, NOW VEHICLE IS USING OIL.

COMPLETED DIAG AS PER OLD TSB, COMPLETED CRANKCASE

PRESSURE TEST, 58KPA LESS THAN 90 SECONDS

NEEDS ENGINE, OIL CONSUMPTION VERIFIED AND OIL LOW

JOB# 1 TOTALS-----

LABOR 48.50

JOB# 1 JOURNAL PREFIX NICS JOB# 1 TOTAL 48.50

MISC-----CODE-----DESCRIPTION-----CONTROL NO-----

JOB # A HW HAZARDOUS WASTE DISPOSAL 1.50

JOB # A SS SHOP SUPPLIES 3.40

TOTAL - MISC 4.90

TOTALS-----

TOTAL LABOR.... 48.50

TOTAL PARTS.... 0.00

TOTAL SUBLET... 0.00

TOTAL G.O.G.... 0.00

TOTAL MISC CHG. 4.90

TOTAL MISC DISC 0.00

TOTAL TAX..... 0.36

TOTAL INVOICE \$ 53.76

CUSTOMER SIGNATURE

The Automotive Garage of Columbia, LLC

2308 Industrial Dr
Columbia, MO. 65202
Phone - 573-446-2047 Fax - 573-446-2049

INVOICE

170

Org. Est. # 000794

INVOICE

Work Completed Date : 07/23/2010

Print Date : 07/23/2010

[REDACTED]
Columbia, MO [REDACTED]
Cell [REDACTED]
Cust ID : 2249

Ref # :

2003 Nissan - Altima S

2.5L, In-Line4, VIN (A)

Lic # : [REDACTED]

Odometer In : 123359

Unit # :

Odometer Out :

Vin # : 1N4AL11D23C [REDACTED]

Hat # :

Part Description	Qty	Sale	Extended	Labor Description	Extended
Exhaust Manifold and converter assembly	1.00	619.97	619.97	Diagnostic Check out of vehicle	76.00
Intermediate pipe with flex pipe and converter assembly	1.00	375.00	375.00	Perform engine compression test (regularly \$60.80)	N/C
Exhaust manifold gasket	1.00	22.00	22.00	Visual/Physical check out of vehicle condition (regularly \$76)	N/C
Pipe flange gasket (donut)	1.00	12.10	12.10	Exhaust manifold/converter assembly - Remove/Renew (includes replacing gaskets, bolts, and springs as needed)	190.00
Pipe flange gasket	1.00	12.10	12.10	Intermediate pipe with flex pipe and converter assembly - Remove/Renew (includes replacing gaskets, bolts, and springs as needed)	152.00
PCV Valve	1.00	27.40	27.40	O2 Sensor - Upstream - Renew	45.60
Bolt (exhaust manifold to intermediate pipe)	2.00	7.16	14.32	O2 Sensor - Downstream - Renew	45.60
Springs	2.00	6.80	13.60	PCV Valve - Renew	38.00
Bolts	2.00	10.90	21.80	Spark Plugs - Renew	45.60
Shop Supplies/Sealer	1.00	20.00	20.00	Ignition Boots - Renew	30.40
O2 Sensor - Upstream	1.00	192.44	192.44	Lube, oil, and filter	9.50
O2 Sensor - Downstream	1.00	202.99	202.99	Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection. Road test vehicle.	
PCV Valve	1.00	22.00	22.00	Service Request/Customer States: Check transmission, Prolonged shift points, check noise, check oil light, check noise when turning to left or right.	
Spark Plugs	4.00	16.50	66.00		
Ignition Boots	4.00	24.44	97.76	Diagnostic/Check-Out: Visual/physical check of transmission. Check engine oil level. Test drive	
Up To 5qt Standard Motor Oil	1.00	14.99	14.99		
Standard Oil Filter	1.00	5.50	5.50		

The Automotive Garage of Columbia, LLC

2308 Industrial Dr
Columbia, MO. 65202
Phone - 573-446-2047 Fax - 573-446-2049

INVOICE

170

Org. Est. # 000794

INVOICE

Work Completed Date : 07/23/2010

Print Date : 07/23/2010

2003 Nissan - Altima S

2.5L, In-Line4, VIN (A)

Lic # :

Odometer In : 123359

Unit # :

Odometer Out :

Vin # : 1N4AL11D23C

Hat # :

Columbia, MO

Cell

Cust ID : 2249

Ref # :

Part Description	Qty	Sale	Extended	Labor Description	Extended
				vehicle. Performance engine testing. Test exhaust system back pressure (6psi and above on acceleration. Normal 1.5psi). Engine compression test (75psi at first gauge reading. 150-160psi final gauge reading. Compression test normal.)	
				Pre-Service Findings: Restriction in exhaust system (catalytic converters primary and secondary have damage).O2 sensors faulty (damaged from excessive back pressure and heat). Spark plug damage from excessive back pressure and heat. PCV system damaged from excessive back pressure and heat.	
				Services Performed: Renew exhaust manifold including primary catalytic converter. Renew intermediate pipe including secondary catalytic converter. Renew gaskets, bolts, and mounting hardware. Renew O2 sensors (primary and secondary). Renew spark plugs, plug boots, and PCV valve. Lube, oil, and filter service. Retest backpressure and engine performance. Visual/Physical check over of vehicle condition.	
				Post-Service Findings: Customer to drive and advise of any performance problems noted.	

The Automotive Garage of Columbia, LLC

2308 Industrial Dr
Columbia, MO. 65202
Phone - 573-446-2047 Fax - 573-446-2049

INVOICE

170

Org. Est. # 000794

INVOICE

Work Completed Date : 07/23/2010

Print Date : 07/23/2010

2003 Nissan - Altima S

2.5L, In-Line4, VIN (A)

Lic #

Unit #

Vin # : 1N4AL11D23C

Hat # :

Odometer In : 123359

Odometer Out :

Columbia, MO

Cell

Cust ID : 2249

Ref # :

Part Description	Qty	Sale	Extended	Labor Description	Extended
------------------	-----	------	----------	-------------------	----------

[Technicians : Dodson, Brent]

Org. Estimate	Revisions	Current Estimate	Additional Cost	Revised Estimate
---------------	-----------	------------------	-----------------	------------------

07/22/2010 - 8:53 <none>
Parts: \$1712.57 Labor: \$632.70 Sublet: \$0.00 Taxes & Fees: \$125.87

\$2,471.14	\$2,471.14
------------	------------

Labor:	632.70
Parts:	1,739.97
Sublet:	0.00

Sub:	2,372.67
Tax:	127.89
Total:	2,500.56
Bal Due:	\$2,500.56

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....