

**Subject:** FW: 2010 dodge 3500  
**Date:** Thursday, February 24, 2011 10:07:01 AM

---

---

**From:** Mattson, Ryan CTR (NHTSA) **On Behalf Of** DataQuality, DataQuality (NHTSA)  
**Sent:** Thursday, February 24, 2011 9:21 AM  
**To:** Wells, Cynthia CTR (NHTSA)  
**Subject:** FW: 2010 dodge 3500

---

**From:** [REDACTED]  
**Sent:** Wednesday, February 23, 2011 8:51 PM  
**To:** DataQuality, DataQuality (NHTSA)  
**Subject:** 2010 dodge 3500

This is the third pump they either installer or worked on. The tech told my wife that they had to replace the whole power steering unit because it was the wrong one for this truck. I am still having problems with it at 20,000 miles

THE CARPET IS ALSO BULGING OUT OVER THE THROTTLE SOMETIMES  
MAKING IT HARD TO GET MY FOOT OFF THE THROTTLE. I think these trucks need to be checked out thank you for your time [REDACTED] [REDACTED]