

**OHIO
PUBLIC
SAFETY**
EDUCATION • SERVICE • PROTECTION

TIME OF CRASH				DAY OF WEEK			CITY*	VILLAGE*	TWP*	NAME (OF CITY, VILLAGE OR TOWNSHIP)*	COUNTY**	LATITUDE	LONGITUDE
0	4	1	0	F	R	I			X	Sandusky	7 2	41:24:14.00	83:07:23.00

OccupantHSY7001

TOP COPY - OOPS BOTTOM COPY - AGENCY

Narrative

Unit 1 was driving eastbound on the Ohio Turnpike in the middle lane when his truck caught fire from underneath the front hood near engine. Unit 1 then drove to the south side of the shoulder where he put the fire out.

MANNER OF COLLISION OR IMPACT

1

1 NOT COLLISION BETWEEN TWO VEHICLES IN TRANSPORT
2 REAR-END
3 HEAD-ON
4 REAR-TO-REAR
5 BACKING
6 AND LE
7 SIDESWIP, SAME DIRECTION
8 SIDESWIP, OPPOSITE DIRECTION
9 UNKNOWN

WEATHER

0 1

01 CLEAR
02 CLOUDY
03 FOG, SMOG, SMOKE
04 RAIN
05 SLEET, HAIL (FREEZING RAIN DRIZZLE)
06 SNOW
07 SEVERE CROSSWINDS
08 BLOWING SAND, SOIL, DIRT, SNOW
09 OTHER
10 UNKNOWN

LIGHT CONDITIONS

5

1 DAYLIGHT
2 DAWN
3 DUSK
4 DARK - LIGHTED ROADWAY
5 DARK - NOT LIGHTED
6 DARK - UNKNOWN LIGHTING
7 GLARE
8 OTHER
9 UNKNOWN

SCHOOL BUS RELATED

1

1 NO
2 YES, DIRECTLY INVOLVED
3 YES, INDIRECTLY INVOLVED
4 UNKNOWN

WORK ZONE RELATED

1

1 NO
2 YES
3 UNKNOWN

TYPE OF WORK ZONE

1

1 LANE CLOSURE
2 LANE SHIFT/CROSSOVER
3 WORK ON SHOULDER OR MEDIAN
4 INTERMITTENT/MOVING WORK
5 OTHER

LOCATION OF CRASH IN WORK ZONE

1


1 BEFORE FIRST WORK ZONE WARNING SIGN
2 ADVANCE WARNING AREA
3 TRANSITION AREA
4 ACTIVITY AREA

WORKERS PRESENT

1

1 NO
2 YES
3 UNKNOWN

Diagram



Truck/Bus

UNIT #

0 1

THE CRASH INVOLVED ONE OR MORE OF THE FOLLOWING:
A TRUCK (MOTOR VEHICLE) WITH A GVWR MORE THAN 10,000 POUNDS; OR
A TRUCK (MOTOR VEHICLE) WITH A HAZARDOUS MATERIALS PLACARD; OR
A BUS DESIGNED FOR AT LEAST 8 PERSONS, INCLUDING DRIVER.

AND

THE CRASH RESULTED IN ONE OR MORE OF THE FOLLOWING:
A FATALITY; OR
AN INJURY REQUIRING TRANSPORTATION FOR IMMEDIATE MEDICAL TREATMENT; OR
AT LEAST ONE VEHICLE WAS TOWED DUE TO DISABLING DAMAGE OR REQUIRED INTERVENING ASSISTANCE BEFORE PROCEEDING UNDER ITS OWN POWER.

COMPANY (FROM SHIPPING PAPERS)

WTS Trucking

COMPANY PHONE

(419)410-7241

ADDRESS (STREET, CITY, ST, ZIP CODE)

27226 Glenwood RD, Perrysburg, Ohio 43551

US DOT

2091688

ICC MC

PUCO

TRAILER LP ST.

OH

TRAILER LP YEAR

2012

TRAILER LP #

PLACARD #

DIA

CARGO BODY TYPE

0 7

01 NOT APPLICABLE
02 BUS (9-15 INCLUDING DRIVER)
03 VAN/ENCLOSED BOX
04 GRAIN CHIP/GRAVEL

05 POLE
06 CARGO TANK
07 FLATBED
08 DUMP

09 CONCRETE MIXER
10 AUTO TRANSPORTER
11 GARBAGE/REFUSE
12 OTHER
13 UNKNOWN

WEIGHT (GVWR)

2

1 LESS THAN 10,000
2 10,001 - 20,000
3 MORE THAN 20,000

CDL CLASS

1

1 CLASS A
2 CLASS B
3 CLASS C
4 CLASS M
5 CLASS D

HAZARDOUS MATERIALS PLACARD

1

1 NO
2 YES
3 UNKNOWN

HAZARDOUS MATERIALS RELEASED

1

1 NO
2 YES
3 NOT APPLICABLE
4 UNKNOWN

Police Action

DATE CRASH REPORTED

0 5 0 6 2 0 1 1

TIME REC CALL

0 4 1 7

DISPATCH

0 4 1 7

ARRIVED

0 4 1 8

CLEARED

0 5 1 8

OTHER

3 0

TOTAL MINUTES

0 0 9 1

OFFICER'S NAME *

Billups, Erick

BADGE # *

0 0 5 0

CHECKED BY

BJGOCKSTETTER

DATE REPORT FILED *

0 5 1 2 2 0 1 1

REPORT TAKEN BY

1

1 POLICE AG ENCY
2 MOTORIST

REPORT TAKEN AT

1

1 SCENE
2 STATION
3 OTHER

SUPPLEMENT *
"X" IF YES

1

LOCAL REPORT # *

1 0 - 0 3 0 2 - 9 0

TOP COPY - ODPS BOTTOM COPY - AG ENCY

CAD Incident Number - LHP110506000726

OHIO TRAFFIC ACCIDENT - DIAGRAM/NARRATIVE CONTINUATION

OH-2 (REV. 1/82)

LOCAL REPORT NUMBER 10-0302-90	REPORTING AGENCY Ohio State Highway Patrol	DATE OF ACCIDENT 05/06/2011
IN COUNTY OF Sandusky	ACCIDENT LOCATION IR0080	

Damage Analysis:

Damage: Red 2005 Peterbuilt 379, Plate [REDACTED] VIN # 1XP5DU9X85D [REDACTED]

- Engine caught fire; possible engine damage.
- Oil leaked from underneath hood of vehicle.
- No damage to trailer, plate # [REDACTED]

Insurance: Westgate Insurance Agency Inc, Policy # [REDACTED]

Comments: While sitting stationary in my patrol on the Ohio Turnpike Exit 91, I Tpr. Billups U-50 was approached by a toll booth worker and she advised that she received a call about a truck on fire. Upon arriving on scene, I noticed that the driver of the vehicle was putting out the fire with a fire extinguisher. The fire was coming from underneath the hood.

The driver of the vehicle stated that there was a vibration coming from the glove box area and soon after a huge ball of fire erupted from underneath the hood. The driver then stated that he drove to the south side shoulder and put out the fire. The driver and occupant reported no injuries.

- Photos were taken.

OFFICER'S SIGNATURE

BADGE NO.
0050

OHIO TRAFFIC CRASH WITNESS STATEMENT

OH-3 REV 1/82

LOCAL REPORT NUMBER	10-0302-90	REPORTING AGENCY	Ohio State Highway Patrol	DATE OF CRASH	05/06/2011
---------------------------	------------	---------------------	---------------------------	---------------	------------

FOR LOCAL USE ONLY - DO NOT SUBMIT TO THE STATE EXCEPT FOR FATAL CRASHES

I, [REDACTED]	HEREBY MAKE THIS VOLUNTARY STATEMENT TO		
(PRINTED)			
Billups, Erick	AT	IR0080	
(OFFICERS NAME)		(LOCATION)	
ADDRESS OF WITNESS [REDACTED] Sylvania, Ohio [REDACTED]		PHONE [REDACTED]	
SIGNATURE OF WITNESS	OFFICERS SIGNATURE		

OHIO TRAFFIC CRASH WITNESS STATEMENT

OH-3 REV 1/82

LOCAL REPORT NUMBER	10-0302-90	REPORTING AGENCY	Ohio State Highway Patrol	DATE OF CRASH	05/06/2011
---------------------------	------------	---------------------	---------------------------	---------------	------------

FOR LOCAL USE ONLY - DO NOT SUBMIT TO THE STATE EXCEPT FOR FATAL CRASHES

[illegible]