



U.S. Department of Transportation
National Highway Traffic Safety Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received
OCT 24 2011
04-OCT-2011

Repository

Reference No.
10428660

OWNER INFORMATION (Type or Print)

Name [Redacted]
Address [Redacted]
City **RIALTO** State **CA** Zip Code [Redacted]

Daytime Telephone Number [Redacted] E-mail Address [Redacted]
Evening Telephone Number [Redacted]

The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side
1HGCM66526A [Redacted] Make **HONDA** Model **ACCORD** Model Year **2006**

Date Purchased **06-25-2006** Dealer's Name and Telephone Number **ROCK HONDA 909-970-8400** Engine: No: Cylinders **6** Fuel Type: **UNLEADED**

Original Owner Dealer's City **FONTANA, CA.** State **CA** Zip Code **92335**

Transmission Type **AUTOMATIC** Antilock Brakes Cruise Control Powertrain **3.0** Multiple Failure: **HIGH-PRESSURE POWER STEERING HOSE** Incident Date(s) **13-SEP-2011**

FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Code: **010000 STEERING** Failure Mileage **158000** Failure Speed **10-15 MPH**

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make [Redacted] Tire Model (Name or Number) [Redacted] Tire Size (Example P215/65R15) [Redacted]
DOT No. (Example: DOTM19ABC036) Original Equipment Prior Repair Failure Location: [Redacted]
Tire Component Code [Redacted] Tire Failure Type: [Redacted]

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: [Redacted] Date Manufactured: [Redacted] Model No./Name: [Redacted]
Seat Type: [Redacted] Installation System: [Redacted]
Child Seat Component Code: [Redacted] Failed Part: [Redacted]

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash Yes No Fire Yes No Number of Persons Injured **NONE** Number of Deaths **NONE** Reported to Police **N**

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

TL* THE CONTACT OWNS A 2006 HONDA ACCORD EX. THE CONTACT STATED THAT THE VEHICLE STARTED TO LEAK FLUIDS AND WHITE SMOKE WAS COMING FROM UNDER THE HOOD OF THE VEHICLE. THE DEALER DIAGNOSED THAT THERE WAS A HOLE IN THE HIGH PRESSURE POWER STEERING HOSE. THE MANUFACTURER WAS NOT CONTACTED. THE CONTACT REFERENCED NHTSA CAMPAIGN ID NUMBER: 07V551000 (STEERING:HYDRAULIC POWER ASSIST:HOSE, PIPING, AND CONNECTIONS), WHICH HE BELIEVED PERTAINED TO THE EXACT DEFECT. THE VEHICLE WAS REPAIRED BY THE CONTACT. THE FAILURE MILEAGE WAS 158,000 AND THE CURRENT MILEAGE WAS 159,000.

SEE ATTACHMENTS & INDICES & PHOTO
I WOULD LIKE REIMBURSEMENT OF THE COST OF THE POWER STEERING HOSE PART (\$159.41) & REIMBURSEMENT OF COST TO REPLACE THE PART BY A HONDA DEALER

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.



16570 SOUTH HIGHLAND AVE. FONTANA, CA 92336

(800) 89-HONDA - (909) 770-8400

SERVICE AND PARTS HOURS

MONDAY - FRIDAY: 7:00 A.M. - 7:00 P.M.

SATURDAY: 7:00 A.M. - 6:00 P.M.

SUNDAY: CLOSED

NO!!! RETURNS ON ELECTRICAL PARTS

SIGN 

CUST. NO.	TAX EXEMPT NUMBER	CUST. P. O. NO.	SHIP VIA	PAY	SOLD BY	INVOICE DATE	INVOICE
1062				PENDING	MUNIR	10/01/11	133008 HOR

B
I
L
L
T
O

CASH RETAIL

S
H
I
P
T
O

QUANTITY		PART NUMBER / DESCRIPTION	BIN	LIST	NET	AMOUNT
SHIP	B. O.					
1	0	53713-SDB-A01 HOSE	210S	154.17	148.00	148.00
<p>DISCLAIMER OF WARRANTIES - PARTS AND ACCESSORIES NO WARRANTIES EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, ARE MADE BY ROCK HONDA CONCERNING ANY PARTS OR ACCESSORIES YOU ARE PURCHASING. THE ONLY WARRANTIES, IF ANY, ARE MADE BY THE MANUFACTURER. ALL PARTS AND ACCESSORIES ARE SOLD BY ROCK HONDA ON AN "AS-IS" OR "ALL FAULTS" BASIS AND THE ENTIRE RISK AS TO THE QUALITY AND PERFORMANCE OF THE PARTS AND ACCESSORIES IS WITH YOU THE BUYER AND POSSIBLY THE MANUFACTURER. IF ANY OF THESE PARTS OR ACCESSORIES SHOULD PROVE DEFECTIVE FOLLOWING PURCHASE, YOU THE BUYER AND POSSIBLY THE MANUFACTURER, BUT NOT ROCK HONDA ASSUME THE ENTIRE COST OF ALL NECESSARY SERVICING AND REPAIR.</p> <p>REFUNDS OVER \$50 WILL BE PAID BY CHECK. PARTS NOT RETURNABLE AFTER 10 DAYS. 20% HANDLING CHARGE ON ALL PARTS RETURNED. ELECTRICAL OR SPECIAL ORDER PARTS NOT RETURNABLE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE. NO REFUND WITHOUT THIS INVOICE. EPA NO. CAL 000267082</p>						<p>SUBTOTAL 148.00</p> <p>TAX 11.47</p> <p>FREIGHT 0.00</p> <p>PAY THIS AMOUNT 159.47</p>

PLEASE REIMBURSE

16:17:13 CUSTOMER COPY

NET504



16570 SOUTH HIGHLAND AVE. FONTANA, CA 92336

(800) 89-HONDA - (909) 770-8400

SERVICE AND PARTS HOURS

MONDAY - FRIDAY: 7:00 A.M. - 7:00 P.M.

SATURDAY: 7:00 A.M. - 6:00 P.M.

SUNDAY: CLOSED

NO!!! RETURNS ON ELECTRICAL PARTS

SIGN

CUST. NO.	TAX EXEMPT NUMBER	CUST. P. O. NO.	SHIP VIA	PAY	SOLD BY	INVOICE DATE	INVOICE
1062				PENDING ELI		10/01/11	133012 HOR

B
I
L
L
T
O

CASH RETAIL

S
H
I
P
T
O

QUANTITY		PART NUMBER / DESCRIPTION	BIN	LIST	NET	AMOUNT
SHIP	B. O.					
2	0	08206-9002 FLUID, P.S.	NWALL	6.53	5.99	11.98
<p>DISCLAIMER OF WARRANTIES - PARTS AND ACCESSORIES</p> <p>NO WARRANTIES EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, ARE MADE BY ROCK HONDA CONCERNING ANY PARTS OR ACCESSORIES YOU ARE PURCHASING. THE ONLY WARRANTIES, IF ANY, ARE MADE BY THE MANUFACTURER. ALL PARTS AND ACCESSORIES ARE SOLD BY ROCK HONDA ON AN "AS-IS" OR "ALL FAULTS" BASIS AND THE ENTIRE RISK AS TO THE QUALITY AND PERFORMANCE OF THE PARTS AND ACCESSORIES IS WITH YOU THE BUYER AND POSSIBLY THE MANUFACTURER. IF ANY OF THESE PARTS OR ACCESSORIES SHOULD PROVE DEFECTIVE FOLLOWING PURCHASE, YOU THE BUYER AND POSSIBLY THE MANUFACTURER, BUT NOT ROCK HONDA ASSUME THE ENTIRE COST OF ALL NECESSARY SERVICING AND REPAIR.</p> <p>REFUNDS OVER \$50 WILL BE PAID BY CHECK. PARTS NOT RETURNABLE AFTER 10 DAYS. 20% HANDLING CHARGE ON ALL PARTS RETURNED. ELECTRICAL OR SPECIAL ORDER PARTS NOT RETURNABLE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE. NO REFUND WITHOUT THIS INVOICE. EPA NO. CAL 000287082</p>						<p>SUBTOTAL 11.98</p> <p>TAX 0.93</p> <p>FREIGHT 0.00</p> <p>PAY THIS AMOUNT 12.91</p>

Rock Honda: Thank you for choosing Rock Honda!

System: We have alerted the online representatives that you are waiting. Someone should be with you momentarily.

Rock Honda: We appreciate your patience. One of the online representatives should be with you momentarily.

Rock Honda: We appreciate your patience. One of the online representatives should be with you momentarily.

Rock Honda: We appreciate your patience. One of the online representatives should be with you momentarily.

Rock Honda: We appreciate your patience. One of the online representatives should be with you momentarily.

Rock Honda: We appreciate your patience. One of the online representatives should be with you momentarily.

Rock Honda: We appreciate your patience. One of the online representatives should be with you momentarily.

Rock Honda: We appreciate your patience. One of the online representatives should be with you momentarily.

Rock Honda: We appreciate your patience. One of the online representatives should be with you momentarily.

Rock Honda: We appreciate your patience. One of the online representatives should be with you momentarily.

Rock Honda: We appreciate your patience. One of the online representatives should be with you momentarily.

System: A representative has joined the conversation. Compose your message below and then click Send.

Internet Sales: Hello, my name is , How may I help you?

You: *I have a 2006 Honda Accord EX V6. I noticed that my power steering hose is leaking and is causing smoke to be generated underneath the passenger side hood of the car. I checked online and there was a recall on Hondas in Australia for the same problem as well as Acuras in North America with the same problem and same type engine and build as my 2006 Honda. Will I be able to bring my Honda to Rock Honda and have it repaired for free? I do not want my Honda that I brought from Rock Honda to catch on fire. I was chatting with Dianna earlier but got disconnected. My name is [REDACTED] the 2006 Honda vehicle owner.*

FRom [REDACTED] - PLEASE READ

You: Did you receive?

Internet Sales: Ok i can have service contact you with further details on this if you would like.

You: *That would be wonderful. My cellular number is [REDACTED]. I can be reached on that telephone number 24/7. I would like to get the maater repaired as soon as possible, as I would hate my vehicel to catch on fire since it currently smokes from the leak and I will ber out of a vehicle unless it is repaired.*

You: Do you need anything else from me for now?

Internet Sales: Your email.

You: [REDACTED]

Internet Sales: Thats all, i will service contact you.

You: Thanky you! Have a wonderful day!

MORE RECALL INFO:

- Honda Accord Honda Civic Honda Element

~~APRIL 2010 -- Honda is recalling certain model year 2010 Acura ZDX passenger cars manufactured between November 12, 2009 and March 22, 2010. During the manufacturing process, the dashboard covering material may have not been properly laser scored to allow complete deployment of the front passenger's SRS airbag. In the event of a crash, the airbag will not deploy properly, increasing the risk of injury. Honda will notify owners and Acura dealers will inspect the dashboard covering material and replace if necessary free of charge. The safety recall began on April 21, 2010. Honda's recall campaign number is R34. 10V-145~~

PLEASE READ

APRIL 2010 -- Honda is recalling certain model year 2004 through 2008 Acura TSX passenger vehicles manufactured between September 25, 2002 and February 13, 2008. Prolonged high under hood temperatures may cause the power steering hose to deteriorate prematurely and may cause the hose to crack and leak power steering oil. Oil leaking onto a hot exhaust pipe will generate smoke and a burning smell, and could potentially result in an under hood fire. Honda will notify owners and dealers will repair the vehicles free of charge. The safety recall is expected to begin on or about May 28, 2010. 10V-174

10-4-3011-1050HRC-SPDKE TO NHTSA REPAT 1-888-327-4236, MADE COMPLAINT CLAIM,
2) DEFECT NO. 10428660,
3) CASE NO. 392013
1. 10-4-11, 11 DOWNS - SPKETO, MARSHON -
AT AMERICAN HONDA.
COMPLAINT # N 012011-10-0401377.

FOUND UNDER AUTO LEMON LAW ATTORNEYS
LEMON AUTO. COM.

HONDA ACCORD Problems with Steering

Car Recalls | Tire Recalls | Motorcycle Recalls | RV Recalls | Commercial Vehicles | Child Car Seats | Complaints

Search | Alerts

2006 HONDA ACCORD Problems & Complaints

Read complaint(s) filed for the **2006 HONDA ACCORD**. These complaints & problems includes information received by **NHTSA** from consumers either directly or as recorded by the Vehicle Safety Hotline. This information may be used by NHTSA during the investigation process. You may file your own complaint for the **2006 HONDA ACCORD** by calling the NHTSA Monday-Friday 8am to 8pm at (888) 327-4236, TTY: (800) 424-9153. You can also [file your complaint online](#).

[Honda Good Reasons](#) Learn about Honda Accord's low cost of ownership. See offers today. [goodreasons.shop honda.com](#)

[Ask a Honda Mechanic](#) 8 Honda Mechanics Are Online. A Question is Answered Every 9 Sec! [Honda.JustAnswer.com](#)

[New Bosch® Iridium Plug](#) Top of the Line Bosch® Spark Plug. Get Info, Watch Videos & More Now! [www.lightemup.com/iridium](#)

AdChoices ▶

Vehicle Information (148 Complaints)

Date reported	May 25, 2011
Location	PEORIA, AZ
Manufacturer	HONDA (AMERICAN HONDA MOTOR CO.)
Vehicle	<u>2006 HONDA ACCORD</u>
Transmission	Automatic
Drivetrain	Front Wheel Drive
Fuel type	Gas
Occurrences	1
Crash involved	N
Injuries	0
Deaths	0
Source	Email

Ventshade Visor - Side Window - Plastic

\$44.99

Shop now!

Complaint - Steering

[All Complaints](#)

TL CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT STATED THE POWER STEERING HOSE LEAKED OIL INTO THE EXHAUST SYSTEM. THE VEHICLE WAS TAKEN TO THE DEALER WHO STATED THERE WERE NO RECALLS FOR THE FAILURE AND THE COST TO REPLACE THE HOSE WOULD BE \$400. THE MANUFACTURER WAS CONTACTED AND A CLAIM WAS FILED. THE MANUFACTURER OFFERED NO OTHER ASSISTANCE. THE VEHICLE WAS NOT REPAIRED. THE VIN WAS UNKNOWN. THE FAILURE MILEAGE WAS 90,000. UPDATED 06/10/11 THE POWER STEERING HIGH PRESSURE HOSE LEAKED ONTO THE EXHAUST GENERATING SMOKE AND A BURNING SMELL. THE VEHICLE WAS TAKEN TO AN ACURA DEALER WHO STATED THAT THE SMOKE WAS CAUSED BY A FAILURE OF THE HIGH PRESSURE STEERING HOSE WHICH WAS INCLUDED ON A SAFETY RECALL BY THE SAME MANUFACTURER FOR TWO SEPARATE ACURA MODELS WITH THE SAME ENGINE AND HIGH PRESSURE POWER STEERING HOSE AS THE ONE IN THE HONDA ACCORD. HOWEVER, THERE WAS NO RECALL FOR THE FAILED PART ON THE HONDA MODEL. THE REPLACEMENT HOSE AND INSTALLATION WOULD COST \$400. THE MANUFACTURER WAS CONTACTED AND A CLAIM WAS FILED. THE MANUFACTURER OFFERED NO OTHER ASSISTANCE. THE VEHICLE WAS REPAIRED BY THE ACURA DEALER AT THE VEHICLE'S OWNERS EXPENSE OF \$438.80. THE REPLACEMENT PART LISTED ON THE DEALERS REPAIR INVOICE IS THE SAME AS THE FAILED PART LISTED ON THE SERVICE BULLETIN FILED WITH THE NHTSA BY THE MANUFACTURER. UPDATED 08/31/11

(PLEASE READ)



FAQs Password Help Contact Us Tell a Friend

Dealer Reviews Classified Ads Consumer Corner About DealerRater

Login | Register

Acura TL Recalls

Recalls for the Acura TL

Listed below are the known recalls for the Acura TL.

[Honda Good Reasons](#) Learn about Honda Accord's low cost of ownership. See offers today. [goodreasons.shophonda.com](#)

[Ask a Honda Mechanic Now](#) A Honda Mechanic Will Answer Now! Honda Questions Answered Today: 87. [Honda-JustAnswer.com](#)

[Honda — 2011 Clearance](#) Honda Dealers Cut Prices to Make Sales — Get Internet Prices & Save! [Honda.DealersClearingLots.com](#)

AdChoices

By Year: [2008](#) | [2007](#) | [2006](#) | [2005](#) | [2004](#) | [2003](#) | [2002](#) | [2000](#) | [1999](#) | [1998](#) | [1997](#) | [1996](#) |

2008 Acura TL Recall

Item Affected: STEERING:HYDRAULIC POWER ASSIST:HOSE, PIPING, AND CONNECTIONS
Date Announced: 2/28/2008

Description of Recall:
HONDA IS RECALLING 273,000 MY 2004-2008 ACURA TL VEHICLES. PROLONGED HIGH UNDER-HOOD TEMPERATURES MAY CAUSE THE POWER STEERING HOSE TO DETERIORATE PREMATURELY CAUSING THE HOSE TO CRACK AND LEAK POWER STEERING FLUID.

Action Needed To Fix It:
DEALERS WILL INSTALL A NEW HEAT RESISTANT POWER STEERING HOSE FREE OF CHARGE. THE RECALL BEGAN ON APRIL 28, 2008. OWNERS MAY CONTACT ACURA AT 800-382-2238. THIS IS AN EXPANSION OF A PREVIOUS RECALL (PLEASE SEE 07V551).

Find your local [Acura Dealer](#).

2007 Acura TL Recall

Item Affected: STEERING:HYDRAULIC POWER ASSIST:HOSE, PIPING, AND CONNECTIONS
Date Announced: 2/28/2008

Description of Recall:
HONDA IS RECALLING 273,000 MY 2004-2008 ACURA TL VEHICLES. PROLONGED HIGH UNDER-HOOD TEMPERATURES MAY CAUSE THE POWER STEERING HOSE TO DETERIORATE PREMATURELY CAUSING THE HOSE TO CRACK AND LEAK POWER STEERING FLUID.

Action Needed To Fix It:
DEALERS WILL INSTALL A NEW HEAT RESISTANT POWER STEERING HOSE FREE OF CHARGE. THE RECALL BEGAN ON APRIL 28, 2008. OWNERS MAY CONTACT ACURA AT 800-382-2238. THIS IS AN EXPANSION OF A PREVIOUS RECALL (PLEASE SEE 07V551).

Find your local [Acura Dealer](#).

2006 Acura TL Recall

Item Affected: STEERING:HYDRAULIC POWER ASSIST:HOSE, PIPING, AND CONNECTIONS
Date Announced: 2/28/2008

Description of Recall:
HONDA IS RECALLING 273,000 MY 2004-2008 ACURA TL VEHICLES. PROLONGED HIGH UNDER-HOOD TEMPERATURES MAY CAUSE THE POWER STEERING HOSE TO DETERIORATE PREMATURELY CAUSING THE HOSE TO CRACK AND LEAK POWER STEERING FLUID.

Action Needed To Fix It:
DEALERS WILL INSTALL A NEW HEAT RESISTANT POWER STEERING HOSE FREE OF CHARGE. THE RECALL BEGAN ON APRIL 28, 2008. OWNERS MAY CONTACT ACURA AT 800-382-2238. THIS IS AN EXPANSION OF A PREVIOUS RECALL (PLEASE SEE 07V551).

Find your local [Acura Dealer](#).

2006 Acura TL Recall


Item Affected: AIR BAGS:FRONTAL
Date Announced: 11/7/2005

Description of Recall:
ON CERTAIN PASSENGER VEHICLES, ON THE FRONTAL AIRBAG SYSTEM WHERE THE TWO EXTERNAL IMPACT SENSORS IS MOUNTED, NEAR THE FRONT HEADLIGHTS THE FRONT IMPACT SENSOR BOLTS WERE NOT PROPERLY TORQUED.

Action Needed To Fix It:
DEALERS WILL INSPECT AND REMOVE THE BUMPER AND RETORQUE THE LOOSE BOLTS. THE RECALL BEGAN ON

PLEASE READ!

PLEASE READ!



Complaints - Search Results

1 Record(s) Displayed.

Report Date : October 2, 2011 at 12:14 PM

Search Type : VEHICLE

Year : 2006

Make : HONDA

Model : ACCORD

Make : HONDA

Model : ACCORD

Year : 2006

Manufacturer : HONDA (AMERICAN HONDA MOTOR CO.)

Crash : No

Fire : No

Number of Injuries : 0

ODI ID Number : 10402670

Number of Deaths : 0

Date of Failure: May 19, 2011

VIN : 1HGCM66546A...

Component: STEERING:HYDRAULIC POWER ASSIST:HOSE, PIPING, AND CONNECTIONS

Summary:

TL*THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT STATED THE POWER STEERING HOSE LEAKED OIL INTO THE EXHAUST SYSTEM. THE VEHICLE WAS TAKEN TO THE DEALER WHO STATED THERE WERE NO RECALLS FOR THE FAILURE AND THE COST TO REPLACE THE HOSE WOULD BE \$400. THE MANUFACTURER WAS CONTACTED AND A CLAIM WAS FILED. THE MANUFACTURER OFFERED NO OTHER ASSISTANCE. THE VEHICLE WAS NOT REPAIRED. THE VIN WAS UNKNOWN. THE FAILURE MILEAGE WAS 90,000. UPDATED 06/10/11 *BF THE POWER STEERING HIGH PRESSURE HOSE LEAKED ONTO THE EXHAUST GENERATING SMOKE AND A BURNING SMELL. THE VEHICLE WAS TAKEN TO AN ACURA DEALER WHO STATED THAT THE SMOKE WAS CAUSED BY A FAILURE OF THE HIGH PRESSURE STEERING HOSE WHICH WAS INCLUDED ON A SAFETY RECALL BY THE SAME MANUFACTURER FOR TWO SEPARATE ACURA MODELS WITH THE SAME ENGINE AND HIGH PRESSURE POWER STEERING HOSE AS THE ONE IN THE HONDA ACCORD. HOWEVER, THERE WAS NO RECALL FOR THE FAILED PART ON THE HONDA MODEL. THE REPLACEMENT HOSE AND INSTALLATION WOULD COST \$400. THE MANUFACTURER WAS CONTACTED AND A CLAIM WAS FILED. THE MANUFACTURER OFFERED NO OTHER ASSISTANCE. THE VEHICLE WAS REPAIRED BY THE ACURA DEALER AT THE VEHICLE'S OWNERS EXPENSE OF \$438.80. THE REPLACEMENT PART LISTED ON THE DEALERS REPAIR INVOICE IS THE SAME AS THE FAILED PART LISTED ON THE SERVICE BULLETIN FILED WITH THE NHTSA BY THE MANUFACTURER. UPDATED 08/31/11

PLEASE
READ!

1200 New Jersey Avenue, SE, West Building Washington DC 20590 USA
1.888.327.4236 TTY 1.800.424.9153



safercar.gov

Recalls Summary

Vehicle Make / Model:	Model Year(s):
HONDA / ACCORD	2005-2010
HONDA / CR-V	2007-2010
HONDA / ELEMENT	2005-2008
NHTSA Campaign ID Number:	11V395000

Summary:

HONDA IS RECALLING CERTAIN MODEL YEAR 2005-2010 ACCORD, 2007-2010 CR-V, AND 2005-2008 ELEMENT PASSENGER CARS MANUFACTURED FROM JULY 1, 2004, THROUGH SEPTEMBER 3, 2010. THE OUTER RACE OF THE SECONDARY SHAFT BEARING MAY BE BROKEN DURING CERTAIN DRIVING STYLES. A BROKEN OUTER RACE MAY CAUSE ABNORMAL NOISE, THE MALFUNCTION INDICATOR LIGHT TO TURN ON, AND ALLOW CONTACT BETWEEN THE TRANSMISSION IDLE GEAR AND AN ELECTRONIC SENSOR HOUSING WITHIN THE TRANSMISSION.

Consequence:

THIS COULD RESULT IN A SHORT CIRCUIT CAUSING THE ENGINE TO STALL. ADDITIONALLY, BROKEN PIECES OF THE OUTER RACE OR BALL BEARING FROM THE SECONDARY SHAFT MAY BECOME LODGED IN THE PARKING PAWL RESULTING IN THE VEHICLE ROLLING AFTER THE DRIVER HAS PLACED THE GEAR SELECTOR IN THE PARK POSITION. ENGINE STALL AND UNEXPECTED VEHICLE MOVEMENT INCREASES THE RISK OF A CRASH OR PERSONAL INJURY TO PERSONS WITHIN THE PATH OF A ROLLING VEHICLE.

Remedy:

HONDA WILL NOTIFY OWNERS AND DEALERS WILL UPDATE THE AUTOMATIC TRANSMISSION CONTROL MODULE SOFTWARE FREE OF CHARGE. THE SAFETY RECALL BEGAN ON AUGUST 27, 2011. OWNERS MAY CONTACT HONDA AUTOMOBILE CUSTOMER SERVICE AT 1-800-999-1009.

Notes:


HONDA'S RECALL CAMPAIGN NUMBER IS R89. OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

10-3-11
Area of
Faulty/Leaking/failed @
High pressure power steering hose for
my 2006 Honda Accord VEHICLE.



10-3-11.

/ Area where hose was leaking



10-3-11

Faulty/leaking
power
steering hose
that was
removed from
my Honda.




10-3-11.
Where
new
power
steering
hose
is
replaced,

A
↓
HONDA
PART (OEM).



10-3-11 / 2006 Honda Accord
Replaced High Pressure
Power Steering hose. No longer leaking.

[REDACTED]
RIALTO, CA



OSI REFERENCE NO. 10428660

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
U.S. DEPARTMENT OF TRANSPORTATION
1200 NEW JERSEY AVENUE,
SE, WEST BUILDING
WASHINGTON D.C. 20590