

INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C . 552(B)(6)

EQ-10448902-3380

From: [Wells, Cynthia CTR \(NHTSA\)](#)
To: [Fogle, Brenda CTR \(NHTSA\)](#)
Subject: FW: Nissan Titan 2005 ODI# 10448902
Date: Monday, March 05, 2012 11:33:11 AM

Report Vehicle Safety Defects!



www.safercar.gov

From: Williams, Maritza CTR (NHTSA) **On Behalf Of** DataQuality, DataQuality (NHTSA)
Sent: Monday, March 05, 2012 11:10 AM
To: Wells, Cynthia CTR (NHTSA)
Subject: FW: Nissan Titan 2005 ODI# 10448902

From: [REDACTED] [\[mailto:\[REDACTED\]\]](mailto:[REDACTED])
Sent: Monday, March 05, 2012 10:33 AM
To: DataQuality, DataQuality (NHTSA)
Subject: Nissan Titan 2005 ODI# 10448902

2005 Nissan Titan 1N6BA06B65N [REDACTED] 1 of 2 vehicles purchased June 2005 Jackie Cooper Nissan, Tulsa, OK
11-30-2006 NHTSA Recall # 06V459000 Defective wiring harness, rear door, effecting seat belts, speakers & air bag
2-6-2012 Nissan North America, Yvette x457201 claims vehicle not covered in NHTSA recall. File # 7372373
2-16-2012 Hauck Tire & Car Care replaced wiring harness #24014ZH10A, Inv #113859, Total \$381.56, problem solved.
2-22-2012 Complaint filed with NHTSA, Renaldo #10448902

ATTACHED:

Recall: NHTSA-1a.jpg, **Repair Invoice:** NHTSA-1b.jpg, **NHTSA 10448902:** NHTSA-1c.jpg

On Jan 29, 2012 I was about 50 miles north of Tulsa in the Nissan Titan preparing to enter a toll road. Recognizing I did not have enough change, I stopped on the side of the road, opened the rear door to obtain change, and after I closed the rear door and entered the driver's seat, the air bag warning light was flashing. On 1-30-2012 I discussed this event with Hauck Car Care and he found the NHTSA recall 06V459000. I determined the other 2005 Nissan Titan, that was sold, did have these repairs done from stated recall, but my vehicle did not. I call Nissan North America 2-6-12 and she stated my vehicle was not included in this recall. I asked why one 2005 vehicle would be recalled and the other 2005 vehicle not, she simply said "not covered". Hauck Care Care called Nissan NA on my behalf and the unknown person said my vehicle has been recalled and repaired, which it has not, which brings me to believe they may have made an error.

Clearly the wiring harness was at fault. I ask why this vehicle would not be included in the recall when the wiring harness was defective on this vehicle as well.

Please review and advise.

[Redacted] Cell [Redacted]

Tulsa, OK

Ph: [Redacted] Fx: [Redacted]



NHTSA Campaign # 06V459000

Vehicles: **Make/Models:** **Model/Build Years:**
NISSAN/TITAN 2004-2006

Defect: ON CERTAIN KING CAB TRUCKS, THE WIRES IN THE HARNESS WERE ROUTED THROUGH THE REAR DOORS AND INTO THE BODY. THESE WIRES MAY BREAK DUE TO OVER BENDING OF THE HARNESS AS THE DOOR IS OPENED AND CLOSED. THE HARNESS CONTAINS WIRES FOR THE DRIVER SEAT BELT PRETENSIONER AND FOR THE FRONT PASSENGER SEAT BELT WHICH IS PART OF THE OCCUPANT CLASSIFICATION SYSTEM. WIRES FOR THE REAR AUDIO SPEAKERS ARE ALSO CONTAINED IN THE HARNESS.

Component Affected: ELECTRICAL SYSTEM

Corrective Action: DEALERS WILL REPLACE THE WIRE HARNESS COVER WITH A DIFFERENT TYPE THAT PREVENTS OVER BENDING OF THE HARNESS AND THE HARNESS WILL BE REROUTED FREE OF CHARGE. THE RECALL BEGAN ON FEBRUARY 19, 2007. OWNERS MAY CONTACT NISSAN AT 1-800-647-7261.

Consequence: IF THE WIRES FOR THE SEAT BELTS AND SPEAKER WIRES BREAK AND MAKE CONTACT, THERE IS A POSSIBILITY THAT THE PRETENSIONER MAY DEPLOY. IF THIS HAPPENS WHEN THE SEAT BELT IS RETRACTED, IT WILL NOT BE POSSIBLE TO USE THE SEAT BELT. IF ONE OF THE WIRES ON THE RIGHT SIDE HARNESS FOR THE SEAT BELT TENSION SENSOR BREAKS, THE PASSENGER SIDE FRONT AIR BAG WILL NOT DEPLOY AS DESIGNED IN A FRONTAL COLLISION INCREASING THE RISK OF A CRASH AND PERSONAL INJURY.

Mfr. Campaign #:

Mfr. Involved: NISSAN NORTH AMERICA, INC.

Vehicles Affected: 96500

File Date: 11/30/2006

The vehicle you are working on may or may not be affected by this recall. Contact the vehicle manufacturer for clarification.



Hauck Tire and Car Care, Inc.
3647 South Harvard
Tulsa OK 74135-2227
749-8473 or 749-TIRE

Repair Order # 113859
 Date In 02/13/2012
 Date Out 02/16/2012

[Redacted]
Tulsa OK

Home

Cell Phones

Work Phones

License	Make	Model	Year	Mileage	Serial #
[Redacted]	Nissan	Titan	2005	121008	1n6ba06b65r [Redacted]

Mechanic	Part #	Description	Quantity	Price	Extended
	NOTICE	Air Bag Light Flashing			
10	24014ZH10A	L/R Door Wire Harnes	1	79.31	79.31
10	LABOR	install l/r wiring harness	1	225.50	225.50
10	COMP CODE #	Computer Scan B1086	1	70.00	70.00

Paid by:

Visa/Mastercard	381.56	Taxable Parts	79.31
		Labor	295.50
		Exempt Parts	0.00
		Sales Tax	6.75
		Tire Tax	0.00
		Total	381.56



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

22-FEB-2012

Repository Reference No.
10448902**OWNER INFORMATION (Type or Print)**

Name

Address

City

TULSA

State

OK

Zip Code

Daytime Telephone Number

Evening Telephone Number

E-mail Address

The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side

1N6BA06B65N

Make

NISSAN

Model

TITAN

Model Year

2005

Date Purchased

Dealer's Name and Telephone Number

Engine:

No: Cylinders

Fuel Type:

Original Owner

Dealer's City

State

Zip Code

Transmission Type

 Antilock Brakes

Powertrain

Multiple Failure:

Incident Date(s)

29-JAN-2012

 Cruise Control**FAILED COMPONENT(S)/PART(S) INFORMATION**

Vehicle Component Code: 140000 AIR BAGS

Failure Mileage

120000

Failure Speed

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number-)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM19ABC036)

 Original Equipment
 Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type:

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash

 Yes No

Fire

 Yes No

Number of Persons Injured

Number of Deaths

Reported to Police

N

Narrative Description of Incident(s), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

TL* THE CONTACT OWNS A 2005 NISSAN TITAN. THE CONTACT STATED THAT WHILE IN PARK, THE AIR BAG WARNING LIGHT ILLUMINATED. THE VEHICLE WAS TAKEN TO A PRIVATE MECHANIC WHERE THE MECHANIC CONFIRMED THAT THE AIR BAG WIRING HARNESS NEEDED TO BE REPLACED. THE MANUFACTURER WAS CONTACTED AND THEY ADVISED THE CONTACT THAT THE VIN DID NOT QUALIFY FOR REPAIRS UNDER NHTSA CAMPAIGN ID NUMBER: 06V459000 (ELECTRICAL SYSTEM). THE VEHICLE WAS REPAIRED. THE FAILURE MILEAGE WAS 120,000 AND THE CURRENT MILEAGE WAS 120,300.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.