

INFORMATION Redacted PURSUANT TO THE FREEDOM OF  
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

**From:** [Wells, Cynthia CTR \(NHTSA\)](#)  
**To:** [Nelson, Carla CTR \(NHTSA\)](#)  
**Subject:** FW: NHTSA: Follow up to ODI Complaint: 10493418  
**Date:** Thursday, January 31, 2013 11:46:21 AM

---

**From:** EVOQ (NHTSA)  
**Sent:** Thursday, January 31, 2013 11:43 AM  
**To:** Wells, Cynthia CTR (NHTSA)  
**Subject:** FW: NHTSA: Follow up to ODI Complaint: 10493418

---

**From:** [REDACTED]  
**Sent:** Wednesday, January 30, 2013 6:35 PM  
**To:** EVOQ (NHTSA)  
**Subject:** RE: NHTSA: Follow up to ODI Complaint: 10493418

The cost to correct this problem is \$615.00 dollars . Paid for by me. Hyundai will not admit to the problem. This is an engineering / design defect for the 2013 veloster turbo car. I drove a Hyundai wagon with the same lighting set up and it was fine. It had to be the way the light is mounted in the fender.

---

**From:** [EVOQ@dot.gov](mailto:EVOQ@dot.gov) [<mailto:EVOQ@dot.gov>]  
**Sent:** Wednesday, January 30, 2013 9:19 AM  
**To:** [REDACTED]  
**Subject:** FW: NHTSA: Follow up to ODI Complaint: 10493418