

CL-10716883-9328

INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

[REDACTED]
Goodyear, Arizona [REDACTED]

NVS-216
Ref. No. 10716883

OCT 22 2015

August 29, 2015

Safety Recall
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Dear Sir:

I am enclosing a copy of a notice I just received from Chevrolet. It sounds like the exact problem I had with my 2008 Malibu, a problem that cost me \$1383.00 to repair, and of which I pleaded with you to follow up on, save lives, and order Chevrolet to reimburse me for.

You have done nothing, except "enter the information into our database."

What will it take -- maybe loss of lives, carport explosions, neighborhood fires -- before you conduct a serious investigation of this deadly situation?

Please advise -- NOW!

[REDACTED]

ET
10/26/15
SHD



Chevrolet
P.O. Box 909989
Milwaukee, WI 53209-9989



14728 1G1AK55F077 13 0024106

GOODYEAR, AZ



August 2015

This notice applies to your 2007 Cobalt VIN: 1G1AK55F077

Dear

As the owner of a 2007 model year Chevrolet Cobalt, your satisfaction with our product is very important to us.

This letter is intended to make you aware that some 2007 model year Chevrolet Cobalt vehicles may have a cracked fuel tank inlet control valve. Vehicles that have had a fuel-tank removal procedure are especially at risk for this condition, as the tank-removal process can damage the inlet control valve. This condition may cause fuel or fuel vapor to leak from the fuel tank. A vehicle with this condition may display an illuminated Service Engine Soon (SES) light, leak fuel onto the ground under the rear of the vehicle between the rear tires during or after fueling, or emit a strong fuel odor from the rear of the vehicle.

Do not take your vehicle to your Chevrolet dealer as a result of this letter unless you believe that your vehicle has the condition as described above.

What We Have Done: General Motors is providing owners with additional protection for the condition described above. If this condition occurs on your 2007 Chevrolet Cobalt within 10 years of the date your vehicle was originally placed in service or 150,000 miles, whichever occurs first, the condition will be repaired for you at **no charge**. Diagnosis or repair for conditions other than the condition described above is not covered under this special coverage program.

What You Should Do: If you believe that your vehicle has the condition described above, repairs and adjustments qualifying under this special coverage must be performed by a Chevrolet dealer. You may want to contact your Chevrolet dealer to find out how long they will need to have your vehicle so that you may schedule the appointment at a time that is convenient for you. This will also allow your dealer to order parts if they are not already in stock. Keep this letter with your other important glove box literature for future reference.

GM

[Redacted]
Goodyear, Arizona [Redacted]

PHOENIX AZ 852

07 OCT 2015 PM 6 L



Director
Office of Defects Investigation
National Highway Traffic Safety Adm.
1200 New Jersey Avenue SE
Washington, D.C. 20590

20590

