

May 11, 2015
CL-10120921-1360

MAY 20 2015

Dear US Department of Transportation NHTSA

I am the owner of a 2014 Nissan Sentra, VIN number 3N1AB7AP6EY [REDACTED] I have a problem I like to report. According to manual, the following is supposed to be the case: "When the ignition is placed in the ON or START position, the supplemental air bag warning light illuminates for about 7 seconds and then turns off." However, for my car, when there's a passenger sitting in the right front seat, it can take more than 5 minutes before the light turns off. Therefore, I think the sensor system has a problem.

I just wish to report this problem. Thank you!

If you like to reply, my name and address is as follows:

[REDACTED]
[REDACTED]
RICHMOND, CA [REDACTED]

NM
5/20/15
SMD

[REDACTED]

RICHMOND, CA [REDACTED]

MAY 19 2015

OAKLAND CA 946

11 MAY 2015 PM 8 L



US DEPT OF TRANSPORTATION
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
OFFICE OF DEFECTS INVESTIGATION (NVS-210)
1200 NEW JERSEY AVE SE
WASHINGTON, DC 20590

20590

