


JUL - 1 2015

 <p>DOT Auto Safety Hotline Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline</p>		FOR AGENCY USE ONLY 100148 Date Received 28-MAY-2015 Repository <input type="checkbox"/> Reference No. 10721870	
OWNER INFORMATION (Type or Print)			
Name		Daytime Telephone Number	
Address		E-mail Address	
City	State	Zip Code	
SADDLE BROOK	NJ		
The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).			
VEHICLE INFORMATION			
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side		Make	Model
3N1CB51D62L		NISSAN	SENTRA
Model Year		Engine:	Fuel Type:
2002		No: Cylinders	Don't Know
Date Purchased	Dealer's Name and Telephone Number	State	
11/4/07	WYCKOFF	NJ	
Original Owner	Dealer's City	Zip Code	
<input type="checkbox"/>	WYCKOFF	07401	
Transmission Type	<input type="checkbox"/> Antilock Brakes	Powertrain	Multiple Failure:
2:7.	<input checked="" type="checkbox"/> Cruise Control	7.7.	Yes
Incident Date(s)			
15-JAN-2014		# MAR 2012	
FAILED COMPONENT(S)/PART(S) INFORMATION			
Vehicle Component Codes: ENGINE (PWS), BRAKES (PWS)		Failure Mileage	Failure Speed
		Don't know Dient receive	5
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE			
Tire Make	Tire Model (Name or Number)	Tire Size (Example P215/65R15)	
D/A	N/A	N/A	
DOT No. (Example: DOTM19ABC036)	<input type="checkbox"/> Original Equipment	Failure Location:	
	<input checked="" type="checkbox"/> Prior Repair		
Tire Component Code	Tire Failure Type:		
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE			
Make:	Date Manufactured:	Model No./Name:	
Seat Type:	Installation System:		
Child Seat Component Code:	Failed Part:		
APPLICABLE INCIDENT INFORMATION (Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)			
Crash	Fire	Number of Persons Injured	Number of Deaths
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	0	0
Reported to Police			
N			
Narrative Description of Incident(S), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).			
TL* THE CONTACT OWNS A 2002 NISSAN SENTRA. WHILE DRIVING AT 5 MPH, THE ENGINE STALLED AND THE BRAKE PEDAL FAILED TO RESPOND WHEN DEPRESSED. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS UNKNOWN. MAY 2012 - WAS ON HIGHWAY ROUTE 46 IN SADDLE BROOK/LODI, THE CAR PLANNED! ALL LIGHTS & POWER SHUT OFF WAS UNABLE TO STOP CAR OR PULL E-BRAKE MANAGED TO GET OFF HIGHWAY HAD TO THROW CAR INTO PARK TO STOP. JAN 2014 - WAS AT A STOP SIGN ONE STARTED TO PULL ENTIRE CAR SHUT OFF AGAIN			
Include, if available, Police/Fire Department Report, Photos, and Repair Invoice.		ATTACH ADDITIONAL SHEETS IF NECESSARY	

ON CAR AS OF 2015. 98,000+ miles of failure

Both resulted in being unable to turn vehicle back on until "CAM & CRANK" sensors were replaced-



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

Dear Consumer:

NVS-216rr

As a follow-up to your report to the Vehicle Safety Hotline (VSH), we have recorded your information on the enclosed Vehicle Owner's Questionnaire (VOQ) form. Please review the form and make changes, additions and corrections as necessary. Additionally, please provide a more detailed description of the failure(s) you reported that you believe relevant to safety. Also, if available, include copies of repair invoices, letters to the manufacturer, or any other document related to the problem(s) you reported. If a crash or fire occurred, include a copy of the police or fire department report.

It is helpful to be as thorough as possible in your report so that our ability to use your report will be maximized. If you do not have the information, it is not necessary to complete all the boxes. However, it is very difficult to identify the scope of a vehicle problem unless the vehicle identification number (VIN) is known. The VIN is located inside the vehicle on the dashboard adjacent to the left (driver's side) of the windshield pillar and on the drivers' door or the driver's door jam. It may also be listed on a dealer repair invoice or your insurance or registration cards. When reporting a tire problem, the brand name, tire line and complete tire size should be included. Be certain to provide the DOT tire identification number. It is usually located near the rim flange of the tire on either side of the tire.

We do not make your personal information (name, address, phone numbers, etc.) available to the general public. However, if we open an investigation that involves your vehicle, we will provide the manufacturer of your vehicle with a complete copy of your report. The information you provide may assist the manufacturer and NHTSA in determining if a safety-related defect exists.

Any information provided is entirely voluntary. There is no consequence or penalty of any kind if you do not wish to provide it. We seek this information to develop both statistical and investigative evidence that will help identify potential safety related problems in vehicles or vehicle equipment, e.g., tires, child safety seats, jacks, etc.

When completed, please fold and staple or tape the form so that the pre-addressed portion of the form is on the outside. If a larger envelope is used, tape the VOQ form to the larger envelope so that the pre-addressed portion of the form is showing.

If further assistance is needed, please contact the VSH at their toll-free number, 1-888-327-4236.

Thank you for your cooperation.

Sincerely,

Randy Reid Chief
Correspondence Research Division
Office of Defects Investigation
Enforcement

Enclosure: VOQ



Search

Search Mail

Search Web

Home

Compose

Delete Move Spam More

Trending Searches

Inbox

Drafts (16)

Sent

Spam (2)

Trash

Smart Views

Folders

ADDRESSES FROM CE...

APARTMENT LIST INFO

BEAUTY QUESTIONS

CANCELLED ORDERS

Capital one pre-paid c...

CAR STUFF

CLOTHING SHOES

Crunch info

Direct Loans correspon...

Documents

Exercise equipment

GIFTS AND PRESENTS

JOKES FROM CELL

LIVING SOCIAL DEALS

Notes

ORDERS FOLLOW UP

Paystubs UE 2014

Pictures

Private

Progressive Insurance

Recipes

Registration PW Chan...

Saved Mail

Songs N Music Stuff

SPREADSHEETS 2015

Sprint Bill and issues

Vapor King Corresp.

WO 4 Home n Nutrition

WO TRACKING

WORK Data Comm

Recent

My Games



Recommended Games



More Games »

please print this i need it to give to nissan

People

On: Friday, March 9, 2012, 3:24 PM

inc.com wrote:

1-800-NISSAN - 1

OPT 2, 3

CALLED 3PM-SPOKE TO BRITANNY EXT #458115

SHE IS LOOKING INTO THIS RECALL

NHTSA Recall ID Number: 03V455008

2002 Nissan Sentra Recall Date:

11/17/2003

2002 Nissan Sentra Component:

ENGINE AND ENGINE COOLING

Potential Units Affected:

13100

Summary:

ON CERTAIN PASSENGER VEHICLES, THE CIRCUIT BOARD FOR THE CRANK POSITION SENSOR OR CAM POSITION SENSOR MAY HAVE AN IMPROPER SOLDER JOINT DUE TO SOLDER DEFORMATION CAUSED BY HEAT STRESS ACCELERATED BY THE EXISTENCE OF FLUX RESIDUE DURING THE SOLDERING PROCESS.

Consequence:

THIS COULD CAUSE THE "SERVICE ENGINE SOON" WARNING LIGHT TO COME ON, CREATE A NO START CONDITION, CAUSE REDUCED ENGINE POWER, OR CAUSE THE ENGINE TO STOP RUNNING WITHOUT WARNING DURING VEHICLE OPERATION, WHICH COULD RESULT IN A CRASH.

Remedy:

DEALERS WILL REPLACE THE CRANK POSITION SENSORS, CAMSHAFT POSITION SENSOR(S), AND IN SOME CASES, THE VARIABLE TIMING CONTROL SENSOR(S). VEHICLES INVOLVED IN A PREVIOUS RECALL CAMPAIGN, 01V357, ARE ALSO INCLUDED IN THIS NEW CAMPAIGN. THE REPLACEMENT SENSORS USED IN THAT CAMPAIGN ARE ALSO AFFECTED. OWNER NOTIFICATION BEGAN ON DECEMBER 22, 2003. OWNERS SHOULD CONTACT NISSAN AT 1-800-647-7261 OR INFINITI AT 1-800-662-6200.

Notes: NISSAN NORTH AMERICA, INC., R3021/R3022

THIS IS EXACTLY WHAT WAS REPLACED ON MY CAR BY BOBBY HAVE TE RECEIPT !!! \$375


FILE: [REDACTED]

Production Dept.
Specialists Marketing Services, Inc.

T [REDACTED] ext. [REDACTED]
F [REDACTED]
E [REDACTED]

Reply, Reply All or Forward | More

Click to reply all



Vintage Blast
PRE-WORKOUT SUPPLEMENT

CLEAN ENERGY. EVERY TIME.

☆☆☆☆☆ 459 Average Amazon.com customer review, 6/8/2015

☆☆☆☆☆ Best yet!
"Top notch product from top notch people. This is now a regular part of my workout routine."

Compose

Delete Move Spam More

Trending Searches

- Inbox
- Drafts (16)
- Sent
- Spam (2)
- Trash
- Smart Views
- Folders
 - ADDRESSES FROM CE...
 - APARTMENT LIST INFO
 - BEAUTY QUESTIONS
 - CANCELLED ORDERS
 - Capital one pre-paid c...
 - CAR STUFF
 - CLOTHINGnSHOES
 - Crunch info.
 - Direct Loans correspon...
 - Documents
 - Exercise equipment
 - GIFTS AND PRESENTS
 - JOKES from CELL
 - LIVING SOCIAL DEALS
 - Notes
 - ORDERS FOLLOW UP
 - Paystubs LIE 2014
 - Pictures
 - Private
 - Progressive Insurance
 - Recipes
 - Registration PW Chan...
 - Saved Mail
 - Songs N Music Stuff
 - SPREADSHEETS 2015
 - Sprint Bill and issues
 - Vapor King Corresp.
 - WO 4 Home n Nutrition
 - WO TRACKING
 - WORK Data Comm

please print this i need it to give to nissan

People

On Friday, March 9, 2012 3:24 PM, [REDACTED] Inc.com> wrote:
 1-800 NISSAN - 1
 OPT 2, 3
 CALLED 3PM SPOKE TO BRITANNY EXT # 458115

SHE IS LOOKING IN TO THIS RECALL

NHTSA Recall ID Number: 03V455000

2002 Nissan Sentra Recall Date:

11/17/2003

2002 Nissan Sentra Component:

ENGINE AND ENGINE COOLING

Potential Units Affected:

13100

Summary:

ON CERTAIN PASSENGER VEHICLES, THE CIRCUIT BOARD FOR THE CRANK POSITION SENSOR OR CAM POSITION SENSOR MAY HAVE AN IMPROPER SOLDER JOINT DUE TO SOLDER DEFORMATION CAUSED BY HEAT STRESS ACCELERATED BY THE EXISTENCE OF FLUX RESIDUE DURING THE SOLDERING PROCESS.

Consequence:

THIS COULD CAUSE THE "SERVICE ENGINE SOON" WARNING LIGHT TO COME ON, CREATE A NO START CONDITION, CAUSE REDUCED ENGINE POWER, OR CAUSE THE ENGINE TO STOP RUNNING WITHOUT WARNING DURING VEHICLE OPERATION, WHICH COULD RESULT IN A CRASH.

Remedy:

DEALERS WILL REPLACE THE CRANK POSITION SENSORS, CAMSHAFT POSITION SENSOR(S), AND IN SOME CASES, THE VARIABLE TIMING CONTROL SENSOR(S). VEHICLES INVOLVED IN A PREVIOUS RECALL CAMPAIGN, 01V357, ARE ALSO INCLUDED IN THIS NEW CAMPAIGN. THE REPLACEMENT SENSORS USED IN THAT CAMPAIGN ARE ALSO AFFECTED. OWNER NOTIFICATION BEGAN ON DECEMBER 22, 2003. OWNERS SHOULD CONTACT NISSAN AT 1-800-647-7261 OR INFINITI AT 1-800-662-6200.

Notes: NISSAN NORTH AMERICA, INC., R3021/R3022

THIS IS EXACTLY WHAT WAS REPLACED ON MY CAR BY BOBBY HAVE TE RECIEPT !!! \$375


FILE # [REDACTED]

Production Dept.
 Specialists Marketing Services, Inc.

T [REDACTED] ext. [REDACTED]
 F [REDACTED]
 E [REDACTED]

Reply, Reply All or Forward | More

Click to reply all



Vintage Blast
 PRE-WORKOUT SUPPLEMENT

CLEAN ENERGY. EVERY TIME.

459 Average Amazon.com customer review, 6/9/12/2015

Best yet!
 "Top notch product from top notch people. This is now a regular part of my workout routine."

My Games



Recommended Games



More Games >

Search

Search Mail

Search Web

Home

Compose

Delete Move Spam More

Trending Searches

Inbox

Drafts (16)

Sent

Spam (1)

Trash

Smart Views

Folders

ADDRESSES FROM CE...
APARTMENT LIST INFO

BEAUTY QUESTIONS

CANCELLED ORDERS

Capital one pre-paid c...

CAR STUFF

CLOTHINGnSHOES

Crunch info

Direct Loans correspon...

Documents

Exercise equipment

GIFTS AND PRESENTS

JOKES from CELL

LIVING SOCIAL DEALS

Notes

ORDERS FOLLOW UP

Paystubs UE 2014

Pictures

Private

Progressive Insurance

Recipes

Registration PW Chan...

Saved Mail

Songs N Music Stuff

SPREADSHEETS 2015

Sprint Bill and issues

Vapor King Corresp.

WO 4 Home n Nutrition

WO TRACKING

WORK Data Comm

Recent

My Games



Recommended Games



More Games

RECALL F/U CALLED 031312 - NOT ELIGIBL

People

Mar 14, 2012

To

1-800 NISSAN - 1

OPT 2, 3

CALLED 3PM SPOKE TO BRITANNY EXT # 458115

SHE IS LOOKING IN TO THIS RECALL

CALLED BACK 031312 11:03AM

SPOKE TO LORENZO EXT 457345- BRITANNY WAS BUSY HE SAID THAT MY CAR IS NOT PART OF THE RECALL AND THAT I CAN NOT BE REIMBURSTED

TOLD HIM TO FAX ME OVER PAPER WORK I WANTED TO SEE IT IN WRITING.

NEW CASE #

NHTSA Recall ID Number: 03V455000

2002 Nissan Sentra Recall Date:

11/17/2003

2002 Nissan Sentra Component:

ENGINE AND ENGINE COOLING

Potential Units Affected:

13100

Summary:

ON CERTAIN PASSENGER VEHICLES, THE CIRCUIT BOARD FOR THE CRANK POSITION SENSOR OR CAM POSITION SENSOR MAY HAVE AN IMPROPER SOLDER JOINT DUE TO SOLDER DEFORMATION CAUSED BY HEAT STRESS ACCELERATED BY THE EXISTENCE OF FLUX RESIDUE DURING THE SOLDERING PROCESS.

Consequence:

THIS COULD CAUSE THE "SERVICE ENGINE SOON" WARNING LIGHT TO COME ON, CREATE A NO START CONDITION, CAUSE REDUCED ENGINE POWER, OR CAUSE THE ENGINE TO STOP RUNNING WITHOUT WARNING DURING VEHICLE OPERATION, WHICH COULD RESULT IN A CRASH.

Remedy:

DEALERS WILL REPLACE THE CRANK POSITION SENSORS. CAMSHAFT POSITION SENSOR(S), AND IN SOME CASES, THE VARIABLE TIMING CONTROL SENSOR(S). VEHICLES INVOLVED IN A PREVIOUS RECALL CAMPAIGN, 01V357, ARE ALSO INCLUDED IN THIS NEW CAMPAIGN. THE REPLACEMENT SENSORS USED IN THAT CAMPAIGN ARE ALSO AFFECTED. OWNER NOTIFICATION BEGAN ON DECEMBER 22, 2003. OWNERS SHOULD CONTACT NISSAN AT 1-800-647-7261 OR INFINITI AT 1-800-662-6200.

Notes: NISSAN NORTH AMERICA, INC., R3021/R3022

THIS IS EXACTLY WHAT WAS REPLACED ON MY CAR BY BOBBY HAVE TE RECEIPT!

FILE #

THESE MAY HAVE BEEN LINKED TO WHAT BOBBY FIXED:

Find great prices on Schick Hydro products

Shop now

Search

Search Mail

Search Web

Home

Compose

Delete Move Spam More

Trending Searches

Inbox

Drafts (16)

Sent

Spam (1)

Trash

Smart Views

Folders

ADDRESSES FROM CE...

APARTMENT LIST INFO

BEAUTY QUESTIONS

CANCELLED ORDERS

Capital one pre-paid c...

CAR STUFF

CLOTHINGnSHOES

Crunch info

Direct Loans correspon...

Documents

Exercise equipment

GIFTS AND PRESENTS

JOKES from CELL

LIVING SOCIAL DEALS

Notes

ORDERS FOLLOW UP

Paystubs UE 2014

Pictures

Private

Progressive Insurance

Recipes

Registration PW Chan...

Saved Mail

Songs N Music Stuff

SPREADSHEETS 2015

Sprint Bill and issues

Vapor King Corresp.

WO 4 Home n Nutrition

WO TRACKING

WORK Data Comm

Recent

My Games



Recommended Games



More Games >

RECALL F/U CALLED 031312 - NOT ELIGIBLI

People

Mar 14, 2012

To [Redacted]

1-800 NISSAN - 1
OPT 2, 3
CALLED 3PM SPOKE TO BRITANNY EXT # 458115

SHE IS LOOKING IN TO THIS RECALL

CALLLED BACK 031312 11:03AM
SPOKE TO LORENZO EXT 457345- BRITTANY WAS BUSY HE SAID THAT
MY CAR IS NOT PART OF THE RECALL AND THAT I CAN NOT BE
REIMBURSTED
TOLD HIM TO FAX ME OVER PAPER WORK I WANTED TO SEE IT IN
WRITING.
NEW CASE # [Redacted]

NHTSA Recall ID Number: 03V455000

2002 Nissan Sentra Recall Date:

11/17/2003

2002 Nissan Sentra Component:

ENGINE AND ENGINE COOLING

Potential Units Affected:

13100

Summary:

ON CERTAIN PASSENGER VEHICLES, THE CIRCUIT BOARD FOR THE CRANK POSITION SENSOR OR CAM POSITION SENSOR MAY HAVE AN IMPROPER SOLDER JOINT DUE TO SOLDER DEFORMATION CAUSED BY HEAT STRESS ACCELERATED BY THE EXISTENCE OF FLUX RESIDUE DURING THE SOLDERING PROCESS.

Consequence:

THIS COULD CAUSE THE "SERVICE ENGINE SOON" WARNING LIGHT TO COME ON, CREATE A NO START CONDITION, CAUSE REDUCED ENGINE POWER, OR CAUSE THE ENGINE TO STOP RUNNING WITHOUT WARNING DURING VEHICLE OPERATION, WHICH COULD RESULT IN A CRASH.

Remedy:

DEALERS WILL REPLACE THE CRANK POSITION SENSORS. CAMSHAFT POSITION SENSOR(S), AND IN SOME CASES, THE VARIABLE TIMING CONTROL SENSOR(S). VEHICLES INVOLVED IN A PREVIOUS RECALL CAMPAIGN, 01V357, ARE ALSO INCLUDED IN THIS NEW CAMPAIGN. THE REPLACEMENT SENSORS USED IN THAT CAMPAIGN ARE ALSO AFFECTED. OWNER NOTIFICATION BEGAN ON DECEMBER 22, 2003. OWNERS SHOULD CONTACT NISSAN AT 1-800-647-7261 OR INFINITI AT 1-800-662-6200.

Notes: NISSAN NORTH AMERICA, INC., R3021/R3022

THIS IS EXACTLY WHAT WAS REPLACED ON MY CAR BY BOBBY HAVE TE RECEIPT !! [Redacted]

FILE # [Redacted]


THESE MAY HAVE BEEN LINKED TO WHAT BOBBY FIXED:

Search

Search Mail

Search Web

Home



Compose

Delete Move Spam More

Trending Searches

- Inbox
- Drafts (16)
- Sent
- Spam (1)
- Trash
- Smart Views
- Folders
 - ADDRESSES FROM CE...
 - APARTMENT LIST INFO
 - BEAUTY QUESTIONS
 - CANCELLED ORDERS
 - Capital one pre-paid c...
 - CAR STUFF
 - CLOTHINGnSHOES
 - Crunch info
 - Direct Loans correspon...
 - Documents
 - Exercise equipment
 - GIFTS AND PRESENTS
 - JOKES from CELL
 - LIVING SOCIAL DEALS
 - Notes
 - ORDERS FOLLOW UP
 - Paystubs UE 2014
 - Pictures
 - Private
 - Progressive Insurance
 - Recipes
 - Registration PW Char...
 - Saved Mail
 - Songs N Music Stuff
 - SPREADSHEETS 2015
 - Sprint Bill and issues
 - Vapor King Corresp.
 - WO 4 Home n Nutrition
 - WO TRACKING
 - WORK Data Comm
- Recent
- My Games
 - SLOTS
- Recommended Games
 -
- More Games »

STILL DIDNT RECEIVE PAPER WORK ON TH-

People

Mar 15, 2012

To [Redacted]

STILL WAITING FOR THE FAX INFO THAT I WAS NOT PART OF THIS RECALL TO BE SENT OVER TO ME.
 C'd/BTHIS AFTERNOON 031512 12:07PM AND GAVE THEM AND ALT FAX NUMBER AT MY JOB [Redacted]
 ASKING THEM TO PLEASE SEND OVER THAT INFORMATION AGAIN typically with in 24hrs so they said it should come today.

SPOKE TO: Evette
EXT # : 457201

Production Dept.
Specialists Marketing Services, Inc.

T [Redacted] xt. [Redacted]
F [Redacted]



From: [Redacted]
 Sent: Wednesday, March 14, 2012 11:17 AM
 To: [Redacted]
 Subject: RECALL F/U CALLED 031312 - NOT ELIGIBLE

1-800 NISSAN - 1
OPT 2, 3
CALLED 3PM SPOKE TO BRITANNY EXT # 458115

SHE IS LOOKING IN TO THIS RECALL

CALLED BACK 031312 11:03AM
 SPOKE TO LORENZO EXT 457345- BRITTANY WAS BUSY HE SAID THAT MY CAR IS NOT PART OF THE RECALL AND THAT I CAN NOT BE REIMBURSTED
 TOLD HIM TO FAX ME OVER PAPER WORK I WANTED TO SEE IT IN WRITING.
 NEW CASE # [Redacted]

NHTSA Recall ID Number: 03V455000

2002 Nissan Sentra Recall Date:

11/17/2003

2002 Nissan Sentra Component:

ENGINE AND ENGINE COOLING

Potential Units Affected:


13100

Summary:

ON CERTAIN PASSENGER VEHICLES, THE CIRCUIT BOARD FOR THE CRANK POSITION SENSOR OR CAM POSITION SENSOR MAY HAVE AN IMPROPER SOLDER JOINT DUE TO SOLDER DEFORMATION CAUSED BY HEAT STRESS ACCELERATED BY THE EXISTENCE OF FLUX RESIDUE DURING THE SOLDERING PROCESS.

Consequence:

THIS COULD CAUSE THE "SERVICE ENGINE SOON" WARNING LIGHT TO COME ON, CREATE A NO START



784 Average Amazon.com customer review

My dog loves this food!
 "I've been feeding this to my dog for about 3 weeks now and he loves it! I have seen improvements with his energy and coat! his coat is so shiny!"

Search

Search Mail

Search Web

Home

Compose

Delete Move Spam More

Trending Searches

- Inbox
- Drafts (16)
- Sent
- Spam (1)
- Trash
- Smart Views
- Folders
 - ADDRESSES FROM CE...
 - APARTMENT LIST INFO
 - BEAUTY QUESTIONS
 - CANCELLED ORDERS
 - Capital one pre-paid c...
 - CAR STUFF
 - CLOTHINGnSHOES
 - Crunch info
 - Direct Loans correspon...
 - Documents
 - Exercise equipment
 - GIFTS AND PRESENTS
 - JOKES from CELL
 - LIVING SOCIAL DEALS
 - Notes
 - ORDERS FOLLOW UP
 - Paystubs UE 2014
 - Pictures
 - Private
 - Progressive Insurance
 - Recipes
 - Registration PW Chan...
 - Saved Mail
 - Songs N Music Stuff
 - SPREADSHEETS 2015
 - Sprint Bill and issues
 - Vapor King Corresp.
 - WO 4 Home n Nutrition
 - WO TRACKING
 - WORK Data Comm

FW: Lawyer #

People

From: [Redacted]
 Sent: Wednesday, April 11, 2012 2:00 PM
 To: [Redacted]
 Subject: Lawyer #

Lawyer #
 Mike Power (610) 558-6220

make sure you tell him that they are saying are vins arent part of a recall but we both had the same issue as the recall and paper work from the mecahnic that it was those censors.

[Redacted]
 Production Dept.
 Specialists Marketing Services, Inc.

T [Redacted] ext. [Redacted]
 F [Redacted]
 E [Redacted]

From: Jorge
 Sent: Wednesday, April 11, 2012 1:48 PM
 To: [Redacted]
 Subject: RE: Lawyer #

Mike Power (610) 558-6220

From: [Redacted]
 Sent: Wednesday, April 11, 2012 12:44 PM
 To: Jorge Patino
 Subject: Lawyer #

I definitely am interested in speaking with the lawyer that helped you out.

[Redacted]
 Production Dept.
 Specialists Marketing Services, Inc.

T [Redacted] ext. [Redacted]
 F [Redacted]
 E [Redacted]

The information contained in this email message is the property of Specialists Marketing Services, Inc. or its affiliates. This message (and any accompanying files) is intended only for the use of the individual or entity to which it is addressed and may contain information that is confidential, subject to copyright or which constitutes a trade secret. Specialists Marketing Services, Inc. does not accept responsibility for any errors or omissions within this message, or any attachments, that have arisen as a result of e-mail transmission.

My Games



Recommended Games



More Games >

- Compose
- Inbox
- Drafts (16)
- Sent
- Spam (1)
- Trash
- Smart Views
- Folders
 - ADDRESSES FROM CE...
 - APARTMENT LIST INFO
 - BEAUTY QUESTIONS
 - CANCELLED ORDERS
 - Capital one pre-paid c...
 - CAR STUFF
 - CLOTHINGnSHOES
 - Crunch info
 - Direct Loans correspon...
 - Documents
 - Exercise equipment
 - GIFTS AND PRESENTS
 - JOKES from CELL
 - LIVING SOCIAL DEALS
 - Notes
 - ORDERS FOLLOW UP
 - Paystubs UE 2014
 - Pictures
 - Private
 - Progressive Insurance
 - Recipes
 - Registration PW Chan...
 - Saved Mail
 - Songs N Music Stuff
 - SPREADSHEETS 2015
 - Sprint Bill and issues
 - Vapor King Corresp.
 - WO 4 Home n Nutrition
 - WO TRACKING
 - WORK Data Comm
- Recent
- My Games
 - SLOTS
- Recommended Games
 -
- More Games »

Delete Move Spam More

Trending Searches

C/B 041112 -FW: RECALL F/U CALLED 03131 People

Apr 11, 2012 To [Redacted]

Rosa - spoke to #457264
 Never received recall letter through them
 told her again that I wanted them to send it over to me
 gave her the house fax # this time!
 Same CASE # [Redacted]

[Redacted]
 Production Dept.
Specialists Marketing Services, Inc.

T [Redacted] ext [Redacted]
 F [Redacted]
 E [Redacted]

From: [Redacted]
Sent: Wednesday, March 14, 2012 11:17 AM
To: [Redacted]
Subject: RECALL F/U CALLED 031312 - NOT ELIGIBLE

1-800 NISSAN - 1
 OPT 2, 3
 CALLED 3PM SPOKE TO BRITANNY EXT # 458115

SHE IS LOOKING IN TO THIS RECALL

CALLLED BACK 031312 11:03AM
 SPOKE TO LORENZO EXT 457345- BRITTANY WAS BUSY HE SAID THAT
 MY CAR IS NOT PART OF THE RECALL AND THAT I CAN NOT BE
 REIMBURSTED
 TOLD HIM TO FAX ME OVER PAPER WORK I WANTED TO SEE IT IN
 WRITING.
 NEW CASE # [Redacted]

NHTSA Recall ID Number: 03V455000

2002 Nissan Sentra Recall Date:

11/17/2003

2002 Nissan Sentra Component:

ENGINE AND ENGINE COOLING

Potential Units Affected:

13100

Summary:

ON CERTAIN PASSENGER VEHICLES, THE CIRCUIT BOARD
 FOR THE CRANK POSITION SENSOR OR CAM POSITION
 SENSOR MAY HAVE AN IMPROPER SOLDER JOINT DUE TO
 SOLDER DEFORMATION CAUSED BY HEAT STRESS
 ACCELERATED BY THE EXISTENCE OF FLUX RESIDUE
 DURING THE SOLDERING PROCESS.

Consequence:

THIS COULD CAUSE THE "SERVICE ENGINE SOON"
 WARNING LIGHT TO COME ON, CREATE A NO START
 CONDITION, CAUSE REDUCED ENGINE POWER, OR CAUSE
 THE ENGINE TO STOP RUNNING WITHOUT WARNING
 DURING VEHICLE OPERATION, WHICH COULD RESULT IN A
 CRASH.

Nissan North America, Inc.
Consumer Affairs
One Nissan Way
Franklin, TN 37068-5003

January 20, 2014

RE: Nissan Recall Issue - On going
Case # [REDACTED] File # [REDACTED]

Dear Sirs,

This is now the second time I have had to contact Nissan Headquarters regarding this issue. I have been having an ongoing issue with the Crank and Cam Sensors since 2012.

The first time these sensors had to be replaced, I was coming home from work and the car completely failed while I was driving on the Highway. The brakes did not work, the emergency brake would not work and I had no power at all. The lights started to flash in the car including the service engine light and the whole car just failed. Luckily I was able to roll off the highway safely where I then had to throw my car into park to get it to stop before running through a building that was in front of me.

The car had to be towed and was unable to be started or jumped. I had to have both the Cam and Crank sensors replaced in March of 2012 {paperwork for bill repair enclosed}. Upon having this replaced I went on to the Nissan website for recalls that were done. My car Make, Model and year was part a recall which I was never notified of {recall information enclosed}.

I had contacted the Nissan recall department and spoken to a Brittany at ext 458115, March 14th, 2012. I was sent a letter and told that I was not notified because my car vin number was not part of the recall list {denial paperwork from Nissan enclosed}.

It is not even two years later and again I was driving the car and thank god I was only at a stop sign this time and the lights started to flash and the entire car failed and shut off, again being unable to be jumped or started. The car had to be towed to another mechanic who determined this again was the Cam and Crank sensors failing. He has replaced both them of them { copy of new bill enclosed}, which I now paid for, for the second time.

He advised me that there is problem with the car that is causing the Cam and Crank sensors to fail. I do not want to hear that I am not part of a recall list that I clearly should have been on. I not only want to

reimbursed for both of the repairs fees at this point, but also want Nissan to fix what is causing this to happen with my car sensors. I have contacted an attorney to deal with this matter as I am now afraid for my life.

The next time it happens and I was told this will happen again by my mechanic, I could be driving on a highway again and not be so lucky. In the event that I am hurt or worse killed, and/or hurt someone else I will be opening a claim against Nissan for their refusal to aid and remedy the situation at hand.

I would like to be contacted immediately regarding this matter and hear your companies resolution to dealing with this is at this point in time. I expect this to be taking very seriously as my life can be in danger as this a reoccurring issue due to a fault with in the vehicle itself upon purchase. I can be contacted at the number listed below.

Sincerely,

[REDACTED]
Saddle Brook, NJ [REDACTED]
PH#: [REDACTED]
Email: [REDACTED]

Sincerely,

[REDACTED]
[REDACTED]
Saddle Brook, NJ [REDACTED]
Ph: [REDACTED] Email: [REDACTED]

Search Search Mail Search Web Home

Compose

Delete Move Spam More

Trending Searches

- Inbox
- Drafts (16)
- Sent
- Spam (2)
- Trash
- Smart Views
- Folders
 - ADDRESSES FROM CE...
 - APARTMENT LIST INFO
 - BEAUTY QUESTIONS
 - CANCELLED ORDERS
 - Capital one pre-paid c...
 - CAR STUFF
 - CLOTHINGnSHOES
 - Crunch info
 - Direct Loans correspon...
 - Documents
 - Exercise equipment
 - GIFTS AND PRESENTS
 - JOKES from CELL
 - LIVING SOCIAL DEALS
 - Notes
 - ORDERS FOLLOW UP
 - Paystubs UE 2014
 - Pictures
 - Private
 - Progressive Insurance
 - Recipes
 - Registration FW Chan...
 - Saved Mail
 - Songs N Music Stuff
 - SPREADSHEETS 2015
 - Sprint Bill and issues
 - Vapor King Corresp.
 - WO 4 Home n Nutrition
 - WO TRACKING
 - WORK Data Comm

please print this i need it to give to nissan

People



Jan 20, 2014

To: Mom

On Friday, March 9, 2012 3:24 PM, [Redacted] wrote:
 1-800 NISSAN - 1
 OPT 2, 3
 CALLED 3PM SPOKE TO BRITANNY EXT # 458115

SHE IS LOOKING IN TO THIS RECALL

NHTSA Recall ID Number: 03V455000

2002 Nissan Sentra Recall Date:

11/17/2003

2002 Nissan Sentra Component:

ENGINE AND COOLING

Potential Units Affected:

13100

Summary:

ON CERTAIN PASSENGER VEHICLES, THE CIRCUIT BOARD FOR THE CRANK POSITION SENSOR OR CAM POSITION SENSOR MAY HAVE AN IMPROPER SOLDER JOINT DUE TO SOLDER DEFORMATION CAUSED BY HEAT STRESS ACCELERATED BY THE EXISTENCE OF FLUX RESIDUE DURING THE SOLDERING PROCESS.

Concern:

THIS COULD CAUSE THE "SERVICE ENGINE SOON" WARNING LIGHT TO COME ON, CREATE A NO START CONDITION, CAUSE REDUCED ENGINE POWER, OR CAUSE THE ENGINE TO STOP RUNNING WITHOUT WARNING DURING VEHICLE OPERATION, WHICH COULD RESULT IN A CRASH.

Remedy:

DEALERS WILL REPLACE THE CRANK POSITION SENSORS, CAMSHAFT POSITION SENSOR(S), AND IN SOME CASES, THE VARIABLE TIMING CONTROL SENSOR(S). VEHICLES INVOLVED IN A PREVIOUS RECALL CAMPAIGN, 01V357, ARE ALSO INCLUDED IN THIS NEW CAMPAIGN. THE REPLACEMENT SENSORS USED IN THAT CAMPAIGN ARE ALSO AFFECTED. OWNER NOTIFICATION BEGAN ON DECEMBER 22, 2003. OWNERS SHOULD CONTACT NISSAN AT 1-800-647-7261 OR INFINITI AT 1-800-662-6200.

Notes: NISSAN NORTH AMERICA, INC., R3021/R3022

THIS IS EXACTLY WHAT WAS REPLACED ON MY CAR BY BOBBY HAVE TE RECIEPT !!!

FILE #

Production Dept.
 Specialists Marketing Services, Inc.

T ext.

F

E

My Games



Recommended Games



More Games »



EASTERN ^{Cell #}
DATACOMM

Sales and Service of
Wiring • Data Networks • VoIP Telephone Systems • Wireless • Video

44 Commerce Way, Hackensack, NJ 07601

P: [REDACTED] F: [REDACTED]

EXT 137

Please See
ENCLOSED PAPERWORK
I have copied
~~the~~ of the Bills if
you need them as
Investigation goes
further.