


INFORMATION Redacted PURSUANT TO THE FREEDOM OF

INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

 U.S. Department of Transportation National Highway Traffic Safety Administration		DOT Auto Safety Hotline Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET:www.nhtsa.dot.gov/hotline		FOR AGENCY USE ONLY 100148	
Date Received 30-JUN-2015		Repository <input type="checkbox"/> Reference No. 10731223			
OWNER INFORMATION (Type or Print)					
Name		Address		Daytime Telephone Number	E-mail Address
City		State	Zip Code	Evening Telephone Number	
ELMONT		NY			
The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).					
VEHICLE INFORMATION					
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side		Make	Model	Model Year	
JN1DA31D33T		NISSAN	MAXIMA	2003	
Date Purchased	Dealer's Name and Telephone Number		Engine: No. Cylinders	Fuel Type:	
			6	GAS	
Original Owner	Dealer's City	State	Zip Code		
<input type="checkbox"/>					
Transmission Type	<input type="checkbox"/> Antilock Brakes	Powertrain	Multiple Failure:	Incident Date(s)	
	<input type="checkbox"/> Cruise Control		9	24-JUN-2015 07-July-2015	
FAILED COMPONENT(S)/PART(S) INFORMATION					
Vehicle Component Code: ENGINE (PWS)			P1800 - Vias Control Solenoid Valve		
P0340 - Camshaft position sensor (2)			Failure Mileage	Failure Speed	
P0335 - Crank position sensor (1)			80000	50	
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE					
Tire Make	Tire Model (Name or Number)		Tire Size (Example P215/65R15)		
DOT No. (Example: DOTM19ABC036)	<input type="checkbox"/> Original Equipment	Failure Location:			
	<input type="checkbox"/> Prior Repair				
Tire Component Code			Tire Failure Type:		
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE					
Make:	Date Manufactured:	Model No./Name:			
Seat Type:	Installation System:				
Child Seat Component Code:		Failed Part:			
APPLICABLE INCIDENT INFORMATION (Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)					
Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured	Number of Deaths	Reported to Police	
		0	0	N	
Narrative Description of Incident(S), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).					
TL* THE CONTACT OWNS A 2003 NISSAN MAXIMA. WHILE DRIVING APPROXIMATELY 50 MPH, THE ENGINE STALLED AND ALL THE WARNING LIGHTS ILLUMINATED. THE VEHICLE WAS MERGED OVER TO THE EMERGENCY LANE, WHERE IT WAS TURNED OFF AND RESTARTED; HOWEVER, THE FAILURE RECURRED MULTIPLE TIMES. THE VEHICLE WAS TAKEN TO THE DEALER. THE TECHNICIAN STATED THAT THE CRANK SHAFT POSITION SENSOR NEEDED TO BE REPLACED. THE VEHICLE WAS REPAIRED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE AND THEY INFORMED THE CONTACT THAT THE VIN WAS NOT INCLUDED IN NHTSA CAMPAIGN NUMBER: 03V455000 (ENGINE AND ENGINE COOLING). THE APPROXIMATE FAILURE MILEAGE WAS 80,000.					
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.			ATTACH ADDITIONAL SHEETS IF NECESSARY		
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.					

CUSTOMER #: [REDACTED]

INVOICE



P.O. Box 727209 · 74-15 Northern Blvd.
Jackson Heights, New York 11372
TEL (718) 898-7800
FAX (718) 898-5916

PAGE 1

ELMONT, NY [REDACTED]
HOME: [REDACTED] CONT: [REDACTED]
BUS: [REDACTED] CELL: [REDACTED]

SERVICE ADVISOR: 2831 CHRIS URENA

NYS -DLR. LIC. NO. [REDACTED] NYC -DCA. LIC. NO. [REDACTED]

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
GREY	03	NISSAN MAXIMA	JN1DA31D335 [REDACTED]	[REDACTED]	80929/80930	T4757	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
02JAN03 IS							
02JAN03 DD			18:00 26JUN15		110.00	CASH	26JUN15
R.O. OPENED	READY	OPTIONS: ENG:3.5_Liter_Gas					
06:25 26JUN15	12:27 26JUN15						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CUST STATE ENGINE LIGHT STAY ON CHECK AND ADVISE.
N10 RPL CAM B1 AND VIAS SOLENIOD.

54	CC	3.00				330.00	330.00
1	23731-6J90B	SENSOR ASSY MAGNET			129.35	129.35	129.35
1	14955-8J10A	VALVE ASSY-SOLENIOD			199.90	199.90	199.90
PARTS:	329.25	LABOR:	330.00	OTHER:	0.00	TOTAL LINE A:	659.25

80929 PERFORMED DIAGNOSTIC RETRIEVED CODE P1800,P0340 DIAGNOSED
BANK 1 CAM SHORTED NECESSARY TO REMOVE AND REPLACE CAM 1 SENSOR ALSO
ALSO FOUND VIAS SOLINIOD BINDING NOT RESPONDING REMOVE AND REPLACE
SOLENIOD RESET RECHECK OPERATION..

B MULT POINT AND PRE STATE INSPECTION
MPI MULT POINT AND PRE STATE INSPECTION

54	CC	0.00				0.00	0.00
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE B:	0.00

80929 UPON SERVICE FOUND BELTS WORN NEEDS REPLACEMENT, ENGINE AIR
FILTER DIRTY, THROTTLE BODY AND FUEL INJECTOR NEEDS TO BE SERVICE AND
FRONT LINK EXCESSIVE PLAY RECOMMEND REPLACEMENT.

EST: 149.95 26JUN15 06:25 SA: 2831

Case # [REDACTED]

RECEIVED
JUN 26 2015
BY: [REDACTED]

THESE REPAIRS ARE COVERED BY A LIMITED WARRANTY. LABOR & PARTS 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST.

Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaim all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

TERMS: STRICTLY CASH ALL PARTS NEW EXCEPT AS NOTED.

CUSTOMER SIGNATURE _____

DESCRIPTION	TOTALS
LABOR AMOUNT	330.00
PARTS AMOUNT	329.25
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	659.25
LESS INSURANCE	0.00
SALES TAX	58.51
PLEASE PAY THIS AMOUNT	717.76

RockAuto Customer Service <service@rockauto.com>

July 7, 2015 10:29 PM

To: [REDACTED]

RockAuto Order Confirmation [REDACTED]

RockAuto Order Confirmation Order [REDACTED]

Go to the RockAuto *Catalog*



Tuesday, July 7, 2015 09:24 PM Central Time

Ship To:

[REDACTED]

Elmont, NY [REDACTED]

United States

[REDACTED]

[REDACTED]

Bill To:

[REDACTED]

Elmont, NY [REDACTED]

United States

[REDACTED]

[REDACTED]

	Part Number	Part Type	Price EA	Core EA	Quantity	Total
2003 NISSAN MAXIMA 3.5L V6						
BECK/ARNLEY	1800501 (180-0501)	Crankshaft Position Sensor	\$ 41.79	\$ 0.00	1	\$ 41.79
Discount						\$ -2.09
Shipping	Ground					\$ 9.15
Order Total						\$ 48.85
Visa						-\$ 48.85
Balance Due						\$ 0.00

Your Visa will be charged when your order ships. Your Card will be charged in US Dollars. If you live outside the US, the amount appearing on your bank statement may vary due to bank fees and conversion rates.

When the last item on your order ships, we will send an email listing tracking numbers for all the items on the order.



[Order Status & Returns](#)

To **CHECK ORDER STATUS, MAKE CHANGES, ARRANGE A RETURN** or **REPORT A PROBLEM**