



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 9999999

Date Received

13-JUL-2015

Repository ☐

Reference No.
10734168

OWNER INFORMATION (Type or Print)

Name [REDACTED]
Address [REDACTED]
City HAYDEN LAKE State ID Zip Code [REDACTED]

Daytime Telephone Number

E-mail Address

Evening Telephone Number

The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side
1VWBP7A30C [REDACTED] Make VOLKSWAGEN Model PASSAT Model Year 2012
Date Purchased 05/04/2012 Dealer's Name and Telephone Number DIRITO BROTHERS VW Engine: No: Cylinders 5 Fuel Type: GAS
Original Owner ☒ Dealer's City WALNUT CREEK, CA. State CA Zip Code 94596
Transmission Type AUTO ☒ Antilock Brakes Powertrain FRONT WHEEL DRIVE Multiple Failure: 1 Incident Date(s) 01-JUL-2015
☒ Cruise Control

FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Codes: 980000 UNKNOWN OR OTHER, 141000 AIR BAGS: FRONTAL, 140000 AIR BAGS, 110000 ELECTRICAL SYSTEM, 141200 AIR BAGS: FRONTAL: DRIVER SIDE INFLATOR MODULE
Failure Mileage 59,600 Failure Speed

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make Tire Model (Name or Number) Tire Size (Example P215/65R15)
DOT No. (Example: DOTM19ABC036) ☐ Original Equipment Failure Location:
☐ Prior Repair
Tire Component Code Tire Failure Type:

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: Date Manufactured: Model No./Name:
Seat Type: Installation System:
Child Seat Component Code: Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash ☐ Yes ☒ No Fire ☐ Yes ☒ No Number of Persons Injured Number of Deaths Reported to Police N

Narrative Description of Incident(s), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

ALL STEERING WHEEL FUNCTIONS HAVE STOPPED WORKING INCLUDING THE HORN. THE AIRBAG ICON SHOWS AN "ERROR" MESSAGE. THE STEERING WHEEL MAKES A CRACKING SOUND WHEN IT TURNS. IDENTICAL PROBLEM AS IN THE NHTSA INVESTIGATION #PE15010. I AM CONCERNED THAT THE AIRBAG WILL NOT DEPLOY IN THE EVENT OF AN ACCIDENT. PROBLEM APPEARS TO BE: STEERING WHEEL CLOCK SPRING/STEERING COLUMN CONTROL MODULE (SCCM). DEALER WANTS OVER \$ 500 TO REPLACE IT. THE CAR HAS LESS THAN 58,000 MILES AND WAS PURCHASED BRAND NEW IN 2012.

REPAIR BILL ATTACHED

TOTAL \$ 551.17

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Questionnaire.

Hayden Lake, ID

CUSTOMER #: [REDACTED]



INVOICE

811 N. Greensferry Road
Post Falls, ID 83854
(208) 773-4939
(800) 207-0292

Service Email: service@parkervw.com
www.parkervw.com

HAYDEN LAKE, ID [REDACTED]

PAGE 1

HOME: [REDACTED] CONT: [REDACTED]
BUS: [REDACTED] CELL: [REDACTED]

SERVICE ADVISOR: 64380 A.J. MILLS

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	12	VOLKSWAGEN PASSAT	1VWBP7A30CC [REDACTED]		60141/60141	T473	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
04MAY12 DD	04MAY12		18:00 03AUG15			CASH	03AUG15

R.O. OPENED	READY	OPTIONS:
03AUG15	03AUG15	ENG:2.5_Liter_F.I.

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A CUSTOMER REQUEST TO REPLACE CLOCK SPRING							
1301 BODY							
66250 CPVW						147.00	147.00
1 5K0-953-569-AL ELEC.MODUL						319.08	319.08

Replaced clock spring. Coded the clock spring and reset basic settings. Reset all faults.

REPLACING CLOCK SPRING

PARTS + LABOR WARRANTY 12 MONTHS / 12,000 MILES

$\$485.22 + 69.95 \text{ TAG} =$

$\rightarrow \$555.17$

WOULD YOU LIKE TO SCHEDULE YOUR NEXT
SERVICE APPOINTMENT?

YES NO

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

X

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	147.00
PARTS AMOUNT	319.08
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	466.08
DISCOUNT	0.00
SALES TAX	19.14
PLEASE PAY THIS AMOUNT	485.22

