


INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

 <p align="center">DOT Auto Safety Hotline</p> <p align="center">Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET:www.nhtsa.dot.gov/hotline</p>		FOR AGENCY USE ONLY 100148	
U.S. Department of Transportation National Highway Traffic Safety Administration		Date Received JAN 13 2016 06-NOV-2015	Repository <input type="checkbox"/> Reference No. 10788779
OWNER INFORMATION (Type or Print)			
Name	[REDACTED]		Daytime Telephone Number
Address	[REDACTED]		E-mail Address
City	NEW CASTLE	State	PA
		Zip Code	[REDACTED]
Evening Telephone Number			
The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).			
VEHICLE INFORMATION			
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side	Make	Model	Model Year
2T1BR32E26C [REDACTED]	TOYOTA	COROLLA	2006
Date Purchased	Dealer's Name and Telephone Number	Engine:	Fuel Type:
		No: Cylinders	
Original Owner <input type="checkbox"/>	Dealer's City	State	Zip Code
Transmission Type	<input type="checkbox"/> Antilock Brakes	Powertrain	Multiple Failure:
	<input type="checkbox"/> Cruise Control		Incident Date(s) 01-JUN-2015
FAILED COMPONENT(S)/PART(S) INFORMATION			
Vehicle Component Code: 140000 AIR BAGS		Failure Mileage	Failure Speed
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE			
Tire Make	Tire Model (Name or Number)	Tire Size (Example P215/65R15)	
DOT No. (Example: DOTM19ABC036)	<input type="checkbox"/> Original Equipment <input type="checkbox"/> Prior Repair	Failure Location:	
Tire Component Code	Tire Failure Type:		
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE			
Make:	Date Manufactured:	Model No./Name:	
Seat Type:	Installation System:		
Child Seat Component Code:	Failed Part:		
APPLICABLE INCIDENT INFORMATION <i>(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)</i>			
Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured	Number of Deaths
		Reported to Police N	
Narrative Description of Incident(S), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e, parts repaired or replaced (and if old part is available).			
TL* THE CONTACT OWNS A 2006 TOYOTA COROLLA. THE CONTACT STATED THAT THE RECALL NOTICE FOR NHTSA CAMPAIGN NUMBER: 15V285000 (AIR BAGS) WAS RECEIVED IN JUNE OF 2015. AFTER CONTACTING THE DEALER AND THE MANUFACTURER ON MULTIPLE OCCASIONS, THE CONTACT WAS INFORMED THAT THE PARTS NEEDED TO REPAIR THE VEHICLE WERE STILL NOT AVAILABLE AND NO ESTIMATED TIME FOR RECEIVING THE PARTS COULD BE GIVEN. THE CONTACT HAD NOT EXPERIENCED A FAILURE.			
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY			
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.			

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

INCONVENIENCE OF HAVING NO ONE SIT IN THE FRONT SEAT OF CAR IS UNACCEPTABLE FOR SUCH A LONG PERIOD OF TIME.

ATTACH ADDITIONAL SHEETS IF NECESSARY


U.S. Department of Transportation

National Highway Traffic Safety Administration

1200 New Jersey Avenue SE. Washington, D.C. 20077-9382

Official Business Penalty for Private Use \$300

PITTSBURGH PA 150 22 DEC '15 PM 6 L



NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES




BUSINESS REPLY MAIL FIRST-CLASS MAIL PERMIT NO. 1888 WASHINGTON, DC POSTAGE WILL BE PAID BY ADDRESSEE

US Department of Transportation National Highway Traffic Safety Administration Office of Defects Investigation, NVS-210 NEF-100 1200 New Jersey Avenue SE. Washington, D.C. 20077-9382



Think your vehicle has a safety defect?



If so: Use the enclosed form to file a report.

or visit: www.safercar.gov

or call: Vehicle Safety Hotline 888-327-4236



Vehicle Owner's Questionnaire (VOQ) U.S. Department of Transportation National Highway Traffic Safety Administration



CA *TX* *CA* [Redacted]

Toyota Motor Sales, U.S.A., Inc.
19001 South Western Avenue
P.O. Box 2991
Torrance, CA 90509-2991

2006 Corolla



[Redacted]
NEW CASTLE, PA [Redacted]

T67 P3



1-800-331-4331

**2003–2007 Model Year Corolla, Corolla Matrix,
2003–2006 Model Year Tundra, and
2002–2007 Model Year Sequoia Vehicles
Front Passenger Airbag Inflator Module
SAFETY RECALL NOTICE (Interim Notice)**

This notice applies to your vehicle: VIN 2T1BR32E260 [Redacted]

Dear Toyota Owner:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Toyota has decided that a defect, which relates to motor vehicle safety, exists in certain 2003–2007 model year Corolla and Corolla Matrix, 2003–2006 model year Tundra, and 2002–2007 model year Sequoia vehicles.

You received this notice because our records, which are based primarily on state registration and title data, indicate that you are the current owner.

What is the condition?

The subject vehicles are equipped with front passenger air bag inflators which may have been manufactured in such a way as to have a potential for the intrusion of moisture over time. Depending on the circumstances, this could create excessive internal pressure when the air bag is deployed and cause the inflator to rupture. In the event of an inflator rupture, metal fragments could pass through the air bag cushion material, striking the vehicle occupants potentially resulting in serious injury or death.

What will Toyota do?

Toyota is currently prioritizing part replacement in geographic locations that are subject to consistently high absolute humidity. Due to limited parts availability, the remedy will be launched in phases based on vehicle registration location. We are currently preparing parts for your location; we will send you another notification once sufficient parts have been produced and the remedy can be performed.

Until the remedy becomes available in your location, we recommend that you do not operate the vehicle with an occupant in the front passenger seat. We sincerely apologize for any inconvenience this will cause, but we are taking this action to ensure your safety.

Spanish translation on back side
Traducción en español en el lado inverso