

Oct 20, 2015

10/20/2015

INFORMATION Redacted PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)



Atascadero CA

Save the Redwoods League

OCT 27 2015

TO Whom Ever,
Outrageous! I want my Tundra Air
bag recall work done now.

How can I take trips or use
my vehicle when I am told
not to use the passenger seat,
do my wife sits in the back
seat? !!!

I sense that should a problem
occur - in air bag deploys - you
would say (in court) that its
my fault for using the front
passenger seat - and Tough
luck Mr. [redacted]

fix the problem - now

[redacted]

{
Copy to FA
Copy to NHTSA
Copy to Toyota Corp
Tammela

NM
11/21/15
SMD

Tundra 2005

R 8/10/2015



Do not sit in front
Passenger seat till
problem is fixed

111
000

TO SUG DEEMBER 9-2
REPLACEMENT PART
STILL NOT AVAILABLE

Toyota Motor Sales, U.S.A., Inc.
19001 South Western Avenue
P.O. Box 2991
Torrance, CA 90509-2991

BA letter
10/21/2015



T247 P6

ATASCADERO, CA



2003-2007 Model Year Corolla, Corolla Matrix,
2003-2006 Model Year Tundra, and
2002-2007 Model Year Sequoia Vehicles
Front Passenger Airbag Inflator Module
SAFETY RECALL NOTICE (Interim Notice)

This notice applies to your vehicle: VIN 5TBDT44165S

Dear Toyota Owner:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Toyota has decided that a defect, which relates to motor vehicle safety, exists in certain 2003-2007 model year Corolla and Corolla Matrix, 2003-2006 model year Tundra, and 2002-2007 model year Sequoia vehicles.

You received this notice because our records, which are based primarily on state registration and title data, indicate that you are the current owner.

What is the condition?

The subject vehicles are equipped with front passenger air bag inflators which may have been manufactured in such a way as to have a potential for the intrusion of moisture over time. Depending on the circumstances, this could create excessive internal pressure when the air bag is deployed and cause the inflator to rupture. In the event of an inflator rupture, metal fragments could pass through the air bag cushion material, striking the vehicle occupants potentially resulting in serious injury or death.

What will Toyota do?

Toyota is currently prioritizing part replacement in geographic locations that are subject to consistently high absolute humidity. Due to limited parts availability, the remedy will be launched in phases based on vehicle registration location. We are currently preparing parts for your location; we will send you another notification once sufficient parts have been produced and the remedy can be performed.


What should you do?

Until the remedy becomes available in your location, we recommend that you do not operate the vehicle with an occupant in the front passenger seat. We sincerely apologize for any inconvenience this will cause, but we are taking this action to ensure your safety.

Spanish translation on back side
Traducción en español en el lado inverso

Atascadero CA

SANTA BARBARA
CA 931
21 OCT 2015 PM 2 E



Administrators
Nat. Highway Traffic Safety
1200 New Jersey Ave SE
Washington DC
20590

