

INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

CL-10838299-8904

gpm
Re Call 4350 JAN 19 2013
Unintended
ignition Key Rotation

I needed to replace
ignition pin
due to this defect.

I would like
reimbursement
for my problem
and inconvenience

[REDACTED]

NAM
1/20/13
SMD

Rome, NY

Y GARAGE TIRE & AUTO
206 CHAMPLIN AVE
YORKVILLE, NY 12502
315-797-5110

Ext 101 50010/500
17 0000

ORISKANY GARAGE TIRE, INC.
P.O. BOX 47 1206 CHAMPLIN AVE
YORKVILLE NY 13495
315-797-5110
4330670

Sale

page 1

Entry Method: Swiped

Approved: Online Batch#: 000001

08/21/13 17:04:54

Inv#: [REDACTED] Appr Code: 021998 Intrigue 3.5 L 214 CID V6 DOHC 24 Valve

Total:

\$

01:19 AM

Repair Order [REDACTED]

Day Phone
Eve Phone
Cell Number
Fax Number

Color : Red
Last Mileage : 116202
Odometer In : 117412
Odometer Out : 0

Customer

THANK
FOR

Description

CUSTOMER REQUEST

Unit Price

\$0.00

Price

\$0.00

PLEASE CHECK THE FOLLOWING:

WHEELS TORQUED TO MANUFACTURERS SPECS

TOWED IN ADIRONDACK

WON'T START

PASS LOCK??

BRAKE LIGHT AND SECUITY LIGHT ON

Parts

Qty	Code/Tech*	Description	Condition	Unit Price	Price
1		SUBLET SACCO'S		\$265.00	\$265.00

REPLACE IGNITION SWITCH AND REKEY

Sublet/Misc.

Qty	Code/Tech*	Description	Unit Price	Price
1		TOWED IN RON'S	\$100.00	\$100.00

Labor		\$0.00
Parts		\$265.00
Sublet/Misc.		\$100.00
Enviromental Charge		\$0.00
Charges		\$0.00
Sales Tax	Tax @ \$365.00 * 8.7500%	\$31.94
	Repair Total	\$396.94

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANICS LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL. STORAGE CHARGE OF \$25.00 DOLLARS PER DAY WILL BE ASSESSED AFTER NOTIFICATION OF COMPLETION OF REPAIR(S).

AUTHORIZED BY: _____ DATE: _____



SACCO'S LOCKSMITH CO., INC.

1000 Oriskany St. W.
UTICA, NEW YORK 13502
(315) 732-0301

CUSTOMER'S ORDER NO.		PHONE		DATE 08/21/13		
[REDACTED]						
YORKVILLE NY						
PAID BY	CASH	C.O.D.	CHARGE	ON ACCT.	MOISE. RET'D.	PAID OUT
TY.	DESCRIPTION				PRICE	AMOUNT
	SERVISE CALL TO YORKVILLE					
	NEW GM 703652 VANDERBILT					
	REKEY (10 SAMPLE KEYS)					
	WORK DONE ON 1. 2002					
	VIA MOBILE IN-RIDE					
	PD CK # [REDACTED]					
	08/21/13					
	LABOR					
Due and Payable Upon Receipt Interest At 1 1/2% Per Month After 30 Days					TAX	265 —
					TOTAL	265 —

CT 610

All claims and returned goods must be accompanied by this bill.

Thank You

Rome, NY [REDACTED]

Dear [REDACTED]

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect which relates to motor vehicle safety exists in your 2002 model year Oldsmobile Intrigue. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

- This notice applies to your 2002 model year Oldsmobile Intrigue, VIN 1G3WS52H82F [REDACTED]
- Your vehicle is involved in GM recall 14350.
- **Until the recall has been performed, it is very important that you remove all items from your key ring, leaving only the vehicle key. The key fob (if applicable), should also be removed from the key ring.**
- Schedule an appointment with your GM dealer on or after October 1, 2014.
- The recall repairs will be performed for you at **no charge**.


Why is your vehicle being recalled?

If the key ring is carrying added weight and the vehicle goes off road or experiences some other jarring event, it may unintentionally move the key away from the "run" position. If this occurs, engine power, power steering and power braking may be affected, increasing the risk of a crash. If the ignition switch is not in the run position, the air bags may not deploy if the vehicle is involved in a crash, increasing the risk of injury or fatality.


...the bags are connected to the key like two links of a chain to reduce the risk of unintentionally moving the key out of the RUN position. Do not add any additional items to the ring attached to the ignition key. Attach additional items only to the second ring, and limit added items to a few essential keys: small, light items no larger than a RKE transmitter.



General Motors LLC. All Rights Reserved.



Rome Ny



SYRACUSE NY 130

04 JAN 2016 PM 3 L



Administrata National Highway
Safety Admin
1200 New Jersey Ave SE
Washington DC 20590

20590

