

INFORMATION Redacted PURSUANT TO THE FREEDOM OF

 U.S. Department of Transportation National Highway Traffic Safety Administration		INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6) DOT Auto Safety Hotline Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline		FOR AGENCY USE ONLY 100148 Date Received 02-MAR-2016 APR 19 2016		Repository ☐ Reference No. 10839371	
OWNER INFORMATION (Type or Print)							
Name		[REDACTED]		Daytime Telephone Number		E-mail Address	
Address		[REDACTED]		[REDACTED]		[REDACTED]	
City MALVERN		State PA		Zip Code [REDACTED]		Evening Telephone Number	
The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).							
VEHICLE INFORMATION							
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side 2G1WX15K119 [REDACTED]				Make CHEVROLET		Model MONTE CARLO	
				Model Year 2001			
Date Purchased 08-29-00		Dealer's Name and Telephone Number Kelly Chev 610-933-7707				Engine: No: Cylinders 6	
Original Owner ☒		Dealer's City Phoenixville		State Pa.		Zip Code 19380	
Transmission Type Auto Matic		☒ Antilock Brakes		Powertrain 3 speed Auto. Matic		Incident Date(s) 22-FEB-2016	
☒ Cruise Control				Multiple Failure:			
FAILED COMPONENT(S)/PART(S) INFORMATION							
Vehicle Component Code: ENGINE (PWS) 3800 Series II V-6 Code - K				Failure Mileage 40000		Failure Speed	
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE							
Tire Make		Tire Model (Name or Number)			Tire Size (Example P215/65R15)		
DOT No. (Example: DOTM19ABC036)		☐ Original Equipment ☐ Prior Repair		Failure Location:			
Tire Component Code				Tire Failure Type:			
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE							
Make:		Date Manufactured:		Model No./Name:			
Seat Type:		Installation System:					
Child Seat Component Code:		Failed Part:					
APPLICABLE INCIDENT INFORMATION							
(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)							
Crash ☐ Yes ☒ No		Fire ☐ Yes ☒ No		Number of Persons Injured		Number of Deaths	
						Reported to Police N	
Narrative Description of Incident(S), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).							
TL* THE CONTACT OWNS A 2001 CHEVROLET MONTE CARLO. THE CONTACT STATED THAT THE REAR VALVE COVER GASKET LEAKED ONTO THE INTAKE MANIFOLD. THE VEHICLE WAS NOT DIAGNOSED NOR REPAIRED. THE VEHICLE WAS INCLUDED IN NHTSA CAMPAIGN NUMBER: 15V701000 (ENGINE AND ENGINE COOLING). THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 40,000.							
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY							
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response,							

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

I don't understand why they, only fix one valve cover gasket, they are the same, one gasket
from all, G.M. will fix one valve cover, not the another one, my back valve cover leaked not
the front one if it leaked I could not see no oil, I think only reason they will pay to fix
front valve cover is because the oil leaked onto the ~~front~~ manifold & it is very
hot, very hot & then starts a fire & the back valve cover leaked onto its intake manifold
that don't get that hot & won't start a fire.

The fix is only half !@#\$. fix it right the first time,

ATTACH ADDITIONAL SHEETS IF NECESSARY

U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

1200 New Jersey Avenue SE.
Washington, D.C. 20077-9382

Official Business
Penalty for Private Use \$300

WILMINGTON DE 197

31 MAR 2016 PM 2 T

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

BUSINESS REPLY MAIL

FIRST CLASS MAIL

PERMIT NO. 1888

WASHINGTON, DC

POSTAGE WILL BE PAID BY ADDRESSEE

**US Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation, NEF-100
1200 New Jersey Avenue SE.
Washington, D.C. 20077-9382**



**Think your vehicle
has a safety defect?**



**If so:
Use the enclosed
form to file a report.**

or visit:

www.safercar.gov

or call:

**Vehicle Safety Hotline
888-327-4236**



Vehicle Owner's Questionnaire (VOQ)
U.S. Department of Transportation
National Highway Traffic Safety Administration

