

CL- 1085 3666- 6275

Administrator of the National Highway Traffic Safety Administration,
1200 New Jersey Ave.,SE.,Washinton, DC20590.

Sir,

sub: Safety Recall - DRIVER AIR BAG INFLATOR REPAIR
NHTSA Campaign No. 15V-345 & 15V-382
VIN 1YVHP80C975 [REDACTED]

MAR 23 2016

With regarding to the re-call notice letter dtd.July 2015. I would like to inform you that several times I contacted my vehicle dealer MUNDAY MAZDA,FM 1960,HOUSTON,TX every time when I contacted - the reply from them is We do not have the parts. You will get a new letter very soon then you bring the car. eight months already over till date I have not get any letter or any other communication from the dealer.

Last week I hv got another re-call notice letter saying that PASSENGER AIR BAG INFLATOR REPLACEMENT NHTSA campaign No.15V-869 for the same my vehicle. Now I surprise-

From where I am going to get a new letter ?

Where I should contact ?

How long I have to wait ?

If anything happen who is going to take responsibility ?

I am awaiting a responsible action from your end to get it rectify both above mentioned air bag inflator replacment.

Thanks
03-07-16

[REDACTED]
[REDACTED] SPRING TX [REDACTED]

E-mail
[REDACTED]

DM
33116
H



IMPORTANT SAFETY RECALL

Driver Air Bag Inflator Interim Repair - Safety Recall 7914J NHTSA Campaign No. 15V-345 & 15V-382

July 2015

This notice applies to your vehicle, VIN 1YVHP80C975 [REDACTED]

Dear Mazda Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Mazda Motor Corporation has decided that a defect which relates to motor vehicle safety exists in 2004-2008 RX-8, 2003-2008 Mazda6, and 2006-2007 Mazdaspeed6 vehicles.

If you are a recipient of this notice, your vehicle is included in this Safety Recall.

What is the problem?

In the subject vehicles, continued exposure to high levels of absolute humidity may cause the driver's front air bag inflator housing to build up excessive internal pressure over time. In the event of a crash necessitating deployment of the driver's side frontal air bag, the inflator could rupture, resulting in metal fragments striking the driver or other vehicle occupants, resulting in serious injury or death.

What will Mazda do?

If your vehicle has not already received the interim repair, your Mazda dealer will replace the driver air bag inflator with a new one free of charge. ~~This is an interim repair. The interim inflators contain new propellant materials that have not been exposed to high absolute humidity, believed to be a cause of abnormal air bag deployment. The repair should take less than one hour to complete; however, it may take longer depending on the service workload at your Mazda dealership.~~

Mazda is working with our suppliers to manufacture a new design of inflator that will be used as a permanent remedy. We expect that the permanent remedy parts may be available later this year. At that time Mazda will launch Safety Recall 8215F for the permanent repair and install the newly designed inflator on your vehicle. **Until then, if you have not already done so, please bring your vehicle to your Mazda dealership for the interim replacement part to prevent the risk of a rupture or abnormal airbag deployment. It is important that you have both the interim and permanent repair performed on your vehicle.**

Mazda North American Operations
Technical Services Division
1444 McGaw Ave.
Irvine, CA 92614-5570
www.MazdaUSA.com

zoom-zoom



IMPORTANT SAFETY RECALL

Safety Recall 9015L

**2003-2008 Mazda6 and 2006-2007 Mazdaspeed6 - Passenger Air Bag Inflator Replacement
NHTSA Campaign No. 15V-869**

February 2016

This notice applies to your vehicle, VIN 1YVHP80C975 [REDACTED]

Dear Mazda Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Mazda Motor Corporation has decided that a defect which relates to motor vehicle safety exists in 2003-2008 Mazda6 and 2006-2007 Mazdaspeed6 vehicles.

If you are a recipient of this notice, your vehicle is included in this Safety Recall.

What is the problem?


In the subject vehicles, continued exposure to high levels of absolute humidity may cause the passenger frontal air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the passenger frontal air bag. An inflator rupture could result in metal fragments striking the driver or other vehicle occupants, resulting in serious injury or death.

What will Mazda do?

Your Mazda dealer will replace the passenger frontal air bag inflator with a new one, free of charge. The repair should take less than one hour to complete; however, it may take longer depending on the service workload at your Mazda dealership.


What should you do?

Mazda is concerned about your safety, and we encourage you to make an appointment with any authorized Mazda dealer to have the airbag inflator replaced as soon as possible. Making an appointment provides the dealer the opportunity to reserve the necessary part for your repair and plan their service activity, thus minimizing your wait time and inconvenience this recall may cause you. You do not need to bring this notice to the dealer, but it may assist in the check-in process.



NORTH HOUSTON TX 773

09 MAR 2016 PM 2 L



To

ADMINISTRATOR OF THE NATIONAL
HIGHWAY TRAFFIC SAFETY ADMINISTRATION
1200 NEW JERSEY AVE. S.E.,
WASHINGTON, DC 20590

20590

