

OF INFORMATION ACT (FOIA), 5 U.S.C.552(B)(6)

From: [DataQuality, DataQuality \(NHTSA\)](#)
To: [EVOQ \(NHTSA\)](#)
Subject: FW: Takata airbag recall Follow up to ODI Complaint ----- 11338152-----
Date: Monday, July 27, 2020 4:16:23 PM
Attachments: [REDACTED]

From: [REDACTED]
Sent: Friday, July 24, 2020 3:46 PM
To: DataQuality, DataQuality (NHTSA) <DataQuality@dot.gov>
Subject: Takata airbag recall Follow up to ODI Complaint ----- 11338152-----

CAUTION: This email originated from outside of the Department of Transportation (DOT). Do not click on links or open attachments unless you recognize the sender and know the content is safe.

Good day,

Per your request please see attached email. I look forward to your response.

Best Regards,

Sent from my iPhone

Begin forwarded message:

From: "EVOQ (NHTSA)" <EVOQ@dot.gov>
Date: July 24, 2020 at 1:17:36 PM EDT
To: [REDACTED]
Subject: FW: Follow up to ODI Complaint ----- 11338152-----

Please see the attached copy of your recent complaint and instructions. Please make any necessary edits and return via email to dataquality@dot.gov or fax to (202) 366-1767. Due to the volume of complaints we receive and our limited resources, we cannot respond to every complaint.
NHTSA/Office of Defects Investigation



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

08-JUL-2020

Repository ☐

Reference No.
11338152

OWNER INFORMATION (Type or Print)

Name [REDACTED]

Address [REDACTED]

City UPPER MARBORO

State MD

Zip Code [REDACTED]

Daytime Telephone Number [REDACTED]

E-mail Address [REDACTED]

Evening Telephone Number [REDACTED]

The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side
1GKFK13077J [REDACTED]

Make
GMC

Model
YUKON

Model Year
2007

Date Purchased

Dealer's Name and Telephone Number

Engine:

No: Cylinders

Fuel Type:

Original Owner
☐

Dealer's City

State

Zip Code

Transmission Type

☐ Antilock Brakes

Powertrain

Multiple Failure:

Incident Date(s)

☐ Cruise Control

08-JUL-2020

FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Code: 140000 AIR BAGS

Failure Mileage
160000

Failure Speed

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM9ABC036)

☐ Original Equipment
☐ Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type:

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash

☐ Yes ☒ No

Fire

☐ Yes ☒ No

Number of Persons Injured

Number of Deaths

Reported to Police

N

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

TL* TAKATA RECALL. THE CONTACT OWNS A 2007 GMC YUKON. AFTER PERFORMING A VIN SEARCH, IT WAS DISCOVERED THAT THE VEHICLE WAS INCLUDED IN NHTSA CAMPAIGN NUMBER 16V383000 (AIR BAGS). AFTER CONTACTING THE DEALER OURISMAN CHEVROLET LOCATED AT 16610 GOVERNOR BRIDGE RD, BOWIE, MD 20716 AND THE MANUFACTURER, THE CONTACT WAS INFORMED THAT THE PARTS NEEDED FOR THE RECALL REPAIR WERE STILL NOT AVAILABLE AND NO ESTIMATED TIME FOR RECEIVING THE PARTS COULD BE PROVIDED. THE CONTACT INDICATED THAT WHILE OPERATING THE VEHICLE, THE AIR BAGS WARNING LIGHT REMAINED ILLUMINATED. THE CAUSE OF THE FAILURE WAS NOT DETERMINED. VIN TOOL CONFIRMS PARTS NOT AVAILABLE. THE FAILURE MILEAGE WAS 160,000.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.