

OF INFORMATION ACT (FOIA), 5 U.S.C.552(B)(6)

From: [DataQuality, DataQuality \(NHTSA\)](#)
To: [EVOQ \(NHTSA\)](#)
Subject: FW: ODI Complaint additional information
Date: Monday, September 14, 2020 10:05:28 AM

From: [REDACTED]
Sent: Friday, September 11, 2020 9:20 AM
To: DataQuality, DataQuality (NHTSA) <DataQuality@dot.gov>
Subject: ODI Complaint additional information

CAUTION: This email originated from outside of the Department of Transportation (DOT). Do not click on links or open attachments unless you recognize the sender and know the content is safe.

Hello,

I've made corrections to the document in the space provided at the end of the document.

I've provided the manufacturer number for my complaint with them and the diagnostic reason for failure due to recalled fuel pump. And my mileage was 29925.

The original dealer is Fox Subaru in Grand Rapids Michigan and we purchased the 2019 Outback in February 2019. The Outback is a wagon model, 3.6R limited with a V-6 engine.

Please let me know if there is any more information needed.

[REDACTED]

U.S. Department of Transportation National Highway Traffic Safety Administration	DOT Auto Safety Hotline Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET:www.nhtsa.dot.gov/hotline			FOR AGENCY USE ONLY 100148	
	Date Received 20-JUL-2020		Repository <input type="checkbox"/> Reference No. 11340309		
OWNER INFORMATION (Type or Print)					
Name		Address		Daytime Telephone Number	
City		State		Evening Telephone Number	
PENTWATER		MI		[REDACTED]	
The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).					
VEHICLE INFORMATION					
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side		Make		Model	
4S4BSENC0K3 [REDACTED]		SUBARU		OUTBACK	
Date Purchased		Dealer's Name and Telephone Number		Engine: No: Cylinders	
Original Owner <input type="checkbox"/>		Dealer's City		Fuel Type:	
State		Zip Code			
Transmission Type		Powertrain		Multiple Failure:	
<input type="checkbox"/> Antilock Brakes <input type="checkbox"/> Cruise Control				Incident Date(s) 19-JUL-2020	
FAILED COMPONENT(S)/PART(S) INFORMATION					
Vehicle Component Codes: 070000 FUEL SYSTEM, GASOLINE, 074000 FUEL/PROPULSION SYSTEM (PWS), 060000 ENGINE (PWS)				Failure Mileage	
				29000	
				Failure Speed	
				55	
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE					
Tire Make		Tire Model (Name or Number)		Tire Size (Example P215/65R15)	
DOT No. (Example: DOTMAL9ABC036)		<input type="checkbox"/> Original Equipment <input type="checkbox"/> Prior Repair		Failure Location:	
Tire Component Code				Tire Failure Type:	
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE					
Make:		Date Manufactured:		Model No./Name:	
Seat Type:		Installation System:			
Child Seat Component Code:		Failed Part:			
APPLICABLE INCIDENT INFORMATION (Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)					
Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Number of Persons Injured	
				Number of Deaths	
				Reported to Police	
				N	
Narrative Description of Incident(S), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).					
TL* THE CONTACT OWNS A 2019 SUBARU OUTBACK. THE CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 55 MPH, THE VEHICLE STALLED WITHOUT WARNING WITH THE ACCELERATOR PEDAL DEPRESSED. THE VEHICLE FAILED TO RESTART AND WAS TOWED TO SERRA SUBARU OF TRAVERS CITY LOCATED AT 1747 S. GARFIELD AVE, TRAVERSE CITY, MI 49686. THE CAUSE OF THE FAILURE WAS NOT YET DETERMINED. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 29,000.					
Manufacturer (Subaru) was notified SR# [REDACTED] Cause of failure was a faulty fuel pump component WRD20 Mileage 29925					
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY.					
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.					