

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C.552(B)(6)

| | | | |
|--|--|---|--------------------------------|
| National Highway Traffic Safety Administration 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline | | FOR AGENCY USE ONLY 100148 Date Received: 28-OCT-2020 Repository: <input type="checkbox"/> Reference No.: 11366905 | |
| OWNER INFORMATION (Type or Print) | | | |
| Name: [REDACTED] | | Daytime Telephone Number: [REDACTED] | |
| Address: [REDACTED] | | E-mail Address: [REDACTED] | |
| City: SOUTH JORDON | State: UT | ZIP Code: [REDACTED] | Evening Telephone Number: Same |
| The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004). | | | |
| VEHICLE INFORMATION | | | |
| 17 digit Vehicle Identification Number Located at bottom of windshield on driver's side: SFNRL5H94EB [REDACTED] | | MAKE: HONDA | Model: ODYSSEY |
| Date Purchased: FEB 2016 | Dealer's Name and Telephone Number: ? | Engine No: Cylinders: 6 | Model Year: 2014 |
| Original Owner: <input type="checkbox"/> | Dealer's City: ? | STATE: UT | ZIP Code: ? |
| Transmission Type: <input checked="" type="checkbox"/> Antilock Brakes | Powertrain: <input checked="" type="checkbox"/> Cruise Control | Multiple Failure: | Fuel Type: UNLEADED |
| | | Incident Date(s): 20-OCT-2020 | |
| FAILED COMPONENT(S)/PART(S) INFORMATION | | | |
| Vehicle Components Codes: 220000 SEATS | | Failure Mileage: 70000.0 | Failure Speed: 0 |
| 2ND ROW REAR PASSENGER SEAT (HONDA ROW) | | | |
| ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE | | | |
| Tire Make: | Tire Model (Name or Number): | Tire Size (Example P215/65R15): | |
| DOT No. (Example: DOTM19ABC036): | <input type="checkbox"/> Original Requirement <input type="checkbox"/> Prior Repair | Failure Location: | |
| Tire Component Code: | Tire Failure Type: | | |
| ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE | | | |
| Make: | Date Manufactured: | Model No./Name: | |
| Seat Type: | Installation System: | | |
| Child Seat Component Code: | Failed Part: | | |
| APPLICABLE INCIDENT INFORMATION <i>(Please describe in detail the Incident(s), Failure(s), Crash(es), Injury(ies).)</i> | | | |
| Crash: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Fire: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Number of Persons Injured: 0 | Number of Deaths: 0 |
| | | Reported to Police: N | |
| Narrative Description of Incident(s), Crash(es), Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available). | | | |
| TL-THE CONTACT OWNS A 2014 HONDA ODYSSEY. THE CONTACT STATED THAT THE 2 SECOND ROW SEAT ON THE PASSENGER SIDE FAILED TO LATCH. THE DEALER STOCK ON 12 HONDA 10860 S AUTO MALL DR, SANDY, UT 84070 (801) 981-4920 WAS CONTACTED AND INFORMED THE CONTACT THAT THE PASSENGER SEAT WAS NOT RECALLED AND THAT NO RECALLS FOR THE PASSENGER SEAT WAS UNDER THE VIN. THE VEHICLE WAS TAKEN TO AN INDEPENDENT MECHANIC WHERE IT WAS INSPECTED HOWEVER NOT REPAIRED. THE CONTACT MENTIONED NHTSA CAMPAIGN NUMBER: 16V933000 (SEATS) NHTSA CAMPAIGN NUMBER: 17V725000 (SEATS) AS A POSSIBLE SOLUTION TO THE FAILURE HOWEVER THE VIN WAS NOT PROVIDED TO CONFIRM INFORMATION. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS APPROXIMATELY 70,000. CK | | | |