


OF INFORMATION ACT (FOIA), 5 U.S.C.552(B)(6)

From: [DataQuality, DataQuality \(NHTSA\)](#)
To: [EVOQ \(NHTSA\)](#)
Subject: FW: NHTSA/Office of Defects Investigation
Date: Monday, March 14, 2022 8:32:54 AM
Attachments: [REDACTED]

From: [REDACTED]
Sent: Saturday, March 12, 2022 9:47 AM
To: DataQuality, DataQuality (NHTSA) <DataQuality@dot.gov>
Cc: [REDACTED]
Subject: NHTSA/Office of Defects Investigation

CAUTION: This email originated from outside of the Department of Transportation (DOT). Do not click on links or open attachments unless you recognize the sender and know the content is safe.

[Sent from Yahoo Mail for iPhone](#)

 DOT Auto Safety Hotline Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET:www.nhtsa.dot.gov/hotline				FOR AGENCY USE ONLY 100148	
U.S. Department of Transportation National Highway Traffic Safety Administration		Date Received 20-DEC-2021		Repository <input type="checkbox"/> Reference No. 11444461	
OWNER INFORMATION (Type or Print)					
Name		Address		Daytime Telephone Number	
City		State		Evening Telephone Number	
Hendersonville		TN			
ZIP Code					
<i>The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).</i>					
VEHICLE INFORMATION					
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side 1hgcv3f54ka		MAKE HONDA		Model ACCORD	
Date Purchased		Dealer's Name and Telephone Number Gallatin Honda (615) 461- 615-461-2000		Model Year 2019	
Original Owner <input checked="" type="checkbox"/>		Dealer's City Gallatin		Engine: No. Cylinders	
STATE TN		ZIP Code 37066		Fuel Type:	
Transmission Type <input type="checkbox"/> Antilock Brakes <input type="checkbox"/> Cruise Control		Powertrain		Multiple Failure:	
				Incident Date(s) 15-OCT-2021	
FAILED COMPONENT(S)/PART(S) INFORMATION					
Vehicle Components Codes: 100000 POWER TRAIN			Failure Mileage 16504.0		Failure Speed Approx. 10 miles/hr
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE					
Tire Make		Tire Model (Name or Number)		Tire Size (Example P215/65R15)	
DOT No. (Example: DOTM1 9ABC036)		<input type="checkbox"/> Original Requirement <input type="checkbox"/> Prior Repair		Failure Location:	
Tire Component Code		Tire Failure Type:			
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE					
Make:		Date Manufactured:		Model No./Name:	
Seat Type:		Installation System:			
Child Seat Component Code:		Failed Part:			
APPLICABLE INCIDENT INFORMATION (Please describe in detail the incident(s), failure(s), crash(es), injury(ies).)					
Crash <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Number of Persons Injured	
				Number of Deaths	
				Reported to Police Y	
Narrative Description of Incident(s), Crash(es), Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).					
The contact owns a 2019 Honda Accord. The contact stated when attempting to park, the vehicle accelerated on its own and hit the vehicle in front of them causing damage to their front driver side headlight and the grill was caved in. The contact had to depress on the brake pedal and hit the ignition switch for the vehicle to stop accelerating. No warning light's illuminated on the vehicle. The air bags did not deploy. No one was injured. A police report was filed. The vehicle was towed to an auto body shop that repaired the physical damage to the vehicle. The vehicle was taken to a local dealer who inspected the vehicle but could not diagnose the cause of the failure. The vehicle was not repaired, however, the contact concern was that failure could reoccur. The manufacturer was made aware of the failure. The failure mileage was approximately 16,504.					
ATTACH ADDITIONAL SHEETS IF NECESSARY					
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.					
The Privacy Act of 1974-Public Law 93-579. This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.					