

OF INFORMATION ACT (FOIA), 5 U.S.C.552(B)(6)

From: EVOQ (NHTSA) EVOQ@dot.gov  
 Subject: FW: Follow up to ODI Complaint ----- 11460475-----  
 Date: Jul 21, 2022 at 9:25:42 AM  
 To: [REDACTED]

Please see the attached copy of your recent complaint and instructions. Please make any necessary edits and return via email to [dataquality@dot.gov](mailto:dataquality@dot.gov) or fax to (202) 366-1767. Due to the volume of complaints we receive and our limited resources, we cannot respond to every complaint.  
 NHTSA/Office of Defects Investigation

Form Approved: O.M.B. No. 2127-0005

<b>DOT Auto Safety Hotline</b> <b>Vehicle Owner's Questionnaire</b> To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: <a href="http://www.nhtsa.dot.gov/hotline">www.nhtsa.dot.gov/hotline</a>		FOR AGENCY USE ONLY 100148	
		Date Received 12-APR-2022	Repository <input type="checkbox"/>
		Reference No. 11460475	
<b>OWNER INFORMATION (Type or Print)</b>			
Name [REDACTED]		Daytime Telephone Number [REDACTED]	
Address [REDACTED]		E-mail Address [REDACTED]	
City [REDACTED]	State [REDACTED]	ZIP Code [REDACTED]	Function [REDACTED]
The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See #9 FM 58071 (Rev. 8, 2004).			
<b>VEHICLE INFORMATION</b>			
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side 1FDXE4F50D [REDACTED] 1FDXE4F5XJD [REDACTED]			
Data Purchased 09/06/2019		Dealer's Name and Telephone Number NELSON'S RV'S 208-322-4121	
Original Owner <input checked="" type="checkbox"/>		Engine, No. Cylinders 10	
Dealer's City/State BOISE ID		ZIP Code 83714	
Transmission Type AUTOMATIC		Fuel Type REGULAR FUEL 87% OCTANE	
<input type="checkbox"/> Anti-Lock Brakes		<input checked="" type="checkbox"/> Cruise Control	
<input type="checkbox"/> Powertrain		<input type="checkbox"/> Multiple Failures	
		Incident Date(s) 04-APR-2022	
<b>FAILED COMPONENT(S)/PART(S) INFORMATION</b>			
Vehicle Component Code: 160000 STRUCTURE		Failure Mileage 16,115	
		Failure Speed UNKNOWN	
<b>ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE</b>			
Tire Make	Tire Model (Name or Number)	Tire Size (Example #215/65R19)	
DOT No. (Example, DOTM1 3ABC35)	<input type="checkbox"/> Original Requirement <input type="checkbox"/> Prior Repair	Failure Location	
Tire Component Code		Tire Failure Type	
<b>ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE</b>			
Make	Date Manufactured	Model No./Name	
Seat Type		Installation System	
Child Seat Component Code		Failed Part	
<b>APPLICABLE INCIDENT INFORMATION</b>			
(Please describe in detail the incident(s) following: Crashing (injury(s))			
Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Injury <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured	Number of Deaths
		Reported to Police N	
Narrative Description of Incident(s), Crash(es), Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure. (i.e. parts repaired or replaced (and if old part is available)).			
The contact owns a 2019 Forest River Sunseeker RV. The contact stated that while the vehicle was in for routine service it was discovered that the rooftop solar panel was no longer attached to the vehicle. The contact was informed by the mechanic that the panel was missing and possibly detached while the vehicle was being driven on the highway. The cause of the failure was not determined. The manufacturer and local dealer were notified of the failure but no assistance was offered. The failure mileage was 16,115.			