

 U.S. Department of Transportation National Highway Traffic Safety Administration		Safety Hotline Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline		FOR AGENCY USE ONLY 100148 Date Received 12-DEC-2022 MAR 16 2023		Repository ☐ Reference No. 11497040			
		OWNER INFORMATION (Type or Print) Name [REDACTED] Address [REDACTED] City Rockville State MD ZIP Code [REDACTED] Daytime Telephone Number [REDACTED] E-mail Address [REDACTED] Evening Telephone Number [REDACTED]		The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).					
VEHICLE INFORMATION									
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side 2HGFB2F96DH [REDACTED]			MAKE HONDA		Model CIVIC		Model Year 2013		
Date Purchased 8/9/13		Dealer's Name and Telephone Number HERSON'S HONDA 301-279-8600			Engine: No. Cylinders 4		Fuel Type: REGULAR		
Original Owner ☒		Dealer's City Westford ROCKVILLE		STATE MD		ZIP Code 15090-2085			
Transmission Type AUTOMATIC		☒ Antilock Brakes ☒ Cruise Control		Powertrain 140HP 1.8 LITER SOHC 16-VALVE		Multiple Failure: INTERMITTENT		Incident Date(s) 25-OCT-2022	
FAILED COMPONENT(S)/PART(S) INFORMATION									
Vehicle Components Codes: 140000 AIR BAGS					Failure Mileage 62000.0		Failure Speed VARIOUS		
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE									
Tire Make			Tire Model (Name or Number)			Tire Size (Example P215/65R15)			
DOT No. (Example: DOTM1 9ABC036)			☐ Original Requirement ☐ Prior Repair		Failure Location:				
Tire Component Code						Tire Failure Type:			
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE									
Make:			Date Manufactured:			Model No./Name:			
Seat Type:			Installation System:						
Child Seat Component Code:			Failed Part:						
APPLICABLE INCIDENT INFORMATION (Please describe in detail the Incident(s), Failure(s), Crash(es), Injury(ies).)									
Crash ☐ Yes ☒ No		Fire ☐ Yes ☒ No		Number of Persons Injured		Number of Deaths		Reported to Police N	
Narrative Description of Incident(s), Crash(es), Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).									
The contact owns a 2013 Honda Civic. The contact stated that on several occasions, the check air bag system warning light intermittently illuminated. The vehicle was taken to an independent mechanic where it was placed on a diagnostic machine and produced code: B0001-13. The vehicle was then taken to the dealer where it was diagnosed that the front driver's side wiring assembly needed to be replaced. The vehicle was not repaired. The manufacturer was notified of the failure and the contact was informed that there was no recall for the failure. The failure mileage was approximately 62,000.									
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.									
ATTACH ADDITIONAL SHEETS IF NECESSARY									
The Privacy Act of 1974-Public Law 93-579. This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.									

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

HONDA DEALER ANALYZED PROBLEM AND FOUND THERE WAS A
DRIVER'S SIDE AIRBAG ASSEMBLY INTERNAL FAILURE.
DEALER'S STATEMENT IS ENCLOSED

ATTACH ADDITIONAL SHEETS IF NECESSARY

U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

1200 New Jersey Avenue SE,
Washington, D.C. 20077-9382

Official Business
Penalty for Private Use \$300

CAPITAL DISTRICT 208

5 MAR 2023 PM 1 L

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

BUSINESS REPLY MAIL

FIRST CLASS MAIL

PERMIT NO. 1888

WASHINGTON, DC

POSTAGE WILL BE PAID BY ADDRESSEE

US Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation, NEF-100
1200 New Jersey Avenue SE.
Washington, D.C. 20077-9382



Think your vehicle
has a safety defect?



If so:

Use the enclosed
form to file a report.

or visit:

www.safercar.gov

or call:

Vehicle Safety Hotline
888-327-4236



Vehicle Safety & Quality Division (VSD)
U.S. Department of Transportation
National Highway Traffic Safety Administration



HERSON'S HONDA

Working to provide you with
what you expect ... The Best!

15525 FREDERICK ROAD
ROCKVILLE, MD 20855-2110
(301) 279-8600



CELL: [REDACTED]

CUSTOMER NO. [REDACTED]	ADVISOR NELSON MEJIA	TAG NO. 386	INVOICE DATE 12/01/22	INVOICE NO. [REDACTED]
[REDACTED] ROCKVILLE, MD	LABOR RATE	LICENSE NO. [REDACTED]	MILEAGE 62,378	COLOR GRAY/
	YEAR / MAKE / MODEL 13/HONDA/CIVIC SDN/4DR SDN 5AT			STOCK NO.
	VEHICLE I.D. NO. 2 H G F B 2 F 9 6 D H			DELIVERY DATE
	F.T.E. NO.			DELIVERY MILES
RESIDENCE PHONE [REDACTED]	BUSINESS PHONE [REDACTED]	P.O. NO.	SELLING DEALER NO.	PRODUCTION DATE
COMMENTS			R.O. DATE 12/01/22	

MO: 62378

LABOR & PARTS	
J# 1 68HOZ-01 AIRBAG CONCERN	TECH(S):207 0.00
CUSTOMER STATES AIRBAG LIGHT IS ON ADVISED AND DECLINED DRIVERS AIRBAG TO START WITH	
JOB # 1 TOTAL LABOR & PARTS 0.00	
J# 2 00HOZ-101001 MULTIPOINT INSPECT	TECH(S):207 INTERNAL
PERFORM MULTIPOINT VEHICLE SAFETY INSPECTION. MULTIPOINT INSPECTION COMPLETED.	
JOB # 2 TOTAL LABOR & PARTS 0.00	
J# 3 00HOZ-99 RECALL/CAMPAIGN CHK	TECH(S):207 INTERNAL
CHECK FOR RECALLS AND CAMPAIGNS	
JOB # 3 TOTAL LABOR & PARTS 0.00	

ESTIMATE-----
CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
ORIGINAL ESTIMATE OF \$0.00 (+TAX)

COMMENTS----- ++WAITER+++	
RECOMMENDED NOT DONE/	DECLINED SERVICES-----
68HOZ CAUSE:	RESTRAINT SYS GROUP TECH: 207 replace drivers side airbag assembly failure internal \$1811.40
00HOZ-60 CAUSE:	BRAKE FLUID EXCHANGE TECH: 207 brake fluid flush \$183.99
01HOZ000002 CAUSE:	SYMBOL 2 SVC TECH: 207 replace air filters engine and cabin filters \$151.79
00HOZ-18 CAUSE:	BALANCE WHEELS TECH: 207 preventive maintenance pro long life of tires \$67.70
00HOZ-26 CAUSE:	4 WHEEL ALIGNMENT TECH: 207 preventive maintenance pro long life of tires \$122.73
00HOZ-54 CAUSE:	TOP ENGINE, THROTTLE TECH: 207 preventive \$240.06

12 MONTH / 12,000 MILE EXPRESS LIMITED REPAIR WARRANTY

Herson's Honda warrants repairs and installation of parts, performed by Herson's Honda and paid for by the car owner for 12 months or 12,000 miles, whichever occurs first. Repairs under this warranty will be performed free of charge, by Herson's Honda for parts and labor. Repairs or parts replaced are covered only for the remainder of the warranty period.

This warranty does not cover any labor operation or parts considered normal maintenance items, unless they are defective in material or workmanship. This warranty does not cover normal wear or deterioration of any part repairs performed or parts installed in a car in which the odometer has been altered, or on which the actual mileage cannot be determined. This warranty does not cover tires, which are warranted by the manufacturer.

You are responsible for all maintenance requirements set by the manufacturer and must have receipts. Failures caused by abuse or lack of proper maintenance are not covered by this warranty.

This warranty is limited to repairs only and does not preclude or assume any warranty made by the manufacturer.

This warranty gives you specific legal rights, and you may have other rights which vary from state to state.