


INFORMATION REDACTED PURSUANT TO THE FREEDOM
OF INFORMATION ACT (FOIA), 5 U.S.C.552(B)(6)

From: [DataQuality, DataQuality \(NHTSA\)](#)
To: [EVOO \(NHTSA\)](#)
Subject: FW: 11567348
Date: Friday, February 23, 2024 10:53:54 AM

From: [REDACTED]
Sent: Friday, February 23, 2024 9:50 AM
To: DataQuality, DataQuality (NHTSA) <DataQuality@dot.gov>
Subject: 11567348

CAUTION: This email originated from outside of the Department of Transportation (DOT). Do not click on links or open attachments unless you recognize the sender and know the content is safe.











Issue is with safety of not being able to see the road at night, this is a common issue on the bi-xenon head lights on Volkswagen golf's 2015-2023 Volkswagen group of America is aware of the issue and is issued a tsb advising customers To let their car run with their headlights on for 30 minutes for them to clear in an excuse to not have to replace the defective units with this being unreasonable and putting drivers at risk of causing accidents let alone they are not warranty them even if after 30 minutes of supply out, I have already done this with the dealer and they still will not warrantee my headlights and the water will get to the point where it covers the inner lens and light can get out or it is extremely scattered.